

Contents

1	Introduction	1
1.1	What Is Creo Parametric	1
1.2	Starting Creo Parametric	2
1.3	Setup Working Directory	6
1.4	Starting Creo Parametric Manufacturing Application	7
2	Engraving Tutorial	13
2.1	Step-by-Step Guide on How to Create a 3D Model	
	Part (REC_PRT1)	13
2.1.1	How to Activate the Modelling Application	13
2.1.2	Activate 2D Sketch Application	17
2.1.3	Activate Extrude Application	22
2.2	Add Material and Colour Visualisation to the 3D Part	24
2.2.1	Add the Part Visualisation Colour to Polished Brass Colour.	24
2.2.2	Add Material to the Part.	27
2.3	Create the Engraving Imprint on the Part Surface	36
2.4	Manufacturing Procedure of the Engraved 3D Part	41
2.4.1	Activate the Manufacturing Application	41
2.4.2	Import and Constrain the Reference Model.	44
2.4.3	Adding Stock to the Part	47
2.5	Add Coordinate System (Programme Zero) to the Part.	47
2.6	Set up the Work Centre	50
2.7	Set up the Operation	51
2.8	Set up the Cutting Tool	53
2.9	Activate the Engraving Process.	54
2.9.1	Activate Play Path.	56
2.10	Add Material Removal (nccheck_Type) Application	58
2.11	Material Removal Simulation Activation	60

2.12	Creating the Cutter Location (CL) Data	61
2.13	Create the G-Code Data	63
3	Face Milling Operation	69
3.1	Start the Manufacturing Application	69
3.2	Importing and Constraining the Saved 3D Part	72
3.3	Adding Stock to the Part	75
3.4	Create Coordinate System (Programme Zero)	77
3.5	Setup Work Centre	80
3.6	Setup the Operation	81
3.7	Setup the Cutting Tool	83
3.8	Setup the Face Milling Operation	84
3.8.1	Activate Face Milling Play Path	87
3.9	Activate the Material Removal (nccheck_type)	89
3.10	Material Removal Simulation	92
3.11	Create the Cutter Location (CL) Data	93
3.12	Creating the G-Code Data	95
4	Volume Rough Milling Operation	107
4.1	Volume Rough Milling Operation Using Mill Volume	107
4.2	Activate the Manufacturing Application	108
4.2.1	Import the Saved Part	109
4.2.2	Constraining the Imported Part	110
4.3	Adding Stock to the Part	112
4.4	Create Coordinate System (Programme Zero) for the Workpiece	114
4.5	Set up the Work Centre	117
4.6	Set up Operation	117
4.7	Set up the Cutting Tool	119
4.8	Creating the Mill Volume	120
4.8.1	Create Reference	123
4.8.2	Project Sketch	125
4.8.3	First Method of Creating the Extrude Depth	126
4.8.4	Second Method of Creating the Extrude Depth	127
4.9	Volume Rough Milling Operation	128
4.10	Material Removal Simulation	138
5	Profile Milling Operation	141
5.1	Activate Profile Milling Operation	142
5.2	Material Removal Simulation	147
5.3	Creating the Cutter Location (CL) Data	149
5.4	Create the G-code Data	151

6	Volume Rough Milling Operation, Mill Surface and Drill Operation	157
6.1	Volume Rough Milling Operation Using Mill Volume.	158
6.1.1	Add Stock to the Imported Part.	158
6.1.2	Create Coordinate System (Programme Zero)	159
6.1.3	Setup the Work Centre.	162
6.1.4	Setup the Operation.	163
6.1.5	Setup the Cutting Tool.	165
6.1.6	Hide the Holes on Part.	166
6.1.7	Create Mill Volume.	167
6.1.8	Volume Rough Milling Operation for the First Mill Volume.	174
6.1.9	Create the Second Mill Volume	181
6.1.10	Volume Rough Milling Operation	187
6.2	Surface Milling Operation	191
6.3	Drilling of the Holes	201
6.3.1	Activate/Un-suppress the Holes.	201
6.3.2	Create Drilling Operation	202
6.4	Create the Cutter Location (CL) Data	206
6.5	Create the G-Code Data.	208
7	Volume Rough Milling Using Mill Window and Surface Milling Operation	217
7.1	Volume Rough Milling Using Mill Window Operation	217
7.1.1	Add Stock to the Imported Part Using Assemble Workpiece Method	218
7.1.2	Create Coordinate System for the Workpiece	219
7.1.3	Setup the Work Centre.	222
7.1.4	Setup the Operation.	223
7.1.5	Setup the Cutting Tool.	224
7.1.6	Volume Rough Milling Using Mill Window.	225
7.1.7	Create Window Mill	228
7.2	Create Surface Milling.	231
7.2.1	Activate the Surface Milling Machining Process	237
8	Expert Machinist	241
8.1	Start Expert Machinist	241
8.2	Import Part, Add Stock and Constrain Workpiece	246
8.2.1	Import Part and Add Stock.	246
8.2.2	Constrain the Part	248
8.3	Create Coordinate System or Programme Zero	250
8.4	Create the Work Centre	252
8.5	Set up Operation.	253
8.6	Create Cutting Tools	254

8.7	Activate the Manufacturing Application	262
8.7.1	Hide the Holes, Pocket, Step and Slots on Part	262
8.8	Activate the Expert Machinist Application	264
8.8.1	Create Face Milling Material Removal Sequence. . . .	265
8.8.2	Create Tool Path for Face1 Milling Operation.	267
8.8.3	Activate the Face Milling Play Path Simulation. . . .	273
8.8.4	View the Material Removal Simulation Process	275
8.9	Activate the Manufacturing Application to Create Mill Volume.	276
8.9.1	Create the Mill Volume	277
8.9.2	Create References	279
8.9.3	Project Line and Curves.	280
8.9.4	Create the Mill Volume Sketch.	280
8.10	Create Volume Rough Milling Operation	283
8.10.1	Activate the Volume Rough Milling Operation	286
8.11	Activate the Manufacturing Application	288
8.11.1	Un-suppress the Hidden Holes, Pocket, Step and Slots.	288
8.11.2	Make Workpiece Active on the Manufacturing Window.	289
8.12	Activate the Expert Machining Application	290
8.12.1	Define the Pocket Milling Feature	291
8.12.2	Define the Step Milling Feature	292
8.12.3	Define the Slots Milling Features	294
8.12.4	Create the Hole Group.	296
8.13	Create Tool Paths for Pocket, Step, Slots and Holes	299
8.13.1	Create Tool Path Sequence for Pocket Milling	299
8.13.2	Create Tool Path for Step Milling	306
8.13.3	Create Tool Path for Slot1 Milling	311
8.13.4	Create Tool Path for Slot2 Milling	314
8.13.5	Create Tool Drill Group 2	315
8.13.6	Run the Whole Operations as Created	318
8.14	Cutter Location (CL) Data	319
8.15	Create Post Processor	320
9	Electric Discharge Machining (EDM).	329
9.1	Activate Manufacturing Application	329
9.2	Import and Constrain the 3D Model	331
9.2.1	Import the Reference Model	331
9.2.2	Constrain the Imported 3D Part/Model.	332
9.3	Create Automatic Stock for the Part	333
9.4	Create Coordinate System (Programme Zero)	334
9.5	Create Work Centre.	336
9.6	Create Operation.	337

9.7	Create Cutting Tool.	338
9.8	Create the Contouring Sequences	340
10	CNC Area Lathe Turning.	357
10.1	Activate the Manufacturing Application	357
10.1.1	Import Reference Model.	359
10.1.2	Constrain the Model	360
10.2	Create Automatic Workpiece	361
10.3	Create Programme Zero (Coordinate System)	363
10.4	Create Work Centre.	364
10.5	Create Operation	365
10.6	Create Cutting Tool.	366
10.7	Create Turn Profile Using Method 1	368
10.7.1	Define References	371
10.7.2	Project Lines and Curve.	372
10.8	Create Area Turning Operation Using the First Method	374
10.8.1	Activate Play Path.	375
10.9	Create Area Turning Operation Using the Second Method	377
10.9.1	Create Tool Motion for Area Turning	378
10.9.2	Activate Play Path.	380
10.9.3	Activate the Material Removal Simulation	381
10.10	Create the Cutter Location (CL) Data	382
10.11	Create the G-code Data	384
11	Area Lathe Turning, Drilling, Boring and Volume Milling	389
11.1	Start the Manufacturing Application	389
11.1.1	Import Reference Part	391
11.1.2	Constrain the Reference Model	391
11.1.3	Create Automatic Workpiece	393
11.1.4	Create Programme Zero (Coordinate System)	394
11.1.5	Create Work Centre.	396
11.1.6	Create Operation	397
11.1.7	Create Cutting Tools	399
11.2	Create a Datum Point	402
11.3	Create Turn Profile	405
11.4	Create Area Turning Sequence	411
11.4.1	Create Tool Motions for Area Turning.	412
11.4.2	Activate Play Path.	414
11.5	Create Drilling Sequence	415
11.6	Create Turn Profile for the Internal Hole Diameter	421
11.7	Create Area Turning for the Internal Hole Diameter	426
11.7.1	Create Tool Motion for Area Turning	427
11.7.2	Activate Play Path.	429

11.8	Create New Coordinate System, Work Centre, Datum and Operation for the Volume Mill Process	430
11.8.1	Create a New Coordinate System	430
11.8.2	Create New Work Centre (MILL02)	432
11.8.3	Create a New Datum Plane.	433
11.8.4	Create Operation and Retract Plane	434
11.8.5	Create New Mill Volume	435
11.9	Create the Volume Rough Operation	440
11.9.1	Activate the Play Path Operation.	443
11.9.2	Material Removal Simulation for Volume Rough Milling	445
11.10	Cuter Location (CL) Data for All Operations	446
11.11	Creating the G-Code Data	448
12	Five-Axis Machining of Intricate Part	455
12.1	Volume Rough Milling Using Mill Volume	456
12.1.1	Start Creo Parametric.	456
12.1.2	Import and Constrain the Reference Part	457
12.1.3	Add Stock to the Part	459
12.1.4	Suppress Holes	461
12.2	Create Coordinate Systems for the Workpiece.	461
12.2.1	Create Top (First) Coordinate System	462
12.2.2	Create Bottom (Second) Coordinate System	463
12.3	Set up the Work Centre	465
12.4	Set up Operation Using the First Coordinate System Created (ACS2)	466
12.5	Set up the Cutting Tools	468
12.6	Create Mill Volumes	477
12.6.1	Create First Mill Volume	477
12.6.2	Create Volume Rough Milling Operation for the First Mill Volume.	482
12.6.3	Create Second Mill Volume	489
12.6.4	Volume Rough Milling Operation for the Second Mill Volume.	494
12.6.5	Create Third Mill Volume	500
12.6.6	Volume Rough Milling Operation for the Third Mill Volume.	503
12.6.7	Create Fourth Mill Volume.	506
12.6.8	Volume Rough Milling Operation for the Fourth Mill Volume.	510
12.6.9	Create the Fifth Mill Volume	515
12.6.10	Volume Rough Milling Operation for the Fifth Mill Volume.	519

12.7	Setup Operation Using the Second Coordinate System (ACS3).	524
12.7.1	Create the First Bottom Mill Volume.	525
12.7.2	Volume Rough Milling Operation for the First Bottom Mill Volume	529
12.7.3	Create the Second Mill Volume on the Bottom Side of the Workpiece	532
12.7.4	Volume Rough Milling Operation for the Second Bottom Mill Volume	536
12.7.5	Create the Third Mill Volume on the Bottom Side of the Workpiece	540
12.7.6	Volume Rough Milling Operation for the Third Bottom Mill Volume	543
12.7.7	Create the Fourth Mill Volume on the Bottom Side of the Workpiece	546
12.7.8	Volume Rough Milling Operation for the Fourth Bottom Mill Volume	549
12.7.9	Create the Fifth Mill Volume on the Bottom Side of the Workpiece	552
12.7.10	Volume Rough Milling Operation for the Fifth Mill Volume.	555
12.7.11	Create the Sixth Mill Volume on the Workpiece	557
12.7.12	Volume Rough Milling Operation for the Sixth Mill Volume.	560
12.8	Surface Milling.	565
12.8.1	Create Surface Milling for the Outer Surface of the Workpiece.	565
12.9	Create Drill Cycle on Workpiece	573
12.9.1	Activate the Part	574
12.9.2	Activate the Automatic/Created Workpiece.	576
12.9.3	Standard Drilling Operation for 100 mm Hole	577
12.9.4	Standard Drilling Operation for 70 mm Hole	580
12.9.5	Standard Drilling Operation for 20 mm Hole	584
12.9.6	Create Tapping Operation for 20 mm Hole.	587
12.10	Create the Cutter Location (CL) Data	592
12.10.1	Create Cutter Location for OP010	592
12.10.2	Create Cutter Location for OP020	594
12.11	Create the G-Code Data.	597
12.11.1	Generate the G-Code Data for OP010.ncl.	597
12.11.2	Generate the G-Code Data for OP020.ncl.	599

13	Surface Milling of Intricate Cast Part	601
13.1	Five Axes Surface Milling of Cast Part	601
13.1.1	Start New Manufacturing Application	601
13.1.2	Import and Constrain the Reference Model.	603
13.2	Create Programme Zero or Coordinate System	605
13.3	Create Work Centre.	607
13.4	Create Operation.	608
13.5	Create Cutting Tool.	609
13.6	Create Surface Milling Sequences	613
13.6.1	Create Surface Milling for Internal Surface of the Cast Part.	613
13.6.2	Create Edge Surface Milling for the Outer Circular Surface of the Cast Part.	621
13.6.3	Activate on Screen Play for the Outer Surface Milling Process.	629
	Further Reading	633
	Index	635

Computer Aided Virtual Manufacturing Using Creo
Parametric

Easy to Learn Step by Step Guide

Kanife, P.O.

2016, L, 640 p. 1251 illus., Hardcover

ISBN: 978-3-319-23358-1