

List of Figures

Fig. 1.1	The Carver County Jail in Chaska, MN, of Type I construction (Photograph courtesy of the Chaska Herald)	3
Fig. 1.2	Type I dry storage warehouse at Pearl Harbor (Photograph courtesy of the Library of Congress)	3
Fig. 1.3	Type II dating to the World War II era (Photograph courtesy of the Library of Congress).....	4
Fig. 1.4	Interior of a Type II warehouse building dating to the World War II era (Photograph courtesy of the Library of Congress).....	5
Fig. 1.5	A typical Type III residential building dating to the World War II era (Photograph courtesy of the Library of Congress).....	6
Fig. 1.6	Guardian Angels Church in Chaska, MN, a Type IV church. Originally built in 1885, but destroyed by fire in 1902. Pictured is the 1902 rebuild (Photograph taken by author)	7
Fig. 1.7	Interior of a Type IV heavy timber Ford plant as viewed in 1966 (Photograph courtesy of the Library of Congress)	8
Fig. 1.8	Typical American lightweight residential construction commonly associated with Type V (Photograph courtesy of NIOSH)	9
Fig. 1.9	An artist's rendering of a typical heavy timber structure's constituent components (Photograph courtesy of the CDC).....	10
Fig. 1.10	Interior walls of Guardian Angels Church in Chaska, MN (Photograph taken by author).....	11
Fig. 1.11	Heavy timber roof assembly of Guardian Angels Church (Photograph taken by author).....	11
Fig. 1.12	Charred heavy timber beam surviving from 1902 fire in Guardian Angels Church and reused in the rebuild (Photograph taken by author).....	12

Fig. 2.1	Heaton and Cowing Mill in Providence, Rhode Island (Photograph courtesy of Ned Connors)	19
Fig. 2.2	The W. L. Douglas Shoe Company in Brockton, Massachusetts, in the 1940s (Photograph by Jack Delano, courtesy of the Library of Congress)	19
Fig. 2.3	The Bull Durham Tobacco Company's complex in Durham, North Carolina, in the mid-twentieth century (Photograph by Marion Post Wolcott, courtesy of the Library of Congress).....	21
Fig. 3.1	Typical 1880s balloon frame home showing extensive damage from unimpeded vertical fire spread (Photograph taken by the author).....	25
Fig. 3.2	The aftermath of the Great Chicago Fire (Photograph courtesy of the Library of Congress)	29
Fig. 3.3	Photograph showing further damage from the Great Chicago Fire (Photograph courtesy of the Library of Congress).....	30
Fig. 3.4	A late-nineteenth-century photograph of the Nixon Building (Photograph courtesy of W. S. Wheeler)	33
Fig. 3.5	Chicago's Old Water Tower (Photograph courtesy of the Library of Congress).....	35
Fig. 3.6	A view of Old St. Pat's exterior and interior during the mid-twentieth century (Photograph courtesy of the Library of Congress).....	36
Fig. 4.1	Schech's Mill located near La Crescent, Minnesota (Photograph courtesy of the Library of Congress)	38
Fig. 4.2	The rebuilt Washburn A Mill in the 1960s (Photograph courtesy of the Library of Congress)	41
Fig. 4.3	The Minneapolis Milling District in the first half of the twentieth century (Photograph courtesy of the Library of Congress).....	42
Fig. 4.4	The 1300 Washington Avenue building, an 1899 Eames & Young design and exceptional example of the ornate style seen in St. Louis, Missouri (Photograph courtesy of public hall, in accordance with GNU Free Documentation License)	43
Fig. 5.1	The Leiter Building in Chicago (Photograph courtesy of Oklahoma University)	47
Fig. 5.2	Jenney's Home Insurance Company Building in the first quarter of the twentieth century, which also gives a great view of downtown Chicago's architectural identity (Photograph courtesy of Construction Week Online).....	48
Fig. 5.3	Frank Lloyd Wright's 1902 E-Z Polish Factory (Photograph courtesy of James N. McNally).....	49

Fig. 5.4	Firefighting efforts being taken against the 1911 Triangle Shirtwaist Factory fire in the Asch Building (Photograph courtesy of the United States Department of Labor)	52
Fig. 5.5	The Baker and Hamilton Building in San Francisco (Photograph courtesy of Christopher Ver Planck)	53
Fig. 5.6	The Ceresota Building in Minneapolis (Photograph courtesy of The Minneapolis Journal).....	54
Fig. 5.7	The steel-framed Chaska Sugar Factory in the early twentieth century (Photograph courtesy of the Carver County Historical Society).....	55
Fig. 6.1	A photograph of a 1925 fire at the heavy timber structure in Washington, DC, which vividly depicts the resources needed to combat fully developed heavy timber structure fire (Photograph courtesy of the Library of Congress)	62
Fig. 6.2	The 1999 Worcester Cold Storage Warehouse Fire that killed six firefighters (Photograph courtesy of the Centers for Disease Control and Prevention)	64
Fig. 7.1	Minneapolis' Crown Roller Mill after conversion (Photograph by Susan G. Lesch, used in accordance with Creative Commons Attribution 2.0 Generic License)	68
Fig. 7.2	St. Louis' International Hat Company Building (1904) after conversion (Photograph by Bob Patton).....	69
Fig. 7.3	Minneapolis' Mill City Museum, in the ruins of the former Washburn A Mill (Photograph by Brady Willette, courtesy of the Minnesota Historical Society).....	70
Fig. 7.4	A photograph of the Faribault Woolen Mill shortly after its renovation and resumption of operations (Photograph by Elizabeth A. Gates, courtesy of Minnesota State Historic Preservation Office).....	71
Fig. 7.5	Interior of Oakland's Cathedral of Christ the Light (Photograph by Carol M. Highsmith's America, Library of Congress, Prints and Photographs Division)	74
Fig. 8.1	A sketch of the Guardian Angels floor plan, measured and drawn by the author.....	77
Fig. 8.2	Guardian Angels prior to the 1902 fire (Photograph courtesy of the Carver County Historical Society).....	78
Fig. 8.3	Guardian Angels' steeple viewed from 2 miles south at dusk (Photograph taken by the author)	79
Fig. 8.4	The church under construction (Photograph courtesy of the Carver County Historical Society).....	80
Fig. 8.5	Junction of the western church wall, transept, and friary (Photograph taken by the author).....	81
Fig. 8.6	Guardian Angels' western wall and north face of the original friary (Photograph taken by the author)	82

Fig. 8.7	Eastern wall of the church near the junction with the eastern transept. The American bond pattern of the brick and its varying condition is evident (Photograph taken by the author)	83
Fig. 8.8	Heavy timbers in the roof assembly above the eastern aisle, flanked by vaults (Photograph taken by the author).....	84
Fig. 8.9	Close-up of a notched king post in the church attic (Photograph taken by the author).....	84
Fig. 8.10	Iron strap and bolts affixed to a post which frames the steeple (Photograph taken by the author).....	85
Fig. 8.11	Tie rods exiting the eastern wall of the church alongside the buttresses (Photograph taken by the author)	86
Fig. 8.12	Close-up of the tip of a tie rod along the eastern wall of the church (Photograph taken by the author).....	86
Fig. 8.13	Anchor plate and rust staining on the friary; both are absent features on the church itself (Photograph taken by the author).....	87
Fig. 8.14	Charred timber and brick in the mechanical room adjacent to the church (Photograph taken by the author).....	88
Fig. 8.15	Rubble and mortar foundation found in the mechanical room adjacent to the church (Photograph taken by the author)	89
Fig. 8.16	Chimney and Ravoux Chapel butted up against the chancel, nave, western transept, and noticeably shorter eastern wing of the friary (Photograph taken by the author).....	89
Fig. 8.17	Passageways into the Ravoux Chapel from the church chancel (Photograph taken by the author)	90
Fig. 8.18	Hatch on the power plant's chimney (Photograph taken by the author).....	91
Fig. 8.19	An offset on one of the church's buttresses (Photograph taken by the author).....	92
Fig. 8.20	Decking, common rafters, and purlin in the church roof (Photograph taken by the author).....	93
Fig. 8.21	Window along the western aisle (Photograph taken by the author).....	94
Fig. 8.22	Vaulting along the central space looking southward to the choir loft (Photograph taken by the author).....	95
Fig. 8.23	Vaulting springing from a column in the nave (Photograph taken by the author).....	95
Fig. 8.24	Vaulting along the western aisle in the nave facing southward (Photograph taken by the author)	96
Fig. 8.25	Corrugated appearance of the vault ribs (Photograph taken by the author).....	97
Fig. 8.26	Wavy appearance of the lath and plaster walls in front of the chancel (Photograph taken by the author)	98
Fig. 8.27	Laths composing a transverse rib as seen from the attic (Photograph taken by the author).....	98

Fig. 8.28	Undated early-twentieth-century photo of the church's central space facing southward (Photograph courtesy of the Carver County Historical Society).....	99
Fig. 8.29	Central space of the church facing southward as seen in 2014 (Photograph taken by the author).....	100
Fig. 8.30	Undated photograph of the church's central space facing the altar (Photograph courtesy of the Carver County Historical Society)	100
Fig. 8.31	Vaulting in the chancel and the top of the altar in 2014 (Photograph taken by the author).....	101
Fig. 8.32	Steps leading from the western transept into the friary (Photograph taken by the author).....	101
Fig. 8.33	Heavy wear is evident on the door knob which is affixed to a door to the stairwell to the choir loft (Photograph taken by the author).....	102
Fig. 8.34	Handicap-accessible entrance attached to the eastern transept (Photograph taken by the author)	102
Fig. 8.35	Brick in disrepair along the western wall (Photograph taken by the author).....	103
Fig. 8.36	The church steeple, with brick in a wide range of conditions (Photograph taken by the author).....	104
Fig. 9.1	Minneapolis' Pillsbury Complex photographed in the twenty-first century (Photograph by Carol M. Highsmith's America, Library of Congress, Prints and Photographs Division)	106

Fire Resistance in American Heavy Timber Construction
History and Preservation

Heitz, J.

2016, XV, 118 p. 76 illus., 54 illus. in color., Hardcover

ISBN: 978-3-319-32126-4