

	Introductory material	
1	Production of atomic defects in metals (P. JUNG)	1
1.1	Introduction	1
1.1.1	General remarks	1
1.1.2	Definitions	1
1.1.3	Symbols and units	1
1.1.4	Abbreviations	2
1.2	Methods to produce atomic defects in metals	3
1.3	Stability of atomic defects in metals	3
1.4	Methods to determine concentrations of atomic defects in metals	4
1.5	Production of atomic defects in metals in thermal equilibrium	4
1.6	Production of atomic defects in metals by plastic deformation	5
1.7	Production of atomic defects in metals by irradiation	6
1.7.1	Production of atomic defects in pure, polycrystalline metals	8
1.7.1.1	Electron irradiation	8
1.7.1.2	Ion irradiation	11
1.7.1.3	Ion implantation	13
1.7.1.4	Thermal neutron irradiation	14
1.7.1.5	Fission neutron, fast neutron, and fission fragment irradiation	15
1.7.2	Production of atomic defects in pure, single crystalline metals	16
1.7.2.1	Displacement energy maps	16
1.7.2.2	Average displacement energy	18
1.7.3	Production of atomic defects in predamaged metals	19
1.7.3.1	Quenched metals	19
1.7.3.2	Deformed metals	19
1.7.3.3	Preirradiated metals	20
1.7.4	Production of atomic defects in metals at high defect densities	20
1.7.4.1	Subthreshold effects	20
1.7.4.2	Defect saturation	21
1.7.4.3	Cascade production	24
1.7.5	Production of atomic defects in alloys	26
1.7.5.1	Dilute alloys	26
1.7.5.2	Concentrated alloys	27
1.7.5.3	Ordered alloys	27
1.7.6	Production of atomic defects in metallic glasses	31
1.7.7	Surface effects	31
1.7.7.1	Threshold energy for sputtering	31
1.7.7.2	Energy dependence of the sputtering yield	33
1.7.7.3	Dependence of the sputtering yield on crystal orientation	33
1.7.7.4	Temperature dependence of the sputtering yield	33
1.7.8	Temperature effects on the production of atomic defects in metals	34

1.7.9	Computer simulation of atomic defect production	34
1.7.9.1	Computer simulation of low energy events	34
1.7.9.2	Computer simulation of high energy cascades	35
1.7.9.3	Computer simulation of temperature effects on atomic defect production	36
	Figures for 1	37
	References for 1	77
2	Properties and interactions of atomic defects in metals and alloys	88
2.1	Introduction (P. EHRHART)	88
2.1.1	General remarks	88
2.1.2	Frequently used symbols and abbreviations	90
2.1.3	Characterization of interstitial atoms and vacancies	92
2.1.3.1	Formation entropies and energies and equilibrium concentrations	92
2.1.3.2	Structure of defects and their agglomerates	93
2.1.3.3	Defect dynamics, migration energies and jump frequencies	95
2.1.3.4	Defect-solute interaction	98
2.1.3.5	Defect reactions and annealing stages	100
2.1.4	Experimental methods	102
2.1.4.1	Residual electrical resistivity ( $\Delta\rho$ )	102
2.1.4.2	Calorimetry (Cal)	102
2.1.4.3	Differential dilatometry (DD)	103
2.1.4.4	Diffuse scattering of X-rays or neutrons, Huang scattering (DXS)	103
2.1.4.5	Extended X-ray absorption fine structure (EXAFS)	104
2.1.4.6	Inelastic neutron scattering (INS)	104
2.1.4.7	Mechanical relaxation (elastic after-effect, internal friction, ultrasonic attenuation) (MechR)	104
2.1.4.8	Magnetic relaxation (MagR)	104
2.1.4.9	Change of the elastic constants ( $\Delta c_{ij}$ )	105
2.1.4.10	Mössbauer spectroscopy (MS)	105
2.1.4.11	Perturbed angular correlation (PAC)	105
2.1.4.12	Positron annihilation spectroscopy (PAS)	106
2.1.4.13	Muon spin rotation experiments ( $\mu$ SR)	106
2.1.4.14	Nuclear magnetic resonance (NMR)	106
2.1.4.15	Ion channeling (Chann)	107
2.1.4.16	Transmission electron microscopy (TEM)	107
2.1.4.17	Field ion microscopy (FIM)	107
2.1.4.18	Thermal helium desorption spectroscopy (THDS)	107
	Figures for 2.1	108
2.2	bcc metals (H. SCHULTZ)	115
2.2.1	Special remarks	115
2.2.2	Concepts of data evaluation	121
2.2.3	Data	122
	Cr	122
	Fe	125
	K	135
	Li	138
	Mo	140
	Na	147

	Nb	149
	Ta	161
	V	173
	W	179
	References for 2.2	191
2.3	fcc metals (P. EHRHART)	202
2.3.1	Special remarks	202
2.3.2	Data	203
	Ag	203
	Al	211
	Au	224
	Ce	230
	Cu	231
	Ir	241
	Ni	242
	Pb	250
	Pd	254
	Pt	256
	Rh	262
	Th	263
2.4	hcp metals (P. EHRHART)	264
2.4.1	Special remarks	264
2.4.2	Data	265
	Be	265
	Cd	266
	Co	271
	Mg	274
	Re	278
	Sc	281
	Tl	282
	Ti	282
	Y	284
	Zn	284
	Zr	288
	RE	296
2.5	Metals with other structures (P. EHRHART)	304
2.5.1	Special remarks	304
2.5.2	Data	304
	Bi	304
	Ga	306
	Hg	307
	In	308
	Sb	309
	Sn	310
	U	312
2.6	Concentrated alloys (P. EHRHART)	313
2.6.1	Special remarks	313

2.6.2	Data	316
	Ag-Al	316
	Ag-Au	318
	Ag-Zn	320
	Al-Cu	322
	Al-Fe	324
	Al-Ni	329
	Au-Cu	332
	Co-Fe	338
	Co-Pt	343
	Cr-Fe	343
	Cr-Ni	349
	Cu-Mn	351
	Cu-Ni	352
	Cu-Zn	354
	Fe-Ni	358
	Mn-Ni	360
	Mo-Ni	361
	Superconducting alloys	361
	References for 2.1 and 2.3 - 2.6	363
3	Helium in metals (H. ULLMAIER)	380
3.1	Introduction	380
3.1.1	General remarks	380
3.1.2	Symbols and abbreviations	381
3.1.3	Experimental and theoretical methods	383
3.2	Production processes and rates	385
3.2.1	(n, $\alpha$ )-reactions	385
3.2.2	Other nuclear reactions	386
3.2.3	Implantation	386
3.2.4	Concurrent displacement damage	388
3.2.5	Tritium decay	388
3.3	Atomistic properties	389
3.3.1	Interstitial and substitutional solubility	389
3.3.2	Binding to defects	391
3.3.3	Diffusion	395
3.4	Clusters and bubbles	397
3.4.1	Formation without vacancy clustering	397
3.4.2	Nucleation involving vacancy migration	398
3.4.3	Growth and coarsening	400
	Figures for 3	402
	References for 3	432
	Subject index for 3	436

Atomic Defects in Metals / Atomare Fehlstellen in  
Metallen

Ullmaier, H. (Ed.)

1991, XIII, 437 p., Hardcover

ISBN: 978-3-540-51435-0