

1	General introduction (D.L. BEKE)	1-1
1.1	Atomic fluxes	1-1
1.2	Equations for diffusion	1-3
1.2.1	Bulk diffusion	1-4
1.2.1.1	Tracer diffusion in a homogeneous matrix	1-4
1.2.1.2	Chemical diffusion	1-6
1.2.2	Grain-boundary diffusion	1-9
1.2.2.1	Self-diffusion	1-11
1.2.2.2	Impurity diffusion and segregation	1-12
1.2.3	Dislocation diffusion	1-12
1.2.4	Surface diffusion	1-12
1.3	Atomic mechanisms of diffusion	1-13
1.3.1	Direct interstitial mechanism	1-14
1.3.2	Indirect interstitial or interstitialcy mechanism	1-14
1.3.3	Ring mechanism	1-14
1.3.4	Vacancy mechanism	1-14
1.3.5	Interstitial-substitutional mechanisms	1-14
1.3.6	Other mechanisms	1-15
1.4	Methods for measuring diffusion coefficients	1-15
1.4.1	Macroscopic methods	1-16
1.4.1.1	Steady-state methods	1-16
1.4.1.2	Non steady-state methods	1-16
1.4.2	Microscopic methods	1-17
1.4.2.1	Relaxation methods	1-17
1.4.2.2	Nuclear methods	1-18
1.5	Temperature, pressure and mass dependence of diffusion	1-18
1.5.1	Temperature and pressure dependence	1-18
1.5.2	Mass dependence	1-19
1.6	Notations, use of the tables	1-19
1.7	Further readings	1-20
1.7.1	Textbooks	1-20
1.7.2	Proceedings	1-20
1.7.3	Collections of data	1-21
1.7.4	Review articles	1-21
1.8	References for 1	1-21

2	Diffusion in alkali and alkaline earth halides (F. BÉNIÈRE)	2 - 1
2.1	Introduction	2 - 1
2.1.1	Order of solids	2 - 1
2.1.2	Order of elements	2 - 2
2.1.3	Experimental techniques	2 - 2
2.1.3.1	Profile determination	2 - 2
2.1.3.2	Indirect nuclear methods	2 - 3
2.1.3.3	Electrical conductivity method	2 - 3
2.1.3.4	Electromigration	2 - 5
2.1.4	Use of table and figures	2 - 5
2.2	Table	2 - 7
	LiF . . . 2 - 7 LiCl . . . 2 - 7 LiBr . . . 2 - 7 LiI . . . 2 - 8	
	NaF . . . 2 - 8 NaCl . . . 2 - 8 NaBr . . . 2 - 12 NaI . . . 2 - 12	
	KF . . . 2 - 13 KCl . . . 2 - 13 KBr . . . 2 - 16 KI . . . 2 - 17	
	RbF . . . 2 - 18 RbCl . . . 2 - 19 RbBr . . . 2 - 19 RbI . . . 2 - 19	
	CsF . . . 2 - 20 CsCl . . . 2 - 20 CsBr . . . 2 - 20 CsI . . . 2 - 21	
	MgF ₂ . . . 2 - 22 CaF ₂ . . . 2 - 22 SrF ₂ . . . 2 - 23 SrCl ₂ . . . 2 - 23	
	BaF ₂ . . . 2 - 23 TiCl . . . 2 - 24	
2.3	Figures for 2	2 - 25
2.4	References for 2	2 - 31

3	Diffusion in fast-ion conducting solids (A.V. CHADWICK)	3 - 1
3.1	General remarks	3 - 1
3.2	Classification of fast-ion conductors	3 - 1
3.3	Methods of investigating diffusion in fast-ion conductors	3 - 2
3.3.1	General comments	3 - 2
3.3.2	Tracer techniques	3 - 3
3.3.3	Indirect nuclear methods	3 - 3
3.3.4	Electrical conductivity	3 - 3
3.4	Use of the tables and figures	3 - 4
3.5	Transition temperatures for fluorite-structured fast-ion conductors	3 - 5
3.6	Anion diffusion in fluorite-structured halide fast-ion conductors	3 - 5
3.6.1	Calcium fluoride	3 - 5
3.6.2	Strontium fluoride	3 - 6
3.6.3	Barium fluoride	3 - 6
3.6.4	Lead fluoride	3 - 6
3.6.5	Strontium chloride	3 - 7
3.7	Anion diffusion in mixed metal fluorite-structured halide fast-ion conductors	3 - 7
3.8	Cation diffusion in antiferro-structured lithium oxide	3 - 9
3.9	Anion diffusion in fluorite-structured oxide fast-ion conductors	3 - 9
3.9.1	Cerium oxide	3 - 9
3.9.2	Zirconium oxide	3 - 12
3.9.3	Thorium oxide	3 - 16
3.9.4	Hafnium oxide	3 - 17
3.9.5	Bismuth oxide	3 - 17
	Figures for 3	3 - 19
3.10	References for 3	3 - 27

4	Diffusion in miscellaneous ionic materials (G. ERDÉLYI)	4 - 1
4.1	Use of tables and figures	4 - 1
4.2	Tables for diffusion in miscellaneous ionic materials	4 - 3
4.2.1	Sulphates and other compounds	4 - 3
4.2.2	Sulfides	4 - 5
4.2.3	Niobates	4 - 11
4.2.4	Titanates	4 - 14
4.2.5	Other mixed oxides	4 - 17
4.2.6	Silicates	4 - 18
4.2.6.1	Nesosilicates	4 - 18
4.2.6.2	Sorosilicates	4 - 20
4.2.6.3	Inosilicates	4 - 21
4.2.6.4	Phyllosilicates	4 - 22
4.2.6.5	Tectosilicates	4 - 22
4.2.7	Phosphates	4 - 24
	Figures for 4	4 - 25
4.3	References for 4	4 - 34

5	Diffusion in carbides, nitrides, hydrides, and borides (HJ. MATZKE, V.V. RONDINELLA)	5 - 1
5.1	Diffusion in carbides	5 - 1
5.1.1	Silicon carbide	5 - 2
5.1.2	Monocarbides of group IV transition metals	5 - 2
5.1.3	Monocarbides of group V and group VI transition metals	5 - 3
5.1.4	Actinide carbides	5 - 3
5.1.5	Diffusion and release of fission products, and measurements on coated particles	5 - 4
5.1.6	Diffusion in silicon systems	5 - 5
5.1.6.1	Self - diffusion in silicon carbide	5 - 5
5.1.6.2	Interdiffusion SiC - AlN	5 - 5
5.1.6.3	Impurity diffusion in silicon carbide	5 - 5
5.1.6.4	Diffusion of gases in silicon carbide	5 - 7
5.1.6.5	Measurements on SiC - coated fuel particles for gas - cooled nuclear reactors	5 - 8
5.1.7	Diffusion in titanium systems	5 - 8
5.1.7.1	Self - diffusion in titanium carbide	5 - 8
5.1.7.2	Impurity diffusion in titanium carbide	5 - 9
5.1.7.3	Diffusion in TiC - VC systems	5 - 9
5.1.8	Diffusion in zirconium systems	5 - 10
5.1.8.1	Diffusion in zirconium carbide	5 - 10
5.1.8.2	Diffusion in the ZrC - NbC system	5 - 10
5.1.8.3	Diffusion in the UC - ZrC system	5 - 11
5.1.8.4	Impurity diffusion in zirconium carbide	5 - 11
5.1.9	Diffusion in hafnium carbide	5 - 12
5.1.10	Diffusion in vanadium carbide	5 - 12
5.1.11	Diffusion in niobium carbide	5 - 12
5.1.12	Diffusion in tantalum carbide	5 - 13
5.1.13	Diffusion in chromium carbide	5 - 13
5.1.14	Diffusion in molybdenum carbide	5 - 14
5.1.15	Diffusion in tungsten carbide	5 - 14
5.1.16	Diffusion in iron carbide	5 - 14
5.1.17	Diffusion in lithium carbide	5 - 14
5.1.18	Diffusion in boron carbide	5 - 15
5.1.19	Diffusion in uranium carbide UC _{1±x}	5 - 15
5.1.20	Diffusion in U ₂ C ₃ and UC ₂	5 - 17
5.1.21	Grain boundary and surface diffusion in UC and UC ₂	5 - 17
5.1.22	Diffusion in uranium carbonitrides	5 - 18
5.1.23	Diffusion in mixed carbides (U, Pu)C	5 - 18
5.1.24	Diffusion in mixed carbonitrides and oxycarbides (U, Pu)(C, N) and (U, Pu)(C, O)	5 - 19
	Figures for 5.1	5 - 20
5.1.25	References for 5.1	5 - 25

6 Volume diffusion in oxides

C.J.A. Monty

Please see subvolume III/33B, Part 2, to be published in 2008

5.2	Diffusion in nitrides (Hj. Matzke, V.V. Rondinella)	5 - 30
5.2.1	Diffusion in silicon systems	5 - 31
5.2.1.1	Self - diffusion in silicon nitride	5 - 31
5.2.1.2	Surface diffusion on silicon nitride	5 - 31
5.2.1.3	Impurity diffusion in silicon nitride	5 - 31
5.2.1.4	Diffusion in silicon oxynitride	5 - 32
5.2.1.5	Interdiffusion in silicon nitride	5 - 32
5.2.2	Diffusion in titanium systems	5 - 33
5.2.2.1	Self - diffusion in titanium nitride	5 - 33
5.2.2.2	Impurity diffusion in titanium nitride	5 - 33
5.2.3	Self - diffusion in zirconium nitride	5 - 34
5.2.4	Diffusion in hafnium nitride	5 - 35
5.2.5	Diffusion in niobium nitride	5 - 35
5.2.6	Diffusion in aluminum nitride	5 - 35
5.2.7	Diffusion in thorium nitride	5 - 36
5.2.8	Diffusion in uranium systems	5 - 36
5.2.8.1	Diffusion in uranium nitride	5 - 36
5.2.8.2	Surface diffusion on uranium nitride	5 - 37
5.2.8.3	Diffusion of Xe in uranium nitride	5 - 37
5.2.9	Self - diffusion in mixed nitride (U, Pu)N	5 - 37
5.2.10	Diffusion in chromium nitride	5 - 37
5.2.11	Self - diffusion in iron nitride	5 - 37
5.2.12	Self - diffusion in potassium azide	5 - 38
5.2.13	Self - diffusion in lithium nitride	5 - 38
	Figures for 5.2	5 - 39
5.2.14	References for 5.2	5 - 42

5.3	Diffusion in hydrides (Hj. Matzke, V.V. Rondinella)	5 - 44
5.3.1	Hydrogen diffusion in lanthanum - based hydrides	5 - 45
5.3.2	Hydrogen diffusion in magnesium - based hydrides	5 - 46
5.3.3	Hydrogen diffusion in vanadium hydride	5 - 46
5.3.4	Hydrogen diffusion in niobium hydride	5 - 46
5.3.5	Hydrogen diffusion in tantalum - based hydrides	5 - 47
5.3.6	Hydrogen diffusion in palladium - based hydrides	5 - 48
5.3.7	Diffusion in lithium hydride	5 - 49
5.3.8	Diffusion in titanium - based hydrides	5 - 50
5.3.9	Diffusion in zirconium - based hydrides	5 - 51
5.3.10	Diffusion in hafnium - based hydrides	5 - 55
5.3.11	Diffusion in uranium hydride	5 - 55
5.3.12	Diffusion in thorium hydride	5 - 56
5.3.13	Diffusion in calcium hydride	5 - 56
5.3.14	Diffusion in iron - based hydrides	5 - 56
5.3.15	Diffusion in nickel hydride	5 - 56
	Figures for 5.3	5 - 57
5.3.16	References for 5.3	5 - 59
5.4	Diffusion in borides: No quantitative data could be found in the literature	

7	Diffusion in oxide glasses (H. JAIN, C.H. HSIEH)	7 - 1
7.1	Introduction	7 - 1
7.2	General remarks	7 - 1
7.3	Diffusion coefficient measurement methods	7 - 2
7.4	Temperature dependence of diffusion coefficient	7 - 3
7.5	Use of the tables and figures	7 - 4
7.6	References for 7.1 ... 7.5	7 - 5
7.7	Data	7 - 6
	Table 1. Diffusion in SiO ₂ glass	7 - 6
	Table 2. Diffusion in binary silicate glasses	7 - 10
	Table 3. Diffusion in ternary silicate glasses	7 - 25
	Table 4. Diffusion in multi component silicate glasses	7 - 42
	Table 5. Diffusion in B ₂ O ₃ glass	7 - 44
	Table 6. Diffusion in binary borate glasses	7 - 45
	Table 7. Diffusion in ternary borate glasses	7 - 50
	Table 8. Diffusion in GeO ₂ glass	7 - 51
	Table 9. Diffusion in binary germanate glasses	7 - 52
	Table 10. Diffusion in ternary germanate glasses	7 - 55
	Table 11. Diffusion in molybdate, niobate and phosphate glasses	7 - 56
	Table 12. Diffusion in selenate, tellurite, tungstate and vanadate glasses	7 - 58
	Figures for 7.7	7 - 62
7.8	References for 7.7	7 - 88

8	Diffusion in molecular solids (A.V. CHADWICK)	8 - 1
8.1	General remarks	8 - 1
8.2	Classification of molecular solids	8 - 2
8.3	Methods of investigating diffusion in molecular solids	8 - 2
8.4	Theoretical considerations	8 - 4
8.5	Use of the tables and figures	8 - 5
8.6	Tables of thermodynamic properties and structures for molecular solids	8 - 7
8.6.1	Rare gas solids	8 - 7
8.6.2	Organic plastic molecular solids	8 - 7
8.6.3	Miscellaneous plastic molecular solids	8 - 11
8.6.4	Non - plastic molecular solids	8 - 12
8.7	Diffusion tables for molecular solids	8 - 13
8.7.1	Self - diffusion in rare gas solids	8 - 13
8.7.2	Self - diffusion in organic plastic molecular solids	8 - 13
8.7.3	Self - diffusion in miscellaneous plastic molecular solids	8 - 18
8.7.4	Self - diffusion in organic non - plastic molecular solids	8 - 19
8.7.5	Self - diffusion in miscellaneous non - plastic molecular solids	8 - 21
8.7.6	Impurity diffusion in miscellaneous molecular solids	8 - 22
8.7.7	Effect of pressure on self - diffusion in miscellaneous molecular solids	8 - 22
8.7.8	Isotope mass effect diffusion in miscellaneous molecular solids	8 - 24
	Figures for 8	8 - 25
8.8	References for 8	8 - 33

9	Diffusion in glassy and semicrystalline polymers (F.FAUPEL, G. KROLL)	9 - 1
9.1	Introduction	9 - 1
9.1.1	Characteristics of diffusion in glassy polymers	9 - 1
9.1.2	Diffusion mechanisms in glassy polymers	9 - 4
9.1.2.1	Activation energy approach	9 - 4
9.1.2.2	Free volume approach	9 - 4
9.1.2.3	Effect of excess volume on diffusion in glassy polymers	9 - 6
9.1.2.4	Influence of partial crystallization and orientation	9 - 7
9.1.3	Measuring techniques	9 - 8
9.1.3.1	Permeation methods	9 - 8
9.1.3.2	Sorption methods	9 - 10
9.1.3.3	Other methods	9 - 12
9.1.4	Use of tables and figures	9 - 14
9.2	Tables for 9	9 - 17
9.2.1	(C -) main chain polymers	9 - 17
9.2.2	(C - N) main chain polymers	9 - 44
9.2.3	(C - N - O) main chain polymers	9 - 55
9.2.4	(C - N - O - S) main chain polymers	9 - 67
9.2.5	(C - N - S) main chain polymers	9 - 67
9.2.6	(C - O) main chain polymers	9 - 69
9.2.7	(C - O - S) main chain polymers	9 - 91
9.2.8	(C - S) main chain polymers	9 - 101
9.2.9	spiro - C - N - O polymers	9 - 102
9.2.10	spiro - C - O polymers	9 - 102
9.2.11	Blends	9 - 104
9.3	Figures for 9	9 - 106
9.4	References for 9	9 - 127

10	Chemical diffusion in bulk inhomogeneous non-metallic compounds (G.E. MURCH, C.M. BRUFF)	10 - 1
10.1	Introduction	10 - 1
10.2	Use of tables	10 - 2
10.3	Chemical diffusion table	10 - 3
	Antimonides	10 - 3
	Carbides	10 - 3
	Chalcogenides	10 - 5
	Halides	10 - 8
	Intercalation compounds	10 - 11
	Nitrides	10 - 15
	Nuclear materials	10 - 15
	Oxides	10 - 18
	Silicates	10 - 29
	Silicides	10 - 29
	Figures for 10	10 - 31
10.4	References for 10	10 - 58

11	Dislocation and grain-boundary diffusion in non-metallic systems (G. ERDÉLYI, D.L. BEKE)	11 - 1
11.1	Introduction	11 - 1
11.1.1	General remarks	11 - 1
11.1.2	Methods of measurement	11 - 2
11.1.2.1	Low angle grain boundary method	11 - 2
11.1.2.2	Defect annealing method	11 - 2
11.1.2.3	Indirect methods in type - A kinetic regime	11 - 2
11.1.2.4	Isoconcentration contour method	11 - 2
11.1.2.5	Determination of double products from creep and sintering experiments	11 - 3
11.1.2.6	Interdiffusion experiments in oxides	11 - 4
11.1.2.7	Hwang - Balluffi method	11 - 4
11.1.2.8	First appearance method	11 - 4
11.1.2.9	Gilmer - Farrell method	11 - 5
11.2	Use of tables and figures	11 - 5
11.3	Tables for dislocation diffusion in non - metallic systems	11 - 7
11.3.1	Dislocation diffusion in oxides	11 - 7
11.3.2	Dislocation diffusion in ionic crystals	11 - 9
11.3.3	Dislocation diffusion in some minerals	11 - 10
11.4	Tables for grain boundary diffusion in non - metallic systems	11 - 11
11.4.1	Grain boundary diffusion in oxides	11 - 11
11.4.2	Grain boundary diffusion in carbides and nitrides	11 - 28
11.4.3	Grain boundary diffusion in ionic crystals	11 - 31
11.4.4	Grain boundary diffusion in some minerals	11 - 34
	Figures for 11	11 - 36
11.5	References for 11	11 - 45

12	Surface diffusion on non-metallic solids (E.G. SEEBAUER, C.E. ALLEN)	12 - 1
12.1	Introduction	12 - 1
12.1	General remarks	12 - 1
12.1.2	Definitions of diffusion parameters	12 - 1
12.2	Experimental techniques	12 - 2
12.2.1	Single - atom imaging	12 - 2
12.2.2	Electron diffraction	12 - 2
12.2.3	Chemical state relaxation	12 - 3
12.2.4	Spin axis relaxation	12 - 3
12.2.5	Profile evolution	12 - 4
12.2.6	Capillarity - driven effects	12 - 4
12.2.7	Island growth	12 - 5
12.2.8	Miscellaneous	12 - 5
12.3	Physical picture	12 - 5
12.3.1	Intrinsic diffusion	12 - 5
12.3.2	Mass transfer diffusion	12 - 5
12.4	General correlations	12 - 7
12.4.1	Intrinsic diffusion	12 - 7
12.4.2	Mass transfer diffusion	12 - 7
12.4.3	Adsorbate concentration dependence	12 - 8
12.5	Commentary to tables	12 - 8
12.6	Surface diffusion tables	12 - 9
	Table 1: Intrinsic diffusion on insulators	12 - 9
	Table 2: Mass transfer diffusion on insulators	12 - 10
	Figures for 12	12 - 11
12.7	Special references: review articles	12 - 13
12.8	References for 12	12 - 14

Diffusion in Non-Metallic Solids without Volume Diffusion
in Oxides

1999, XVI, 575 p. 424 illus. With CD-ROM., Hardcover

ISBN: 978-3-540-62391-5