

Contents

1	Transmission Photoelasticity	1
1.1	Introduction	1
1.2	Physical Principle Used in Photoelasticity	1
1.3	Nature of Light	2
1.4	Polarization	3
1.5	Passage of Light Through Isotropic Media	4
1.6	Passage of Light Through a Crystalline Medium	5
1.7	Light Ellipse	6
1.8	Retardation Plates and Wave Plates	8
1.9	Stress-Optic Law	9
1.10	Plane Polariscope	10
1.10.1	Analysis by Trigonometric Resolution	13
1.11	Jones Calculus	14
1.11.1	Rotation Matrix	14
1.11.2	Retardation Matrix	15
1.11.3	Representation of a Retarder	16
1.11.4	Polarizer	17
1.11.5	Quarter-Wave Plate	17
1.12	Analysis of Plane Polariscope by Jones Calculus	17
1.13	Circular Polariscope	18
1.14	Use of White Light	20
1.15	Determination of Isoclinic and Isochromatic Fringe	
	Order at a Point	21
1.15.1	Ordering of Isoclinics	21
1.15.2	Ordering of Isochromatics	22
1.16	Tardy's Method of Compensation	22
1.17	Calibration of Photoelastic Model Materials	24
1.17.1	Stress Field in a Circular Disc Under Diametral Compression	24
1.17.2	Conventional Method	25
1.17.3	Sampled Linear Least Squares Method	26
	Need for a better methodology	26
	Use of whole field data to evaluate material fringe value	26
1.17.4	Theoretical Reconstruction of Fringe Patterns	28
1.18	Further Comments on Fringe Ordering	29
1.18.1	Properties of Isochromatic Fringe Field	30

1.18.2 Properties of Isoclinic Fringe Field	31
1.18.3 Use of Fringe Field Properties to Identify Fringe Ordering	32
1.18.4 Role of Principles of Solid Mechanics in Fringe Ordering	33
1.19 Determination of the Sign of the Boundary Stresses	34
1.20 Resolving the Ambiguity on the Principal Stress Direction	34
1.21 Introduction to Three-Dimensional Photoelasticity and Integrated Photoelasticity	35
1.21.1 Conventional Three-Dimensional Photoelasticity	36
1.21.2 Principle of Optical Equivalence	37
1.22 Model to Prototype Relations	39
1.23 Closure	42
Exercises	42
References	46
 2 Reflection Photoelasticity	 47
2.1 Introduction	47
2.2 Reflection Polariscopes	48
2.3 Stress and Strain-Optic Relations for Coatings	49
2.4 Coating and Specimen Stresses	50
2.5 Correction Factors for Photoelastic Coatings	52
2.6 Poisson's Ratio Mismatch	56
2.7 Coating Materials	57
2.8 Bonding the Coating	59
2.9 Selection of the Coating Thickness	60
2.10 Calibration of the Coating Material	62
2.11 Data Collection and Analysis	64
2.12 Application of Photoelastic Coatings	65
2.13 Closure	65
Exercises	65
References	66
 3 Digital Image Processing	 67
3.1 Introduction	67
3.2 Image Sampling and Quantization	67
3.2.1 Pictures as Functions	67
3.2.2 Uniform Sampling and Quantization	68
3.3 Video Standards	69
3.4 Image Sensors	71
3.5 Image Display	72
3.6 Image Perception	73
3.7 Image Storage	74

3.8	Some Basic Relationships and Mathematical Operations Between Pixels	74
3.8.1	Neighbours of a Pixel	74
3.8.2	Arithmetic and Logic Operations	75
3.8.3	Neighbourhood Oriented Operations	75
3.9	Basic Steps in Image Processing	77
3.10	Typical Image Processing Systems for Digital Photoelasticity	77
3.11	Software Structure and Design	79
3.12	Image Acquisition	80
3.13	Tools for Image Understanding	82
3.13.1	Pseudo Colouring	82
3.13.2	Histogram	83
3.13.3	Two-Dimensional and Three-Dimensional Intensity Plots	84
3.14	Filtering in Spatial Domain	86
3.14.1	Low Pass Spatial Filtering	88
3.14.2	Median Filtering	88
3.15	Image Enhancement	88
3.15.1	Contrast Stretching	89
3.15.2	Histogram Equalisation	90
3.16	Image Segmentation	91
3.16.1	Thresholding	91
	Global thresholding	92
	Semi thresholding	92
	Dynamic thresholding	92
3.16.2	Edge Detection	94
	Edge detection by convolution filters	94
	Edge detection by non-convolution filters	95
	Edge detection by thresholding	96
3.17	Morphological Filters	98
3.18	Further Discussions on Image Sensors	98
3.18.1	Operation of CCD Arrays	98
3.18.2	Interline Transfer CCD	100
3.18.3	Linearity and Dynamic Range	101
3.18.4	Sources of Noise	102
3.19	Digitisation of the Camera Video Signal	103
3.20	Resolution of an Image Processing System	103
3.21	Gamma Compensation	104
	Exercises	104
	References	105

4	Fringe Multiplication, Fringe Thinning and Fringe Clustering	107
4.1	Introduction	107
4.2	Fringe Multiplication	108

4.3	Half Fringe Photoelasticity (HFP)	110
4.4	DIP Methods for Fringe Thinning	111
4.5	Algorithms Based on Considering the Fringe Patterns as a Binary Image	112
4.6	Mask-Based Algorithms for Skeleton Extraction Using Intensity Variation within a Fringe	113
4.7	Global Identification of Fringe Skeletons Based on Intensity Variation	115
4.7.1	Edge Detection	115
4.7.2	Fringe Skeletonization	116
	Row-Wise scanning algorithm	116
	Algorithm for fringe skeleton extraction for arbitrarily shaped fringes	117
4.7.3	Applications of the Algorithm to Actual Experimental Conditions	120
4.8	Further Improvements on the Global Thinning Algorithm	123
4.9	Performance Evaluation of Various Fringe Thinning Algorithms	126
4.9.1	Comparison of the Skeleton Extraction	127
	Computer generated test images	127
	Images recorded from actual experimental situations	129
4.9.2	Comparison of the Computational Effort	131
4.10	Use of Tiling to Improve Information in Stress Concentration Zones	131
4.11	Fringe Tracing Algorithm	133
4.12	Ordering of Fringes	135
4.13	Closure	136
	Exercises	137
	References	138

5 Phase Shifting, Polarization Stepping and Fourier Transform Methods

5.1	Introduction	141
5.2	Early Attempts for Automated Polariscopes	142
5.3	Phase Shifting in Photoelasticity	144
5.4	Intensity of Light Transmitted for a Generic Arrangement of a Plane Polariscopes	146
5.5	Intensity of Light Transmitted for a Generic Arrangement of a Circular Polariscopes	149
5.6	Evaluation of Fractional Fringe Order along an Isoclinic Contour	152
5.7	Whole Field Evaluation of Photoelastic Data by Using a Plane Polariscopes	153
5.8	Whole Field Evaluation of Photoelastic Data by Using a Circular Polariscopes	155

5.8.1	The Generic Procedure	155
5.8.2	Calculation and Representation of Whole Field Data	159
5.8.3	Parameters Affecting the Generation of Phase Map and its Solution	162
	Influence of local oscillations of isoclinic parameter on fractional retardation calculation	162
	Importance of isoclinic parameter representing either σ_1 or σ_2 direction over the domain	163
	Ambiguity in experimentally evaluating the isoclinic parameter	167
	Interactive approach to obtain a good phase map	169
5.9	Error Sources and Methods to Minimise Their Influence	172
5.9.1	Influence of Error in Measuring Intensities	174
5.9.2	Errors Due to Mismatch of Quarter-Wave Plates	177
5.10	Evaluation of Isoclinic Value by Phase Shifting Technique	181
5.10.1	Use of Two Loads to Get Continuous Isoclinic Contours	181
5.10.2	Use of Multiple Wavelengths to Get Continuous Isoclinic Contours	183
5.11	Polarization Stepping for Isoclinic Determination	185
5.12	Fourier Transform Methods for Photoelastic Data Acquisition	188
5.12.1	Use of Carrier Fringes	188
5.12.2	Use of Multiple Polarization Stepped Images	189
5.12.3	Use of Load Stepping	191
5.13	Comparative Evaluation of Phase Shifting, Polarization Stepping and Fourier Transform Techniques	192
5.14	Closure	193
	Exercises	193
	References	194

6 Phase Unwrapping and Optically Enhanced Tiling in Digital Photoelasticity

6.1	Introduction	199
6.2	Boundary Detection	200
6.3	Noise Removal in Phase Maps	201
6.4	Algorithm for Phase Unwrapping	202
6.5	Representation of the Unwrapped Phase.	205
6.5.1	Three-Dimensional Plots	205
6.5.2	Total Fringe Order Viewing on the Image	206
6.6	Parameters Affecting Phase Unwrapping	207
6.6.1	Influence of the Selection of the Phase Unwrapping Threshold	207
6.6.2	Influence of the Location of the Primary Seed Point.	209
6.7	Use of Tiling Procedure for Phase Unwrapping.	210

6.8	Digital Magnification of High Fringe Density Zones	211
6.8.1	Replication	211
6.8.2	Linear Interpolation	212
6.8.3	Higher Order Interpolation	212
6.9	Optically Enhanced Tiling (OET)	212
6.10	Cementing of a Tile	213
6.11	OET Applied to a Circular Disc Under Diametral Compression	215
6.12	OET Applied to a Ring Under Diametral Compression.	217
6.13	Closure	219
	Exercises	220
	References	220

7 Colour Image Processing Techniques 221

7.1	Introduction	221
7.2	Colour Models	223
7.2.1	RGB Model	224
7.2.2	HSI Model	225
7.3	Colour Image Processing Systems	226
7.3.1	Hardware	226
	Transmission Photoelasticity	227
	Reflection Photoelasticity	227
7.3.2	Software	228
7.4	Typical Spectral Response of a Colour Camera	228
7.5	Intensity of Light Transmitted in White Light for Various Polariscope Arrangements	230
7.6	Three Fringe Photoelasticity (TFP)	234
7.6.1	Calibration	235
7.6.2	Methodology	240
7.6.3	Application to the Problem of a Circular Disc Under Diametral Compression	240
7.7	Green Image Plane as a Green Filter	243
7.8	Phase Shifting in Colour Domain	244
7.8.1	Transmission Photoelasticity	244
7.8.2	Reflection Photoelasticity	246
7.9	Spectral Content Analysis (SCA)	249
7.10	Digital Spectral Content Analysis (DSCA)	252
7.11	Hybrid Techniques	252
7.11.1	Polarization Stepping in Colour Domain	253
7.12	Tricolour Photoelastic Method	254
7.13	Closure	258
	Exercises	261
	References	261

8 Evaluation of Contact Stress Parameters and Fracture Parameters	265
8.1 Introduction	265
8.2 Basic Data Required and its Digital Acquisition	266
8.2.1 Conversion of Pixel Co-ordinates to Model Co-ordinates	266
8.2.2 Rotational Transformation	267
8.3 Stresses in Terms of Contact Length and Geometrical and Elastic Properties of the Bodies in Contact	268
8.4 Evaluation of Contact Stress Parameters by Least Squares Analysis	270
8.4.1 Validation for Hertzian and Non-Hertzian Contact	272
8.5 Developments in the Description of the Stress Field Equations in the Neighbourhood of a Crack-tip	273
8.5.1 Mode-I Stress Field Equations	273
8.5.2 Mixed-Mode (Combination of Mode-I and Mode-II) Stress Field Equations	276
8.5.3 Equivalence Between the Multi-Parameter Stress Field Equations	278
8.6 Developments in SIF Evaluation Methodology	278
8.7 Evaluation of Mixed-Mode Stress Field Parameters Using Least Squares Technique	281
8.8 Experimental Validation of the Methodology	284
8.8.1 Mode-I Loading	284
8.8.2 Mixed-Mode Loading	288
8.9 Contact Stress and Fracture Analysis of a Spur Gear	290
8.9.1 Loading Frame Design	290
8.9.2 Evaluation of Contact Parameters	292
Measurement of radius of curvature at the point of contact	292
Experimental results	293
8.9.3 Evaluation of Fracture Parameters	294
8.10 Closure	298
Exercises	299
References	299
9 Stress Separation Techniques	303
9.1 Introduction	303
9.2 Oblique Incidence Method	304
9.2.1 Secondary Principal Stresses	304
9.2.2 The Methodology	305
9.3 Shear Difference Technique	307
9.3.1 Conventional Method	307
9.3.2 Improvement by Tesar	308

9.4	Survey of Numerical Methods	309
9.4.1	Integration of Compatibility Condition	309
	Finite difference approach	309
9.4.2	Integration of Stress Difference Equations	312
9.4.3	Least Squares Method	314
9.4.4	Hybrid Techniques	316
9.4.5	Methods Using Only Isochromatic Data	317
9.5	Stress Separation by Combined Phase Shifting and FEM	318
9.5.1	Finite Element Formulation	319
9.5.2	Meaningful Discretization of the Domain	323
9.5.3	Plotting of Fringe Contours from FE Results	324
9.5.4	Influence of Error in Fringe Data	327
9.5.5	Application of the Technique to the Problem of Plate with a Hole	330
9.6	Use of Integrated Photoelasticity Concepts for Stress Separation	332
9.6.1	Least Squares Algorithm	333
9.6.2	Design of the Loading Frame	333
9.6.3	Application to the Problem of Disc under Diametral Compression	334
9.7	Stress Separation in Three-Dimensional Photoelasticity	337
9.8	Stress Separation in Reflection Photoelasticity	342
9.8	Closure	344
	Exercises	344
	References	345

10 Fusion of Digital Photoelasticity, Rapid Prototyping and Rapid Tooling Technologies 347

10.1	Introduction	347
10.2	Difficulties in Conventional Three-Dimensional Photoelasticity	348
10.3	Rapid Prototyping in Model Making	348
10.3.1	Software Issues in RP	349
10.3.2	Stereolithography Process	351
10.3.3	Solid Ground Curing	354
10.3.4	Fused Deposition Modelling	355
10.4	Direct Analysis of RP Models by Photoelastic Coatings	356
10.4.1	Experimental Results	357
10.4.2	Analysis of the Results	358
	Evaluation of Young's modulus by tensile test	358
	Study on the seepage of the adhesive	359
	Numerical simulation of fringe patterns	359
10.4.3	Recommendations	361
10.5	Direct Use of RP Models for Transmission Photoelastic Analysis	361

10.6 Rapid Tooling for Model Making	363
10.6.1 Basic Steps in Rapid Tooling	363
10.6.2 Digital Photoelastic Characterisation of the Process	364
10.7 Closure	365
Exercises	366
References	366

11 Recent Developments and Future Trends 369

11.1 Introduction	369
11.2 Evaluation of Characteristic Parameters	369
11.2.1 Srinath and Keshavan's Method	370
11.2.2 Whole Field Determination of Characteristic Parameters by Phase Shifting	371
Development of relevant equations.	371
Experimental evaluation of characteristic parameters	375
Whole field theoretical evaluation of characteristic parameters.	375
11.3 Tensorial Tomography	378
11.4 Developments in DIP Hardware	383
11.5 Developments in DIP Software	384
11.5.1 Development of a Device Independent Software	385
Selection of software features	385
FRN_DAT software	385
An application	386
11.5.2 Future Possibility	387
11.6 Digital Dynamic Photoelasticity	388
11.6.1 Classification of High, Very-high and Ultra-high-speed Photography.	388
11.6.2 Classical Methods for High-speed Photography	388
11.6.3 Digital Dynamic Recording.	391
11.7 Application to Composites	395
11.7.1 Photo-Orthotropic Elasticity Theories	396
Stress-Optic law	396
Strain-Optic law	397
11.7.2 Calibration of Photo-Orthotropic Composites	398
11.7.3 Influence of Residual Birefringence	399
11.7.4 Separation of Stresses in Photo-Orthotropic Elasticity	400
11.7.5 Application of Digital Photoelasticity to Composites	400
11.8 Closure	401
Exercises	401
References	401

Index	405
--------------	-----

Digital Photoelasticity

Advanced Techniques and Applications

Ramesh, K.

2000, XX, 410 p. 103 illus. With CD-ROM., Hardcover

ISBN: 978-3-540-66795-7