

LB-SEARCH

LB-CONTENTS

GROUP III: Condensed Matter

VOLUME 42

Physics of Covered Solid Surfaces

SUBVOLUME A2

Adsorbed Layers on Surfaces. Part 2: Measuring Techniques and Surface Properties Changed by Adsorption

	Title Page, Preface, Contributors	
2	Characterization of adsorbate overlayers: measuring techniques (CH. WÖLL)	1
2.1	Introduction	1
2.2	Direct methods	4
2.3	Techniques based on a mass spectrometer	7
2.4	Techniques for a chemical analysis	9
2.5	Structural sensitive techniques	13
2.6	Imaging techniques	21
2.7	Vibrational spectroscopy of adsorbed particles	25
2.8	Techniques probing the electronic structure	28
2.9	Nonlinear optical techniques	32
2.10	Bulk techniques - Nuclear Magnetic Resonance (NMR) and Electron Spin Resonance (ESR)	33
	References for 2	35
4	Data: Adsorbate-induced changes of substrate properties	43
4.1	Surface structure on metals and semiconductors (M.A. VAN HOVE, K. HERMANN, P.R. WATSON)	43
4.1.1	Introduction	43
4.1.2	Relaxation vs. reconstruction	43
4.1.3	Notations and conventions	45
4.1.4	Organization of the tables	46
4.1.5	Organization of data for individual structures	46
4.1.6	Adsorption on fcc(111)	48
4.1.7	Adsorption on hcp(0001)	48
4.1.8	Adsorption on bcc(110)	49
4.1.9	Adsorption on fcc (100)	49
4.1.10	Adsorption on bcc (100), pure or alloyed	50
4.1.11	Adsorption on fcc (110)	50
4.1.12	Adsorption on hcp (10-10)	51
4.1.13	Adsorption on bcc (211)	51
4.1.14	Adsorption on bcc (111)	51
4.1.15	Adsorption on Si, Ge and C(111)	51
4.1.16	Adsorption on Si and Ge(100)	52
4.1.17	Adsorption on diamond-like(311)	52
4.1.18	Adsorption on zincblende(110)	52
4.1.18	Adsorption on zincblende(110)	52
4.1.19	Adsorption on zincblende(111) and (-1-1-1)	53
4.1.20	Adsorption on zincblende(100)	53
4.1.21	Adsorption on 6H-SiC(0001)	53
	Acknowledgments	53

	Tables for 4.1	54
	Figures for 4.1	141
	References for 4.1	151
4.2	Electron work function of metals and semiconductors (K. JAKOBI)	165
4.2.1	Introduction	165
4.2.2	Rare gases	171
4.2.3	Atomically chemisorbed adsorbates	177
4.2.4	Small molecules	199
4.2.5	Nonpolar hydrocarbons	215
4.2.6	Polar hydrocarbons	222
4.2.7	Halohydrocarbons	224
4.2.8	Other hydrocarbons	226
4.2.9	Alkali metals	227
4.2.10	Noble metals	240
4.2.11	3d transition metals	247
4.2.12	4d transition metals	250
4.2.13	5d transition metals	253
4.2.14	Rare-earth metals	255
4.2.15	Group IIa metals	257
4.2.16	Group IIIa metals	259
4.2.17	Group IVa elements	260
4.2.18	Group Va elements	262
4.2.19	Other elements	263
	Figures for 4.2	264
	References for 4.2	282
4.4	Surface free energy and surface stress (D. SANDER, H. IBACH)	303
4.4.1	Introduction	303
4.4.2	Experimental determination of surface free energy	304
4.4.3	Experimental determination of the absolute value of the surface stress	310
4.4.4	Experimental determination of changes of surface stress due to adsorption	312
4.4.5	Calculations of surface free energy and surface stress	315
4.4.6	Data	320
4.4.7	Clean surfaces	321
4.4.8	Adsorbate-induced changes of surface free energy	336
4.4.9	Adsorbate-induced changes of surface stress	338
4.5	Surface phonon dispersion (M.A. ROCCA)	352
4.5.1	Introduction	352
4.5.2	Data collection	358
	Acknowledgements	375
	Figures for 4.5	376
	References for 4.5	419

Measuring Techniques and Surface Properties Changed
by Adsorption

Hermann, K.; Ibach, H.; Jacobi, K.; Rocca, M.A.; Sander,
D.; Hove, M.A.V.; Watson, P.R.; Wöll, C.

2002, XXII, 429 p. 241 illus. With CD-ROM., Hardcover

ISBN: 978-3-540-41224-3