



Contents

Preface	vii
1 Introduction	1
1.1 Measurand and Measurement Errors	1
1.2 Exercises	7
2 Mean and Standard Deviation	9
2.1 Estimation of Mean and Variance	9
2.2 How to Round off the Measurement Data	17
2.3 Normal Distribution in Measurements	19
2.4 The Uniform Distribution	24
2.5 Dixon's Test for a Single Outlier	26
2.6 Using Range to Estimate σ	28
2.7 Confidence Interval for the Population Mean	30
2.8 Control Charts for Measurement Data	32
2.9 Exercises	40
3 Comparing Means and Variances	43
3.1 t -test for Comparing Two Population Means	43
3.2 Comparing More Than Two Means	50
3.3 Comparing Variances	54
3.4 Exercises	56
4 Sources of Uncertainty: Process and Measurement Variability	59
4.1 Introduction: Sources of Uncertainty	59
4.2 Process and Measurement Variability:	
One-way ANOVA with Random Effects	60
4.3 Hierarchical Measurement Design	66
4.3.1 The Mathematical Model of Hierarchical Design	67
4.3.2 Testing the Hypotheses $\sigma_A = 0, \sigma_{B(A)} = 0$	70
4.4 Repeatability and Reproducibility Studies	71
4.4.1 Introduction and Definitions	71

4.4.2	Example of an R&R Study	72
4.4.3	Confidence Intervals for R&R Parameters	76
4.5	Measurement Analysis for Destructive Testing	78
4.6	Complements and Exercises	82
5	Measurement Uncertainty: Error Propagation Formula	87
5.1	Introduction	87
5.2	Error Propagation Formula	88
5.3	EPF for Particular Cases of $Y = f(X_1, \dots, X_n)$	90
5.4	Exercises	93
6	Calibration of Measurement Instruments	95
6.1	Calibration Curves	95
6.1.1	Formulation of the Problem	95
6.1.2	Linear Calibration Curve, Equal Response Variances	97
6.2	Calibration Curve for Nonconstant Response Variance	103
6.2.1	The Model and the Formulas	103
6.2.2	Uncertainty in x^* for the Weighted Case	106
6.3	Calibration Curve When Both Variables Are Subject to Errors	107
6.3.1	Parameter Estimation	107
6.3.2	Uncertainty in x When Both Variables Are Subject to Errors	111
6.4	Exercises	111
7	Collaborative Studies	113
7.1	Introduction: The Purpose of Collaborative Studies	113
7.2	Ruggedness (Robustness) Test	115
7.3	Elimination of Outlying Laboratories	118
7.4	Homogeneity of Experimental Variation	120
8	Measurements in Special Circumstances	123
8.1	Measurements With Large Round-off Errors	123
8.1.1	Introduction and Examples	123
8.1.2	Estimation of μ and σ by Maximum Likelihood Method: $Y^* = 0$ or 1	125
8.1.3	Estimation of μ and σ : $Y^* = 0, 1, 2$	128
8.2	Measurements with Constraints	130
8.3	Exercises	132
	Answers and Solutions to Exercises	133

CONTENTS

xiii

Appendix A: Normal Distribution

137

Appendix B: Quantiles of the Chi-Square Distribution

139

Appendix C: Critical Values of the F -distribution

141

References

143

Index

147



<http://www.springer.com/978-3-540-00081-5>

Measurement Theory for Engineers

Gertsbakh, I.

2003, XIII, 150 p., Hardcover

ISBN: 978-3-540-00081-5