
Contents

1	Casting of Light Metals	1
1.1	Casting Processes	1
1.2	Sand Casting	1
1.2.1	Gating System	2
1.2.2	Risers and Chills	2
1.3	Permanent Mould	3
1.3.1	Gravity Casting	4
1.3.2	Low-pressure Permanent Mould Casting	4
1.3.3	Counterpressure Casting	4
1.4	Die Casting	5
1.4.1	Die-cast Process	5
1.4.2	Die-cast Dies	8
1.4.3	Runner System	8
1.4.4	Cavity of Die-cast Die	11
1.4.5	Air Ventilation System	11
1.4.6	Ventilation Blocks	12
2	Introduction to Fluid Dynamics	13
2.1	Basic Concepts	13
2.1.1	Pressure	13
2.1.2	Viscosity	14
2.1.3	Temperature and Enthalpy	16
2.2	Equations of Motion	18
2.3	Boundary Conditions	19
2.3.1	Velocity Boundary Conditions at Walls	20
2.3.2	Thermal Boundary Conditions at Walls	20
2.3.3	Free Surface Boundary Conditions	21
2.4	Useful Dimensionless Numbers	23
2.4.1	Definitions	23
2.4.2	The Reynolds number	24
2.4.3	The Weber Number	24

2.4.4	The Bond Number	25
2.4.5	The Froude Number.....	25
2.5	The Bernoulli Equation.....	26
2.6	Compressible Flow	26
2.6.1	Equation of State	27
2.6.2	Equations of Motion.....	28
2.6.3	Specific Heats.....	29
2.6.4	Adiabatic Processes.....	31
2.6.5	Speed of Sound.....	31
2.6.6	Mach Number.....	33
2.6.7	The Bernoulli Equation for Gases	33
2.7	Computational Fluid Dynamics	35
2.7.1	Computational Mesh.....	35
2.7.2	Numerical approximations	36
2.7.3	Representation of Geometry	38
2.7.4	Free Surface Tracking	39
2.7.5	Summary	41
3	Part Design	43
3.1	Design of Light Metal Castings	43
3.2	Static Analysis	43
3.2.1	Moment of an Area.....	44
3.2.2	Moment of Inertia of an Area	44
3.3	Loading	46
3.4	Stress Components.....	47
3.4.1	Linear Stress.....	48
3.4.2	Plane Stress.....	50
3.4.3	Mohr's Circle.....	51
3.5	Hooke's Law.....	55
3.6	Saint-Venant's Principle	56
3.7	Criteria of Failure.....	57
3.7.1	Ductile Material Failure Theory	58
3.7.2	Brittle Material Failure Theory.....	58
3.8	Beam Analysis	58
3.8.1	Free Body Diagram	67
3.8.2	Reactions	67
3.9	Buckling	68
3.10	Bending Stresses.....	71
3.10.1	Normal Stresses in Bending	72
3.10.2	Shear Stress	74
3.11	Stresses in Cylinders.....	76
3.12	Press-fit Analysis	82
3.13	Thermal Stresses.....	86
3.14	Torque.....	87
3.15	Stress Concentration	93

3.16 Fatigue	94
3.17 MATLAB® Functions Used in Chapter 3	96
4 Process Design	97
4.1 Evaluation of Dimensionless Numbers	97
4.1.1 Gravity Pour	98
4.1.2 High-pressure Die Casting: Slow Shot	98
4.1.3 High-pressure Die Casting: Fast Shot	99
4.2 Flow in Viscous Boundary Layer	100
4.3 The Bernoulli Equation	102
4.3.1 Stagnation, Dynamic and Total Pressure	102
4.3.2 Gravity Controlled Flow	103
4.3.3 Flow in the Runner System	104
4.3.4 Filling Rate	106
4.4 Flow in a Shot Cylinder	108
4.5 Gas Ventilation System	116
4.6 Ventilation Blocks	125
4.7 Little's Formula	126
4.8 Poisson Process and the Exponential Distribution	127
4.9 Cooling	132
4.9.1 Lumped-temperature Model	132
4.9.2 Heat Flow into a Semi-infinite Medium	138
4.10 CFD Simulations	141
4.10.1 High-pressure Die Casting	142
4.10.2 Gravity Sand Casting	152
5 Quality Control	157
5.1 Basic Concepts of Quality Control	157
5.2 Definition of Quality	158
5.3 Definition of Control	158
5.4 Statistical Process Control	159
5.5 Tabular Summarization of Data	160
5.6 Numerical Data Summarization	160
5.6.1 Normal Probability Distribution	161
5.6.2 Poisson Probability Distribution	162
Appendix	165
A.1 Unit Conversions	165
A.2 Prefixes	171
References	173
Index	175

Casting: An Analytical Approach

Reikher, A.; Barkhudarov, M.R.

2007, XI, 177 p. With CD-ROM., Hardcover

ISBN: 978-1-84628-849-4