



Figure 6.2. Principle of the spin-coating process and illustration of the characteristic time regimes during rotation and solvent evaporation. Step 1: placement of coating solution. Step 2: start of rotation (3000 rpm) and expulsion of solution. Step 3: laminar radial flow of solution and increase in viscosity. Step 4: evaporation of remaining solvent.