

Contents

- 1 Introduction 1**
- 2 Metrology and Workpiece Quality 3**
 - 2.1 Manufacturing Disturbances and Manufacturing History 3
 - 2.2 Measuring and Testing 8
 - 2.2.1 Measurement Errors 9
 - 2.2.2 Macro- and Microgeometry of Components 10
 - 2.3 Length Testing Devices 13
 - 2.3.1 Material Measures 13
 - 2.3.2 Gauges 13
 - 2.3.3 Indicating Measuring Instruments 14
 - 2.4 Surface Inspection 21
 - 2.4.1 Surface Parameters 22
 - 2.4.2 Subjective Surface Inspection 26
 - 2.4.3 Surface Measurement 27
 - 2.5 Inspection of the Workpiece Rim 30
 - 2.5.1 Surface Layers 31
 - 2.5.2 Inspection of the Surface Rim Zone 33
- 3 Fundamentals of Cutting 39**
 - 3.1 The Cutting Part – Concepts and Terms 39
 - 3.2 Reference Systems 42
 - 3.3 Basic Process Variants 45
 - 3.4 Chip Formation 47
 - 3.4.1 The Cutting Process 47
 - 3.4.2 Different Types of Chip Formation 49
 - 3.5 Kinematic Surface Roughness 54
 - 3.6 Mechanical and Thermal Strain on the Cutting Section 55
 - 3.6.1 Influence of the Geometry of the Cutting Section 68
 - 3.7 Wear 71
 - 3.7.1 Wear Mechanisms 71
 - 3.7.2 Causes of Wear 74
 - 3.7.3 Forms and Dimensions of Wear 85

3.8	Cutting Theory	87
3.8.1	Shear Plane Theory	87
3.8.2	Application of Plasticity Theory to Cutting	92
4	Cutting Tool Materials and Tools	95
4.1	Overview of Cutting Tool Materials	95
4.1.1	Classification of Hard Cutting Tool Materials	97
4.2	Tool Steels	99
4.2.1	Cold Work Steels	100
4.2.2	High Speed Steels	101
4.3	Cemented Carbides	110
4.3.1	Historical Development	111
4.3.2	Cemented Carbide Production	112
4.3.3	Components of Cemented Carbides and Their Properties	114
4.3.4	Microstructure	116
4.3.5	Classification of Cemented Carbides	117
4.3.6	Uncoated Cemented Carbides and Cermets	123
4.3.7	Function Gradient Cemented Carbides	123
4.3.8	Coated Cemented Carbides and Cermets	126
4.4	Coatings	127
4.4.1	Coating Methods	128
4.4.2	Specific Properties of Hard Material Coatings	149
4.4.3	Substrate Pretreatment	161
4.5	Ceramic Cutting Tool Materials	161
4.5.1	Cutting Ceramics	162
4.5.2	Superhard Non-metallic Cutting Tool Materials	173
4.6	Tool Designs	184
4.6.1	Solid Tools	185
4.6.2	Tools with Inserts	187
4.7	Tool Preparation	193
5	Finite Element Method (FEM)	197
5.1	Basic Concepts of FEM	197
5.2	Lagrangian and Eulerian Considerations of the Continuum	199
5.3	Explicit and Implicit Methods of Solution	199
5.4	Combined Thermal and Mechanical FEA	200
5.5	Nonlinearities	200
5.6	Material Laws	201
5.7	Software	204
5.8	Hardware	205
5.9	Phases of a Finite Element Analysis (FEA)	205
5.10	The Use of FEM in Cutting Technology	206
5.10.1	Continuous Chip Simulation	207
5.10.2	Segmented Chip Simulation	209
5.10.3	Simulation of the Cutting Process	212

6	Cutting Fluids	219
6.1	The Functions of Cutting Fluids	219
6.2	Types of Cutting Fluids	219
6.2.1	Non Water-Miscible Cutting Fluids	220
6.2.2	Water-Based Cutting Fluids	221
6.3	Guidelines on the Use of Coolant Emulsions	222
6.4	Effects of the Cutting Fluid on the Machining Process	223
6.5	Selection of Cutting Fluids	226
6.6	Reducing or Avoiding the Use of Cutting Fluids	227
6.6.1	Reducing Cutting Fluids	228
6.6.2	Minimum Quantity Cooling Lubrication (MQCL)	229
6.6.3	Avoiding Cutting Fluids	233
7	Tool Life Behaviour	237
7.1	Determining Tool Life Parameters	239
7.2	Machinability	239
7.2.1	Tool Life	240
7.2.2	Resultant Force	243
7.2.3	Surface Quality	245
7.2.4	Chip Form	248
7.2.5	Cutting Speed	248
7.3	The Machinability of Steel Materials	249
7.3.1	Metallographic Constituents	250
7.3.2	Carbon Content	252
7.3.3	Alloying Elements	254
7.3.4	Types of Heat Treatment	256
7.4	Machinability of Various Steel Materials	263
7.4.1	Machining Steels	263
7.4.2	Case-Hardened Steels	266
7.4.3	Heat-Treatable Steels	267
7.4.4	Nitrided Steels	268
7.4.5	Tool Steels	269
7.4.6	Hardened Steels	271
7.4.7	Non-rusting Steels	274
7.5	Machinability of Cast Iron	280
7.5.1	White Cast Iron	280
7.5.2	Grey Cast Iron	283
7.6	Machinability of Non-ferrous Metals	290
7.6.1	Aluminium Alloys	290
7.6.2	Magnesium Alloys	293
7.6.3	Titanium Alloys	296
7.6.4	Copper Alloys	311
7.6.5	Nickel Alloys	314
7.7	Machinability of Non-metals	327
7.7.1	Graphite	327
7.7.2	Fibre-Reinforced Plastics	331

8	Process Design and Process Monitoring	339
8.1	Finding Economical Cutting Parameters	339
8.1.1	Cutting Parameter Limits	339
8.1.2	Optimizing the Cutting Parameters	342
8.1.3	Calculating the Machine Hour-Rate	350
8.1.4	Planning Methods and Tools	351
8.2	Process Monitoring	352
8.2.1	Sensors for Process Monitoring	354
8.2.2	Signal Processing and Monitoring Strategies	371
9	Processes with Rotational Primary Movement	383
9.1	Turning	383
9.1.1	Face Turning	385
9.1.2	Cylindrical Turning	386
9.1.3	Helical Turning	387
9.1.4	Profile Turning	388
9.1.5	Form Turning	389
9.1.6	Further Process Variants	390
9.2	Milling	390
9.2.1	Process Variants, Specific Characteristics and Tools	395
9.3	Drilling	416
9.3.1	Profile Counterboring	416
9.3.2	Rotary Drilling	418
9.4	Sawing	439
9.4.1	Bandsawing	439
9.4.2	Hacksawing	442
9.4.3	Circular Sawing	442
10	Processes with Translatory Primary Movement	445
10.1	Broaching	445
10.1.1	Face and Circular Broaching	446
10.1.2	Profile Broaching	449
10.1.3	Form Broaching	451
10.2	Shaving	454
10.3	Planing and Shaping	457
10.3.1	Face Shaping and Face Planing	458
10.3.2	Gear Shaping	459
10.3.3	Gear Planing	466
	References	469
	Subject Index	497



<http://www.springer.com/978-3-642-11978-1>

Manufacturing Processes 1

Cutting

Klocke, F.

2011, XVIII, 506 p., Hardcover

ISBN: 978-3-642-11978-1