

Contents

1	Introduction	1
1.1	General	1
1.2	Radiometric, Photometric, and Photonic Quantities and Units	3
1.3	Relationship Between Radiometric, Photometric, and Photonic Units	8
1.4	The Essential Features Required of Metrological Assurance for Radiometric Measurements	9
	References	10
2	Radiation Sources in Radiometric Applications	11
2.1	General	11
2.2	Calibrated Sources of Thermal Radiation	11
2.2.1	Planck's Law in Different Units	13
2.2.2	Radiation from True Bodies	14
2.2.3	The Brightness and Color Temperatures in Measurements with Strip Lamps	17
2.2.4	Quartz Tungsten–Halogen Lamps	17
2.3	Gas-Discharge Radiation Sources for the UV of $\lambda > 190$ nm	20
2.4	Gas-Discharge Radiation Sources for Vacuum UV of $\lambda > 115$ nm	23
2.5	Synchrotron Radiation	24
2.5.1	Calibration of Radiation Sources	26
2.5.2	Calibration of Photodetectors	28
	References	29
3	Photodetectors in Radiometric Applications	31
3.1	Classification of Photodetectors	31
3.2	Operational Features of Photodetectors	32
3.2.1	Photodetector Responsivity	32
3.2.2	Spectral Responsivity	33
3.2.3	Total Responsivity	36

3.2.4	Responsivity of Nonlinear Photodetectors	37
3.2.5	Effects Affecting Responsivity	37
3.2.6	Noise and Detectivity	39
3.2.7	Dynamic Characteristics of Photodetectors	40
3.3	Thermal Detectors	41
3.3.1	Thermocouples and Thermopiles	41
3.3.2	Electrical Substitution and Cryogenic Radiometers	42
3.3.3	Bolometers and Thermistors	43
3.3.4	Pyroelectric Detectors	44
3.3.5	Golay Pneumatic Detectors	44
3.4	Photoemissive Detectors	45
3.4.1	Vacuum Phototubes	49
3.4.2	Photomultiplier Tubes	52
3.4.3	CCD Cameras	62
3.5	Photodetectors with the Internal Photoeffect	63
3.5.1	Photoconductors	64
3.5.2	Junction Photodetectors	64
3.6	Luminescence Quantum Counters	65
3.7	Photoionization Chambers	66
3.8	Chemical Photodetectors	68
3.8.1	Requirements to Well-Established Actinometers	69
3.8.2	Basic Advantages of Actinometers	70
3.8.3	Primary and Secondary Photochemical Processes. Quantum Yields of the Gas-Phase Photoprocesses	71
3.8.4	Photoprocesses in Condensed Phase	78
3.8.5	Gas-Phase Actinometers	78
3.8.6	Liquid-Phase Actinometers	96
	References	97
4	Methods of Absolute Calibration for Photodetectors and Light Sources	103
4.1	General	103
4.2	Calibration by Means of Standard Detectors	105
4.2.1	The Visible and Near UV Spectral Range	106
4.2.2	The Vacuum UV Spectral Range	112
4.3	Calibration by Means of Standard Sources	117
4.3.1	Photodetector Calibration by Means of Resonance Lamps ...	118
4.3.2	Photodetector Calibration by Means of Strip Lamps	118
4.4	Absolute Intensity Measurements of Light Sources Used in Experiments	120
4.4.1	The Visible and Near UV Spectral Range	120
4.4.2	The Vacuum UV Spectral Range	121
	References	124

5 Methods of Calibration of Spectral Instruments	
in Arbitrary Units	125
5.1 General	125
5.2 Sensitivity Calibration Using Calibrated Strip and Quartz Tungsten–Halogen Lamps for Spectrometer/Photodetector Systems	127
5.3 Sensitivity Calibration of Spectrometer/Photodetector Systems in the UV Spectral Range	130
5.4 Calibration of Lens (Condenser)/Spectrometer/Photodetector System	131
5.4.1 The Layout Impact on the Spectral Sensitivity Function	131
5.4.2 Scheme and Algorithm of Calibration of Condenser/Spectrometer/Photodetector System	137
5.5 Sensitivity Calibration of Spectrometer/Photodetector Systems in the VUV Spectral Range	145
5.5.1 Extended Hydrogen (Deuterium) Lamp	146
5.5.2 Collapsible Extended Hydrogen-Discharge Lamp	149
5.5.3 Branching Ratio Methods	150
5.5.4 Double Monochromator Methods	151
5.6 Sensitivity Calibration of Spectrometer/Photodetector Systems by Means of Well-Known Spectra	152
5.6.1 Test of the Calibration Method	159
5.7 Calibration of Spectral Transmittance of Spectral Device	161
References	161
6 Absolute Measurements of Spectral Radiation Intensity of Processes Under Study	165
6.1 General	165
6.2 Absolute Intensity Measurements from Point Source, Illuminating Sphere, and Illuminating Plane	166
6.2.1 Point Source and Uniform Illuminating Sphere	166
6.2.2 Uniform Illuminating Plane	167
6.3 Absolute Calibration of Registration Systems by Means of Well-Known Photoprocesses	167
6.3.1 Calibration by Means of Rayleigh Scattering	168
6.3.2 Calibration by Means of Photoluminescence	172
6.3.3 Absolute Measurements of Spectral Radiation Intensity of the Uniform Illuminating Cylinder	174
6.4 Absolute Calibration of Spectrometer/Photodetector Systems	174
References	179
Solution of the problems	181
Appendix A	185
Appendix B	189
Index	193



<http://www.springer.com/978-3-7091-0103-2>

Radiometry in Modern Scientific Experiments

Anatoly, P.

2011, XVIII, 196 p., Hardcover

ISBN: 978-3-7091-0103-2