

# Contents

<b>1 Crystallographic Aspects of Interfaces in Ferroelectrics and Related Materials</b>	1
1.1 Domain Structures and Interfaces	
Between Polydomain Regions	2
1.1.1 Formation of Domain Structures in Ferroelectric Single Crystals	2
1.1.2 Elastic-Matching Concept and Its Application to Domain Boundaries	4
1.1.3 Classification of Domain Boundaries in Ferroelectric Single Crystals	8
1.1.4 Crystallographic Interpretation of Interfaces in the Case of Complicated Domain Structures	8
1.2 Phase Coexistence at First-Order Phase Transitions	12
1.2.1 Elastic Matching of Phases and Zero-Net-Strain Planes	12
1.2.2 Stress Relief and Conical Interphase Boundaries	16
1.3 Polydomain/Heterophase Ferroelectrics	18
References	19
<b>2 Two-Phase States</b>	23
2.1 Elastic Matching of Morphotropic Phases in $\text{Pb}(\text{Zr}_{1-x}\text{Ti}_x)\text{O}_3$	25
2.1.1 Tetragonal–rhombohedral Phase Coexistence and Crystallographic Interpretation	25
2.1.2 Elastic Matching and Stress Relief in the Presence of the Intermediate Monoclinic Phase	28
2.2 Phase Coexistence in $(1 - x)\text{Pb}(\text{Mg}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ Near the Morphotropic Phase Boundary	32
2.2.1 Phase Coexistence Without the Monoclinic Phase	32
2.2.2 Phase Coexistence in the Presence of the Monoclinic Phases	36
2.2.3 Effect of Non-180° Domains on Phase Coexistence	39
2.2.4 Different Scenarios of Stress Relief	44

2.3	Model of Interpenetrating Phases: Application to $(1 - x)\text{Pb}(\text{Mg}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ Near the Morphotropic Phase Boundary .....	49
2.4	Domain and Heterophase States in $(1 - x)\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ Near the Morphotropic Phase Boundary .....	53
2.4.1	Phase Transitions and Intermediate Phases .....	53
2.4.2	Crystallographic Study of Elastic Matching of Morphotropic Phases.....	55
2.4.3	Interpenetrating Phases in $0.90\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3 - 0.10\text{PbTiO}_3$ Single Crystals .....	57
	References .....	60
<b>3</b>	<b>Phase Coexistence Under Electric Field .....</b>	<b>65</b>
3.1	Heterophase $\text{Pb}(\text{Mg}_{1/3}\text{Nb}_{2/3})\text{O}_3$ at the Induced Phase Transition ...	65
3.2	Domain State: Interface Relationships at Electric Field $E \parallel [001]$ .....	68
3.2.1	Heterophase $(1 - x)\text{Pb}(\text{Mg}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ .....	68
3.2.2	Heterophase $(1 - x)\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ .....	79
3.3	Domain State: Interface Relationships at Electric Field $E \parallel [110]$ .....	83
3.4	Domain State: Interface Relationships at Electric Field $E \parallel [111]$ .....	87
3.5	Role of Intermediate Phases in Heterophase States.....	92
	References .....	93
<b>4</b>	<b>Three-Phase States .....</b>	<b>97</b>
4.1	Model of Three-Phase Single Crystal .....	97
4.2	Application of Model Concepts to $\text{PbZrO}_3$ and $\text{Pb}(\text{Zr}_{1-x}\text{Ti}_x)\text{O}_3$ ( $x \approx 0.22$ ) .....	100
4.2.1	Phase Coexistence in $\text{PbZrO}_3$ Single Crystals .....	100
4.2.2	Phase Coexistence in $\text{Pb}(\text{Zr}_{1-x}\text{Ti}_x)\text{O}_3$ Single Crystals ( $x \approx 0.22$ ) .....	101
4.3	Application of Model Concepts to $(1 - x)\text{Pb}(\text{Mg}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ .....	102
4.4	Three-Phase Coexistence and Complete Stress Relief in $(1 - x)\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$ .....	103
4.5	Thermodynamic Description of Three-Phase States in Ferroelectric Solid Solutions .....	108
4.6	Crystallographic and Thermodynamic Studies of Three-Phase States .....	114
	References .....	115

<b>5</b>	<b>Overlapping Structures and Transition Regions</b>	119
5.1	Overlapping Structures in $\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3$	119
5.2	$S_j$ : Interface Relationships in $\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3$	121
5.3	Transition Regions in $(1 - x)\text{Pb}(\text{Zn}_{1/3}\text{Nb}_{2/3})\text{O}_3 - x\text{PbTiO}_3$	124
5.4	Stress Relief at Variable Unit-Cell Parameters	128
	References	129
<b>6</b>	<b>Conclusions</b>	131
6.1	A Way from a Unit Cell to Morphotropic Polydomain/Heterophase Structures	131
	References	133
<b>A</b>	<b>Methods for Description of Heterophase and Polydomain Single Crystals</b>	135
A.1	Concepts on the Zero-Net-Strain Plane	135
A.2	Comparison of Data	141
	References	147
<b>B</b>	<b>Optimal Volume Fractions in Terms of Angles Between Spontaneous Polarization</b>	149
B.1	Optimal Volume Fractions and Polarization Rotations	149
	References	152
	<b>Index</b>	153
	<b>About the Author</b>	155

Heterogeneous Ferroelectric Solid Solutions  
Phases and Domain States

Topolov, V.Y.

2012, XIV, 158 p., Hardcover

ISBN: 978-3-642-22482-9