

Contents

Part I Basic Problems

1 Principles of Vector Orientation and Vector Orientated Control Structures for Systems Using Three-Phase AC Machines	3
1.1 Formation of the Space Vectors and Its Vector Orientated Philosophy	3
1.2 Basic Structures with Field-Orientated Control for Three-Phase AC Drives	8
1.3 Basic Structures of Grid Voltage Orientated Control for DFIM Generators	12
References	16
2 Inverter Control with Space Vector Modulation	17
2.1 Principle of Vector Modulation	17
2.2 Calculation and Output of the Switching Times	23
2.3 Restrictions of the Procedure	25
2.3.1 Actually Utilizable Vector Space	25
2.3.2 Synchronization Between Modulation and Signal Processing	27
2.3.3 Consequences of the Protection Time and Its Compensation	28
2.4 Realization Examples	30
2.4.1 Modulation with Microcontroller SAB 80C166	31
2.4.2 Modulation with Digital Signal Processor TMS 320C20/C25	35
2.4.3 Modulation with Double Processor Configuration	41

2.5	Special Modulation Procedures	45
2.5.1	Modulation with Two Legs	45
2.5.2	Synchronous Modulation	46
2.5.3	Stochastic Modulation	48
2.6	Degrees of Freedom in Modulation	53
2.6.1	Modulation with Different Combinations of Component Vectors.	54
2.6.2	Modulation with Different Sequences of Component Vectors.	55
2.6.3	Execution Time of Zero Vectors.	57
	References.	58
3	Machine Models as Prerequisite to Design the Controllers and Observers	61
3.1	General Issues of State Space Representation	61
3.1.1	Continuous State Space Representation	61
3.1.2	Discontinuous State Space Representation	63
3.2	Induction Machine with Squirrel-Cage Rotor (IM)	68
3.2.1	Continuous State Space Models of the IM in Stator-Fixed and Field-Synchronous Coordinate Systems.	69
3.2.2	Discrete State Space Models of the IM	77
3.3	Permanent Magnet Excited Synchronous Machine (PMSM)	83
3.3.1	Continuous State Space Model of the PMSM in the Field Synchronous Coordinate System	83
3.3.2	Discrete State Space Model of the PMSM	86
3.4	Doubly-Fed Induction Machine (DFIM).	88
3.4.1	Continuous State Space Model of the DFIM in the Grid Synchronous Coordinate System.	88
3.4.2	Discrete State Model of the DFIM	91
3.5	Generalized Current Process Model for the Two Machine Types IM and PMSM.	92
3.6	Nonlinear Properties of the Machine Models and the Way to Nonlinear Controllers.	95
3.6.1	Idea of the Exact Linearization Using State Coordinate Transformation.	95
3.6.2	Flatness and the Idea of the Flatness-Based Control Design.	102
	References.	112

4	Problems of Actual-Value Measurement and Vector Orientation	113
4.1	Acquisition of the Current	113
4.2	Acquisition of the Speed	116
4.3	Possibilities for Sensor-Less Acquisition of the Speed.	122
4.3.1	Example for the Speed Sensor-Less Control of an IM Drive	123
4.3.2	Example for the Speed Sensor-Less Control of a PMSM Drive.	131
4.4	Field Orientation and Its Problems	132
4.4.1	Principle and Rotor Flux Estimation for IM Drives.	133
4.4.2	Calculation of Current Set Points	138
4.4.3	Problems of the Sampling Operation of the Control System	139
	References.	144

Part II Three-Phase AC Drives with IM and PMSM

5	Dynamic Current Feedback Control for Fast Torque Impression in Drive Systems	149
5.1	Survey About Existing Current Control Methods	150
5.2	Environmental Conditions, Closed Loop Transfer Function and Control Approach	160
5.3	Design of a Current Vector Controller with Dead-Beat Behaviour	164
5.3.1	Design of a Current Vector Controller with Dead-Beat Behaviour with Instantaneous Value Measurement of the Current Actual-Values.	164
5.3.2	Design of a Current Vector Controller with Dead-Beat Behaviour for Integrating Measurement of the Current Actual-Values	169
5.3.3	Design of a Current Vector Controller with Finite Adjustment Time.	171
5.4	Design of a Current State Space Controller with Dead-Beat Behaviour	172
5.4.1	Feedback Matrix K	173
5.4.2	Pre-filter Matrix V	174

5.5	Treatment of the Limitation of Control Variables	177
5.5.1	Splitting Strategy at Voltage Limitation	180
5.5.2	Correction Strategy at Voltage Limitation	184
	References.	186
6	Equivalent Circuits and Methods to Determine the System Parameters	189
6.1	Equivalent Circuits with Constant Parameters	189
6.1.1	Equivalent Circuits of the IM	189
6.1.2	Equivalent Circuits of the PMSM	194
6.2	Modelling of the Nonlinearities of the IM	194
6.2.1	Iron Losses	195
6.2.2	Current and Field Displacement	197
6.2.3	Magnetic Saturation	201
6.2.4	Transient Parameters	206
6.3	Parameter Estimation from Name Plate Data	207
6.3.1	Calculation for IM with Power Factor $\cos\phi$	208
6.3.2	Calculation for IM Without Power Factor $\cos\phi$	211
6.3.3	Parameter Estimation from Name Plate of PMSM	212
6.4	Automatic Parameter Estimation for IM in Standstill	213
6.4.1	Pre-considerations	213
6.4.2	Current-Voltage Characteristics of the Inverter, Stator Resistance and Transient Leakage Inductance	215
6.4.3	Identification of Inductances and Rotor Resistance with Frequency Response Methods	217
6.4.4	Identification of the Stator Inductance with Direct Current Excitation	223
	References.	224
7	On-Line Adaptation of the Rotor Time Constant for IM Drives	227
7.1	Motivation	227
7.2	Classification of Adaptation Methods	232
7.3	Adaptation of the Rotor Resistance with Model Methods	236
7.3.1	Observer Approach and System Dynamics	236
7.3.2	Fault Models	240
7.3.3	Parameter Sensitivity	245
7.3.4	Influence of the Iron Losses	249
7.3.5	Adaptation in the Stationary and Dynamic Operation.	250
	References.	254

8	Optimal Control of State Variables and Set Points for IM Drives	257
8.1	Objective	257
8.2	Efficiency Optimized Control	258
8.3	Stationary Torque Optimal Set Point Generation	261
8.3.1	Basic Speed Range	261
8.3.2	Upper Field Weakening Area	265
8.3.3	Lower Field Weakening Area	268
8.3.4	Common Quasi-stationary Control Strategy	271
8.3.5	Torque Dynamics at Voltage Limitation	273
8.4	Comparison of the Optimization Strategies	277
8.5	Rotor Flux Feedback Control	280
	References	282
9	Nonlinear Control Structures for Three-Phase AC Drive Systems	283
9.1	Existing Problems at Linear Controlled Drive Systems	283
9.2	Nonlinear Control Structures for Drive Systems with IM	284
9.2.1	Nonlinear Control Based on Exact Linearization of IM	284
9.2.2	Nonlinear Control Based on Flatness of IM	289
9.3	Nonlinear Control Structure for Drive Systems with PMSM	298
9.3.1	Nonlinear Control Based on Exact Linearization of PMSM	298
9.3.2	Nonlinear Control Based on Flatness of PMSM	303
	References	309

Part III Wind Power Plants with DFIM

10	Linear Control Structure for Wind Power Plants with DFIM	313
10.1	Construction of Wind Power Plants with DFIM	313
10.2	Grid Voltage Orientated Controlled Systems	315
10.2.1	Control Variables for Active and Reactive Power	316
10.2.2	Dynamic Rotor Current Control for Decoupling of Active and Reactive Power	317
10.2.3	Problems of the Implementation	319
10.3	Front-End Converter Current Control	321
10.3.1	Process Model	322
10.3.2	Controller Design	324
	References	326

11 Nonlinear Control Structure for Wind Power Plants with DFIM	327
11.1 Existing Problems with Linear Controlled Wind Power Plants	327
11.2 Nonlinear Control Based on Exact Linearization of DFIM	328
11.2.1 Controller Design	328
11.2.2 Control Structure with Direct Decoupling for DFIM.	331
11.3 Nonlinear Control Based on Flatness of DFIM	335
11.3.1 Controller Design	335
11.3.2 Flatness-Based Control Structure for DFIM	338
References.	342
Appendix	345
Index	361

<http://www.springer.com/978-3-662-46914-9>

Vector Control of Three-Phase AC Machines

System Development in the Practice

Quang, N.P.; Dittrich, J.-A.

2015, XIX, 364 p. 194 illus., 193 illus. in color.,

Hardcover

ISBN: 978-3-662-46914-9