

Contents

Part I What Caused the Core Melt and Hydrogen Explosion?

1 Three Mile Island Nuclear Power Station Accident.....	3
1.1 Shape of the Molten Core.....	3
1.2 TMI Reactor's Performance During the Accident.....	8
1.3 Fuel Behavior Test Simulating Power Cooling Mismatch Accident (PCM-1) at Power Burst Facility (PBF).....	12
1.4 Zircaloy Oxidation and Fuel Rod Behavior	17
1.5 Core Melt Process of TMI Accident.....	22
1.6 Settlement of TMI Accident	25
1.7 Conclusion from TMI Accident.....	27
1.8 Influences and Excursuses of the TMI Accident	28
Appendices.....	31
Appendix 1.1	31
Appendix 1.2	32
References.....	33
 2 Fukushima Daiichi Unit 1, 2 and 3 Accidents.....	35
2.1 Outline of Fukushima Daiichi Nuclear Power Station	35
2.2 Initiation of the Accidents – Earthquake and Tsunami.....	39
2.3 Outline of the Accident.....	41
2.4 Case of Unit 1	45
2.4.1 Isolation Condenser (IC) Problem	45
2.4.2 Fuel Temperature Rise	48
2.5 Case of Unit 2.....	51
2.5.1 Reactor Core Isolation Cooling System (RCIC).....	51
2.5.2 Sea Water Injection and Core Melt	56
2.5.3 Hydrogen Gas Generation and Radioactive Release	61
2.5.4 Section Conclusion	65

2.6	Case of Unit 3	69
2.6.1	Operating Period of RCIC and HPCI (① 4 p.m. on March 11–2:42 a.m. on March 13)	73
2.6.2	Core Temperature Rise After HPCI Stoppage (② 2:42 a.m. on March 13–9:08 a.m. on March 13)	76
2.6.3	Start of Core Collapse (③ 9:08 a.m. – 0:20 p.m.)	79
2.6.4	Sea Water Injection and Core Melt (④ Approximately 22 h from 0:20 p.m. on March 13 Through 11 a.m. on March 14).....	81
2.6.5	Explosion of Reactor Building (⑤ 11:01 a.m. on March 14).....	84
2.6.6	Section Conclusion	89
2.7	Back to the Case of Unit 1	91
2.7.1	Radiation Heat in Reactor Pressure Vessel	91
2.7.2	Core Melt and Meltdown	97
2.7.3	Reverse Study from Hydrogen Explosion	98
2.7.4	Drop of Partially Molten Core and Its Internals	101
2.7.5	Sea Water Injection and Explosion	104
2.7.6	Section Conclusion	106
2.8	Conclusion from Studies of Units 1–3	109
	Appendices.....	114
	Appendix 2.1	114
	Appendix 2.2	115
	Appendix 2.3	115
	Appendix 2.4	116
	Appendix 2.5	116
	Appendix 2.6	117
	Appendix 2.7	117
	Appendix 2.8	119
	Appendix 2.9	120
	Appendix 2.10	120
	Appendix 2.11	121
	Reference	122
3	Fukushima Daiichi Unit 4 Accident.....	123
3.1	Explosion of Reactor Building	125
3.2	Global Influence of the Explosion	129
 Part II Improving Nuclear Safety and Reconstructing Fukushima		
4	Release of Radioactive Materials and the Evacuation of Residents.....	135
4.1	Background Radiation Level Increased by the Release of Radioactive Materials	135
4.1.1	First Increases in the Background Radiation Level – Amount of Radiation Released from Units 1 and 3	136

4.1.2	Background Radiation Level Increase for the Second Time – Amount of Radioactive Materials Released from Unit 2	139
4.2	Emergency Evacuation	142
4.2.1	Dose Band for Evacuation Recommended by the ICRP	145
4.2.2	Lives of Evacuees	146
4.3	Release of Radioactive Materials and Contamination.....	147
4.3.1	Radioactive Materials Released from the Chernobyl Accident.....	148
4.3.2	Release of Radioactive Materials from the Fukushima Accident.....	152
	Appendices.....	156
	Appendix 4.1	156
	Appendix 4.2	157
	References.....	157
5	Tsunami and Station Blackout	159
5.1	Seawall (Tide Embankment)	160
5.2	Station Blackout	162
5.3	Layout of Equipment and B5b Issue	168
5.4	Reliability and Diversity of Equipment.....	171
5.5	Natural Disasters and Safety Design	172
6	Reconstruction of Safety.....	175
6.1	Conventional Nuclear Safety.....	175
6.2	Safety Design and Natural Disasters	177
6.3	Mitigation Safety Systems Against Disasters (MISSAD)	180
6.4	Safety of Nuclear Power Plant.....	182
6.5	Antiterrorism Measures	186
6.5.1	What Is Nuclear Terrorism?.....	186
6.5.2	Measures Against Terrorism by Land and Sea Based on the Design Basis Threat (DBT)	188
6.5.3	Terrorism Using Aircraft.....	190
7	Road to Decommissioning.....	195
7.1	The Current Situations of Reactors That Suffered Core Melt	196
7.2	Decommissioning in the Earliest Days and Today	198
7.3	Advice to Fukushima.....	201
8	Outcome of the Study	205
9	New Insights Obtained from the Accident – To Commemorate the Publication of the English Edition	209
9.1	Insights and Lessons Learned from the World-First Experiences	209
9.1.1	Nuclear Power Plants That Withstood a Massive Earthquake of Magnitude 9.....	210

9.1.2	Safety Design to Mitigate Natural Disasters Learned from Tsunami Damage	210
9.1.3	Countermeasures for Station Blackout	211
9.1.4	Reactor Water Level and Core Melt.....	211
9.1.5	Water Injection from Fire Engines.....	212
9.1.6	SC Vent.....	213
9.1.7	Slow Cooling with Reactor Core Depressurization	213
9.2	What Could Have Been Done to Prevent the Accident?	214
9.3	Improvements to Be Considered	215
9.3.1	Enhancement of SC Vent Performance	215
9.3.2	Containment Vessels	215
9.3.3	Reactor Buildings.....	216
9.3.4	Study of Cooling by Radiation Heat.....	216
9.4	Toward More Robust Safety Systems.....	217
	Reference	218
10	At the End of This Study	219
10.1	Careful Studies Required to Clarify What Actually Happened	219
10.2	The Government's Failure to Support	221
10.3	More Information Required from TEPCO for More Accurate Analyses	222
10.4	The Need to Provide Precise Information to the World.....	223
10.5	Fukushima Reconstruction with Cool-Headed Judgments.....	224
	References.....	225
	Postscript.....	227
	About the Author.....	231

A Study of the Fukushima Daiichi Nuclear Accident
Process

What caused the core melt and hydrogen explosion?

Ishikawa, M.

2015, XVI, 231 p. 39 illus., 36 illus. in color., Softcover

ISBN: 978-4-431-55542-1