
Contents

1	Introduction.	1
2	Requirements for Spacecraft Materials	7
2.1	General Background	7
2.2	Considerations for Materials and Processes	10
2.2.1	General Considerations During the Selection of Materials and Processes	10
2.2.2	Some Futuristic Ideas	11
2.2.3	Some Basic Considerations Regarding Corrosion Prevention	17
2.2.4	Space Project's Phases and Management Events	20
2.3	The Effect of a Space Environment	22
2.4	Materials for Space Launch Vehicles	28
2.5	Non-metallic Materials	38
2.5.1	General	38
2.5.2	Classes of Non-metallic Materials	42
2.5.3	Novel Non-metallics	43
2.6	The Potential for Welding and Joining in a Space Environment	49
2.6.1	Background Considerations	49
2.6.2	Potential Joining and Cutting Processes	50
2.6.3	Expectations	53
3	The Integration of 'Materials' into Product Assurance Schemes	55
3.1	General Product Assurance and the Role of Materials	55
3.1.1	Product Assurance Management	55
3.1.2	Quality Assurance	55
3.1.3	Reliability and Safety	57
3.1.4	Materials and Processes	59
3.1.5	Component Part Selection, and Procurement	61
3.1.6	Control of Ground-Handling Facilities	63
3.2	The Materials Laboratory	66
3.2.1	Major Objectives of Laboratory	66
3.2.2	Facilities and Instrumentation	67
3.2.3	The Use of New Laboratory Techniques for NDT	85
3.2.4	Organic Chemistry and Environmental Test Laboratories	98
3.3	Preparation of Materials and Metallographic Evidence	100
3.3.1	The Metallographer	100
3.3.2	Laboratory Records and Reports	101
3.3.3	Report of Materials Data to Spacecraft Projects	101
3.3.4	Training of Materials Engineers and Laboratory Staff	103
3.3.5	Ethical Issues	104

3.4	The Future for Materials Failure Investigations.	104
3.4.1	The Larger Company	104
3.4.2	The Smaller Company.	105
3.4.3	Product Liability.	105
3.5	'Greener' Spacecraft.	105
3.6	The Potential for Recycling Electronic Waste.	111
3.6.1	General	111
3.6.2	Elemental Distribution for Spacecraft Electronic Box	111
4	Spacecraft Manufacturing—Failure Prevention and the Application of Material Analysis and Metallography	115
4.1	Sources of Failure	115
4.2	Drawings and Workmanship	115
4.2.1	Design and Manufacturing Drawings.	115
4.2.2	Workmanship Standards	116
4.3	Mechanical Damage Revealed by Microstructure	122
4.4	Hydrogen Embrittlement	122
4.4.1	Interaction of Metal with Hydrogen	122
4.4.2	Hydrogen Embrittlement of Spring Steel	123
4.4.3	Blistering of Plated Aluminium Alloy	124
4.4.4	Examination for Titanium Hydride Precipitates.	125
4.4.5	Embrittlement of Copper	127
4.4.6	Future Developments	128
4.5	General Corrosion Problems	128
4.5.1	Bimetallic Corrosion-Related Failures	128
4.5.2	Corrosion Resistance of Anodic and Chemical Conversion Coatings on Al 2219 Alloy	132
4.5.3	Evaluation of Alodine Finishes on Common Spacecraft Aluminium Alloys	134
4.5.4	Cleaning, Passivation, and Plating of Spacecraft Steels	137
4.5.5	Launch Site Exposure and Corrosion.	138
4.6	Stress-Corrosion Resistance of Metals.	139
4.6.1	Stress-Corrosion Cracking	139
4.6.2	SCC Evaluation	140
4.6.3	The Properties of Spring Materials	144
4.6.4	Bearing Materials	148
4.7	Control of Printed Circuit Boards.	148
4.7.1	Chemical Composition of Tin-Lead from Microstructure	148
4.7.2	Grainy Solder Coverage on PCBs and the Effects of Rework.	150
4.7.3	Evaluation of Multilayer Board Internal Connections.	155
4.7.4	Flexible Circuits.	159
4.7.5	Hot-Air-Levelled Circuit Boards.	160
4.7.6	Solder Assembly of Component Packages onto Multilayer Boards with High Heat Capacity	161
4.8	Control of Composite Materials	161
4.8.1	Metal–Matrix Composites for Space Structures.	161
4.8.2	Composite Contact Devices	164
4.8.3	Fibre-Reinforced Plastic Composites	166
4.8.4	Fibre-Reinforced Glass Ceramics	170
4.8.5	Carbon–Carbon Composites.	170
4.8.6	Metal Matrix Composites for Spacecraft Pressure Vessels	172

4.9	Control of Capillary Screens	172
4.10	Examination of Electroless Nickel Deposits	173
4.10.1	Microcracked Electroless Nickel	173
4.10.2	Electroless Nickel Plating of Aluminium Electronic Housings	175
4.11	Control of Electroforming Processes	176
4.12	Dip Brazing of Aluminium Alloys	179
4.13	Considerations for the Assembly of Subsystems by Welding	181
4.13.1	General Welding Methods and Controls	181
4.13.2	Electron Beam Welding	184
4.13.3	Laser Beam Welding	185
4.13.4	Explosive Welding	186
4.13.5	Welding of Aluminium–Lithium Alloys	187
4.13.6	Welding of Thermoplastics for Space Applications	188
4.14	Control of Power System Weldments	189
4.14.1	General	189
4.14.2	Welded Solar Arrays	189
4.14.3	Suitability of Welded Battery Cells	193
4.15	Problems Associated with Residual Stresses in Weldments	195
4.16	Electromagnetic Emission from TIG Welding Equipment	195
4.17	Titanium Aluminides for High-Temperature Applications	196
4.18	Shape-Memory Alloys for Spacecraft Devices	197
4.19	Foamed Aluminium for Damping Purposes	202
4.20	Superplastic Forming and Diffusion Bonding of Metals	203
4.20.1	Forming of Propellant Tanks	203
4.20.2	Diffusion Bonding	206
4.20.3	Superplastic Forming and Diffusion Bonding in One Operation	206
4.21	Cleaning of Mechanical Parts	207
4.21.1	General Background	207
4.21.2	Metallic Surfaces	209
4.21.3	Cleaning of Individual Parts	210
4.21.4	Cleaning of Metallurgically Joined Assemblies	213
4.21.5	Maintenance of Cleanliness	216
4.21.6	Cleaning of Silicone Contamination	219
4.22	Novel Thermal Management Materials	220
4.23	Cold Sprayed Coatings	223
4.24	Advanced Plasma Electrolytic Oxidation Treatment for Aluminium, Magnesium and Titanium Alloys	224
4.24.1	General Process	224
4.24.2	Characteristics of PEO Coatings	225
4.24.3	Applications	229
4.25	Joining by “Friction Stir”	231
4.25.1	Friction Stir Welding	231
4.25.2	Friction Stud Welding	234
4.26	Selective Brush Electroplating	234
4.27	Control of Coatings and Bonded Items by Tape Testing	237
4.28	The Application of EB Welding Machine for Reflow Brazing	239

5	Metallography Applied to Spacecraft Test Failures	247
5.1	Application of Electron Microscope	247
5.1.1	SEM Examination of Fracture Surfaces	247
5.1.2	TEM Examination of Metallic Failures	250
5.2	Fasteners	251
5.2.1	Spacecraft Fasteners	251
5.2.2	Fastener Failure Due to Forging Defect	254
5.2.3	Laps and Surface Irregularities in Threads	255
5.2.4	Hydrogen Embrittlement of Steel Fasteners	255
5.2.5	Embrittlement of Titanium Alloys	255
5.2.6	Galvanic Corrosion of Fasteners	257
5.2.7	Contamination and Organic Fastener Lubrication Systems	257
5.2.8	Metallic Particle Generation	258
5.2.9	Quality Assurance Controls for Fasteners	261
5.3	Thermal History from Microstructure	262
5.4	Effect of Inclusions Within the Microstructure of Explosively Deformed Material	264
5.5	Degradation of Passive Thermal Control Systems	266
5.5.1	General Background	266
5.5.2	Low-Emissivity Surfaces	268
5.5.3	High-Absorption Surfaces	269
5.5.4	Rigid Optical Solar Reflectors	270
5.5.5	Flexible Second Surface Mirrors	271
5.6	Sublimation of Metals	272
5.6.1	General	272
5.6.2	Sublimation of and Condensation of Cadmium and Zinc	274
5.6.3	Heater Sublimation Problem Associated with Thruster Motor	276
5.6.4	Sublimation of Klystron Cathode-Heaters	276
5.6.5	Sublimation of Rhenium	278
5.7	Beryllium for Spacecraft Applications	280
5.7.1	General	280
5.7.2	Health and Safety	281
5.7.3	Integrity of Machined Beryllium	283
5.7.4	Thermal Cycling on Work-Hardened Beryllium	284
5.7.5	General Etching Solutions for Beryllium	285
5.7.6	Investigation of Microcracked Thin-Foil Detector Windows	286
5.7.7	Aluminium-Beryllium Alloys	288
5.8	Deactivation of Catalyst Particles for Hydrazine Decomposition	288
5.8.1	Testing Procedure	288
5.8.2	Material Investigation	288
5.8.3	Mechanism of Particle Deactivation	290
5.9	Cathode Emitter Degradation	291
5.10	Investigation of a Failed Spacecraft Antenna	293
5.11	The Wear of Ball Bearings	296
5.12	Cold Welding of Mechanisms	304
5.12.1	General	304
5.12.2	Cold Welding Due to Cyclic, Impact Loading	306
5.12.3	Cold-Welding Due to Fretting	307
5.13	Defective Black-Anodized Electrical Connector	308
5.14	Contaminant Particles—Identification of Their Sources	309

5.15	Silicone Contamination	310
5.15.1	General	310
5.15.2	Contamination of Black-Anodized Finish.	311
5.15.3	Contamination of Invar Moulding Tool	312
5.15.4	Removal of Silicone Polymers	314
5.15.5	Contamination of Aluminium Tubes for Vacuum Pinch-Offs . . .	317
5.16	Magnetic Problems	317
5.17	Thermal Stress-Induced Dimensional Changes	319
5.17.1	General Problems	319
5.17.2	Stress-Relaxation by Thermal Gradients.	319
5.17.3	Thermally Induced Vibrations	321
5.18	Defects in Titanium Piece-Parts	323
5.18.1	General	323
5.18.2	Alpha-Case Embrittlement	323
5.18.3	Titanium Hydride Embrittlement.	324
5.19	Leaking Water Tank on Launcher.	325
5.20	Compatibility of Liquid and Solid Propellants with Components and Subsystems	326
6	Failure Analysis of Electrical Interconnections and Recommended Processes	329
6.1	Material Problems	329
6.2	Welded Lead Wire Interconnections	329
6.3	'Purple Plague'	332
6.4	Mechanical Electrical Connections	337
6.4.1	General	337
6.4.2	Wire-Wrapped Connections	337
6.4.3	Crimped Joints	339
6.5	Soldered Interconnections	340
6.5.1	Introduction to Soldering	340
6.5.2	Inspection of Soldered Joints	341
6.5.3	The Effect of Thermal Fatigue on Solder-Assembled Leaded Components	344
6.5.4	Effect of Thermal Fatigue on Leadless Components	351
6.5.5	The Effect of Thermal Fatigue on Semi-rigid Cable Connections	353
6.6	Problems Associated with Coatings for Soldering Applications	357
6.6.1	The Need for Coatings	357
6.6.2	Surfaces that Can Be 'Soldered To'	357
6.6.3	Surfaces that Can Be 'Soldered Through'	359
6.7	The Use of Indium Solder Alloys.	363
6.8	Wires and Cables	369
6.8.1	Selection of Plated Finish on Copper Conductors	369
6.8.2	Effect of Ageing on the Solderability of Tin-Plated and Silver-Plated Wires	371
6.8.3	'Red Plague' Corrosion of Silver-Plated Copper, and Plagues on Other Plated Stranded Wires	375
6.8.4	Manganin Wire	379
6.8.5	High-Voltage Wires, Cables, and Connections	380
6.8.6	Cold Welding of Stranded Wires and Cables	380

6.9	Problems Associated with Soldering Fluxes	380
6.9.1	Purpose of a Flux	380
6.9.2	Heat-Shrinkable Sleeves Containing Solder Preforms	381
6.9.3	Stress Corrosion of Component Lead Material	383
6.9.4	Flux-Corrosion of Silver-Plated Stranded Wires	383
6.9.5	Selection of a Soldering Flux or a Solderable Finish	386
6.9.6	Control of Galvanic Corrosion	389
6.9.7	Cleaning of Flux-Contaminated Surfaces	389
6.9.8	Flux Residues, Their Ingress into Top-Coat of PCB Surfaces, and Bake Out After Cleaning	391
6.9.9	Conductive Anodic Filament (CAF) Formation and Particulate Contamination	394
6.9.10	Potential Health Hazards in the Electronic Assembly Area	398
6.10	Problems Associated with Brazing	399
6.10.1	Design Considerations	399
6.10.2	Brazeability of Materials and Braze Alloy Compositions	400
6.10.3	Brazing Fluxes and Their Removal	403
6.10.4	Atmospheres for Brazing	404
6.10.5	Safety Precautions	405
6.10.6	Produce Assurance Applied to Brazing Operations	405
6.10.7	Inspection Criteria for Brazed Aluminium Alloy Waveguide-to-Flange Joints	406
6.11	Diffusion Soldering/Brazing	408
6.12	Effects of Rework and Repair on Soldered Interconnections	408
6.12.1	General	408
6.12.2	Cosmetics of Solder Fillets	410
6.12.3	Effect of Rework Electronic Components	410
6.12.4	Effect of Rework on Plated-Through Holes	410
6.12.5	Effect of Rework on Composition of Joint	412
6.12.6	Recuperation of Unsolderable PCBs and Component Leads	413
6.13	Electrical Conductive Adhesives	413
6.14	Training and Certification	415
6.14.1	General	415
6.14.2	Certification for Electronic Assembly Techniques	417
6.14.3	Understanding Process-Induced Failures and the Importance of Workshops	418
6.15	Verification of Surface-Mount Technology and Prevalent Failure Mechanisms	419
6.15.1	Verification Testing	419
6.15.2	Failure Under Mechanical Overloading	422
6.15.3	Failures Due to Board Flatness Problems	422
6.15.4	Failure Due to Co-planarity Problems	423
6.15.5	Solder Joint Failure Due to Thermal Mismatch Between SMD and Substrate	425
6.15.6	Conductor Track Failure Due to Thermal Mismatch	428
6.15.7	Failure of RF Cables Connected by SMT	428
6.15.8	SMT Solder Joint Failure Due to Conformal Coatings	428
6.15.9	SMT Problems Related to Flux and White Residues	432
6.15.10	Area Grid Array (AGA) Packaging	434

6.15.11	High Voltage Interconnections and Influence of Geometry (Workmanship) on Corona Discharge	442
6.15.12	Tin Pest.	448
6.15.13	Mechanical and Electrical Properties of Electronic Materials at Temperatures Down to 4.2 K	451
7	Whisker Growths	461
7.1	The Problem of Whisker Growth	461
7.2	Analysis of Failures Due to Whisker Growth	462
7.2.1	Molybdenum Whiskers on Metallized Miniature Circuits	462
7.2.2	Tungsten Whisker Growth Within Travelling Wave Tubes	466
7.2.3	Metal Oxide Whisker Precipitation in Glass Seals	466
7.2.4	Integrated Circuit Failure Modes Due to Electromigration—Aluminium Whisker Growth and Solder Joint Voiding	468
7.3	Tin Whisker Growths	472
7.3.1	Tin Whisker Growth on a Plated Steel Housing	472
7.3.2	Tin Whisker Growth on PCB and Other Electronic Materials During Thermal Cycling	474
7.3.3	Tin Whisker Growth on Crimp Termination Devices	479
7.3.4	The Nucleation, Growth and Mechanism of Growth of Tin Whiskers—Results from a C-Ring Test Programme	481
7.3.5	Some Properties of Tin Whiskers	485
7.4	Precautions to Avoid General Whisker Growths	491
7.5	The Creation of Lead-Free Control Plans	494
7.5.1	General	494
7.5.2	Methods for Reprocessing Pure Tin Terminations	495
7.5.3	Mitigation Approaches	498
8	Assessment of Post-flight Materials	501
8.1	General	501
8.1.1	Hardware Return from Space	501
8.1.2	Raw Materials from the Moon	501
8.1.3	Recent Investigations Using Retrieved Materials	503
8.2	Space Environmental Effects from Vacuum and Radiation	503
8.2.1	Organic Materials and Lubricants	503
8.2.2	Radiation Effects	507
8.2.3	Effects of Vacuum on Metals	508
8.3	Temperature Cycling	509
8.4	Micrometeoroids and Debris	509
8.4.1	General	509
8.4.2	Debris Emanating from Catalytic Bed Thruster Motors	512
8.4.3	Returned Hardware	514
8.4.4	Protection Shields	515
8.5	Effect of Atomic Oxygen on Materials	517
8.6	Decelerators and Heat Shield Materials	524
8.6.1	General Examples	524
8.6.2	Beryllium as a Heat Shield	528
8.6.3	Alternative Heat Shield Materials	531
8.6.4	High-Temperature Fasteners	533

8.7	Manned Compartments	535
8.7.1	General Conditions	535
8.7.2	Solder Assembly Defects	538
8.7.3	Inspection of Spacelab Post-flight Hardware.	542
Appendix 1: Coefficient of (Linear) Thermal Expansion for Selected Materials (COE or CTE)		557
Appendix 2: Properties of Printed Circuit Laminates		559
Appendix 3: Reagents for Microetching Metals and Alloys		561
Appendix 4: Conversion Table for Mechanical Properties		565
Appendix 5: Aluminium Alloy Temper Designations		567
Appendix 6: Metal Alloy Comparison Tables		571
Appendix 7: Variation of Standard Free Energy of Formation of Oxides with Temperature		613
Appendix 8: Simplified Procedure for the Management of Materials, Processes and Mechanical Parts—Possible Guidelines for a Cubesat or Small University Spacecraft		615
Appendix 9: Materials and Processes Standards Related to Space (Released by ECSS, JAXA and NASA) as of 2015		619
Appendix 10: Examples of Declared Process Lists (DPL).		621
Appendix 11: Examples of Declared Materials Lists (DMLs)		625
Glossary		629
References.		639
Index		655

Materials and Processes
for Spacecraft and High Reliability Applications

Dunn, B.

2016, XX, 667 p. 490 illus., 295 illus. in color.,

Hardcover

ISBN: 978-3-319-23361-1