

Contents

1	Introduction and Overview	1
1.1	Introduction	2
1.2	The Continuous Casting Process for Steel	2
1.3	The Introduction of Casting Powders	4
1.4	Mould Powder Behaviour in the Mould	6
1.5	Slag Film and Slag Rim Characteristics	7
1.5.1	Slag Film	7
1.5.2	Slag Rim	9
1.6	Casting Conditions	10
1.6.1	Casting Speed (V_c)	10
1.6.2	Metal Flow	11
1.6.3	Mould Dimensions	12
1.6.4	Oscillation Characteristics	12
1.6.5	Steel Grade	12
1.6.6	Ar Flow Rate	13
1.7	Physical Properties of Mould Slags	13
1.8	Fluctuations in the Process	14
1.9	Definitions	14
1.9.1	Powders, Slags, Fluxes	14
1.9.2	Powder Consumption Terms	14
1.9.3	Temperature	15
1.9.4	Viscosity	16
	References	16
2	Slag Infiltration, Lubrication and Frictional Forces	19
2.1	Introduction	20
2.2	Powder Consumption (Q)	21
2.2.1	Various Powder Consumption Terms	22
2.2.2	Measurement of Powder Consumption	23
2.2.3	Methods Used to Understand Slag Infiltration Mechanisms	23

2.2.4	Problems Arising from Poor Powder Consumption.	30
2.2.5	Optimum Casting Conditions	30
2.2.6	Factors Affecting Powder Consumption	32
2.3	Slag Infiltration During the Oscillation Cycle.	41
2.4	Empirical Equations for Calculating Powder Consumption . . .	44
2.4.1	Frictional Forces	45
2.4.2	Factors Affecting Frictional Forces in the Mould . . .	48
2.5	Summary	54
	References	55
3	Heat Transfer in the Mould and Shell Solidification	59
3.1	Introduction	60
3.1.1	Heat Flux	62
3.2	Horizontal Heat Flux	62
3.2.1	Heat Transfer Mechanisms Involved in Horizontal Heat Transfer.	63
3.2.2	Interfacial Thermal Resistance ($R_{Cu/Sl}$)	65
3.2.3	Factors Affecting the Horizontal Heat Flux.	71
3.2.4	Measurement and Calculation of Heat Fluxes.	80
3.3	Shell Solidification and Growth	85
3.4	Variability in Heat Flux	87
3.4.1	Variations in Heat Flux (q_{Hor}) During the Oscillation Cycle.	88
3.4.2	Thermal Gradient Variations Arising from Metal Flow and Other Causes.	88
3.4.3	Mould Level Variations	91
3.4.4	Carbon Content of Steel	92
3.4.5	Thermal Gradients in the Mould.	94
3.4.6	Fracture of Slag Films.	95
3.5	Vertical Heat Flux	96
3.5.1	Heat Transfer Mechanisms Involved in Vertical Heat Transfer	96
3.5.2	Factors Affecting Vertical Heat Transfer.	97
3.6	Summary	102
	References	103
4	How to Manipulate Slag Behaviour in the Mould	109
4.1	Introduction	110
4.2	Vertical Heat Flux and Thermal Insulation of Bed.	111
4.2.1	Vertical Heat Flux.	111
4.2.2	Thermal Insulation of the Bed	114
4.2.3	Measurements of Thermal Insulation of Powders . . .	116
4.2.4	Ways of Improving the Thermal Insulation of the Bed.	116

4.3	Melting Rate of the Powder (Q_{MR})	116
4.3.1	The Effect of Mould Powder Properties on Melting Rate	118
4.3.2	The Effect of Casting Conditions on Melting Rate	119
4.3.3	Ways of Increasing Melting Rate	119
4.4	Depth of Molten Slag Pool	120
4.4.1	Molten Slag Pool	120
4.4.2	Importance of Depth of Molten Slag Pool	122
4.4.3	Factors Affecting Slag Pool Depth	122
4.4.4	The Effect of Casting Speed and Oscillation Characteristics	124
4.4.5	The Effect of Thermal Insulation of Bed on Pool Depth	125
4.4.6	Ways of Increasing the Melting Rate	125
4.5	Powder Consumption (Q) and Liquid Film Thickness (d_l)	125
4.5.1	Reasons for Controlling Powder Consumption	126
4.5.2	Factors Affecting Powder Consumption	127
4.5.3	Ways of Controlling the Powder Consumption	131
4.6	Solid Slag Film and Horizontal Heat Flux	131
4.6.1	Reasons for Control of Slag Film Thickness and Horizontal Heat Flux	132
4.6.2	Factors Affecting of Slag Film Thickness and Horizontal Heat Flux	132
4.6.3	Measurement of Horizontal Heat Flux	135
4.7	Crystallinity in Slag Film	135
4.7.1	Importance of Crystallinity to the Casting Process	136
4.7.2	Factors Affecting f_{crys}	137
4.7.3	Ways of Increasing Crystallinity in Slag Film	139
4.8	Delaying Solidification and Shortening the Length of Shell	139
4.8.1	Factors Affecting Shell Length	140
4.8.2	Ways of Controlling the Length of Meniscus/ Shell	140
4.9	Summary	142
	References	142
5	Effect of Casting Variables on Mould Flux Performance	147
5.1	Introduction	148
5.2	Mould Characteristics	148
5.2.1	Mould Dimensions	148
5.2.2	Mould Length (L_{mould})	150
5.2.3	Mould Taper (L_{mould})	150
5.2.4	Mould Coatings	150

5.3	Casting Speed (V_c)	150
5.3.1	Effect of Casting Speed on Powder Consumption . . .	151
5.3.2	Effect of Casting Speed on Heat Transfer	151
5.3.3	Effect of Casting Speed on Metal Flow Turbulence	152
5.3.4	Effect of Casting Speed on Negative Strip Time . . .	152
5.4	Oscillation Characteristics	153
5.4.1	Effect of Oscillation Characteristics on Powder Consumption	154
5.4.2	Effect of Oscillation Characteristics on Heat Flux . . .	155
5.4.3	Effect of Oscillation Characteristics on Oscillation Mark Depth (D_{OM})	156
5.5	Mould-Level Control	156
5.6	Metal Flow	158
5.7	Fluctuations in Processes	160
5.8	Application of Electromagnetic Devices	162
5.8.1	Electromagnetic Stirring (EMS)	162
5.8.2	Level Magnetic Field (LMF)	163
5.8.3	Electromagnetic Casting (EMC)	164
5.8.4	Electromagnetic Braking (EMBr)	165
5.9	Steel Grade	166
5.9.1	Peritectic Steels	166
5.9.2	High-Al Steels	170
5.10	Water Flow Rate	171
5.11	Argon Flow Rate	172
	References	172
6	Different Types of Mould Powders	177
6.1	Introduction	178
6.1.1	Functions Carried Out by Mould Powder	179
6.1.2	Criteria Affecting Selection of Mould Powders	180
6.2	Selection of Mould Fluxes	186
6.2.1	Conventional Mould Powders	187
6.2.2	Pre-melted Fluxes	194
6.2.3	Starter Powders	195
6.2.4	Exothermic Fluxes	196
6.2.5	Fluoride-Free Powders	198
6.2.6	Reduced F-Powders	205
6.2.7	C-Free Powders	205
6.2.8	Powders for High-Speed Casting and Thin Slab Casting	206
6.2.9	Powders for Casting Round Billets	208
6.2.10	Powders for Casting Beam Blanks	208
6.2.11	Non-Newtonian Powders	209

6.2.12	Powders for Casting TRIP and TWIP Steels	210
6.2.13	Powders for Casting Stainless Steels	217
6.2.14	Powders for Casting Steels with Rare Earths	218
6.3	Summary	218
	References	219
7	Fluxes for Ingot Casting	223
7.1	The Ingot Casting Process	224
7.1.1	Classification of Ingot Cast Steels	225
7.1.2	Ingot Casting of Killed Steels	228
7.2	Aspects of Importance for Ingot Casting Quality	231
7.2.1	Surface Quality	231
7.2.2	Inner Quality	240
7.2.3	Macro Segregation (Hot Top Insulation)	242
7.3	History of the Development of Mould Powders for Ingot Casting (and CC)	245
7.3.1	Development of Mould Powders for Continuous Casting	250
7.3.2	Development of Synthetic Mould Powders	251
7.3.3	Development of Granulated Powders	252
7.3.4	Today's Situation Regarding Mould Powders for Ingot Casting	253
7.4	Selection of Mould Powders for Ingot Casting	253
7.4.1	Important Properties of the Mould Powder	253
7.4.2	Important Properties of the Mould Powder Slag	255
7.4.3	Selection of Mould Powders in Regard to Steel Grade	258
7.5	Application Techniques for Mould Powders	262
7.6	Use of Mould Powders to Minimise Defects and Process Problems	266
7.6.1	Laps and Ripple Marks	266
7.6.2	Entrapped Oxides	266
7.6.3	Slag Patches	267
7.6.4	Porosity	267
7.6.5	Cracks	268
7.6.6	Bottom-End Defects	268
	References	268
8	Manufacture of Mould Fluxes	271
8.1	Introduction	271
8.2	Raw Materials	272
8.2.1	Selection of Carbon Additions to Mould Powders	274
8.2.2	Reactions During Melting and Cooling of Mould Powders	275

8.3	Manufacturing	276
8.4	Quality Control at the Manufacturer.	280
8.5	Information Provided by the Manufacturer.	280
8.6	Delivery Control by the Steel Makers	282
	References	283
9	Properties of Mould Fluxes and Slag Films	285
9.1	Introduction	287
9.2	Structure of Slags.	287
9.2.1	Effect of Individual Slag Components on Structure	287
9.2.2	Parameters to Represent the Structure of Slags	292
9.2.3	Effect of Cations	295
9.2.4	Effect of Temperature on Properties	297
9.3	Crystallisation in Mould Fluxes	299
9.3.1	Importance of Crystallisation to the Process	299
9.3.2	Crystalline Phases Formed in Slag Films	300
9.3.3	Crystallisation Process.	303
9.3.4	Crystallisation Kinetics	305
9.3.5	Effects of Crystallisation	308
9.3.6	Methods of Determining Fraction of Crystalline Phase in Slag Films	310
9.3.7	Tests to Simulate f_{crys} Formed in Slag Film	313
9.3.8	Empirical Rules to Calculate the Crystal Fraction in Slag Films.	313
9.3.9	Data for f_{crys}	314
9.4	Physical Properties of Mould Slags	315
9.4.1	Thermodynamic Properties and Liquidus Temperatures (T_{liq})	315
9.4.2	Break Temperature (T_{br})	318
9.4.3	Glass Transition Temperatures (T_g).	320
9.4.4	Viscosities (η).	321
9.4.5	Thermal Conductivities	327
9.4.6	Interfacial Tension (γ_{msl}) and Surface Tension (γ_s).	341
9.4.7	Density (ρ) and Thermal Expansion Coefficient (α).	350
9.4.8	Heat Capacity (C_p) and Enthalpy ($H_T - H_{298}$).	354
9.5	Optical Properties of Mould Slags	360
9.5.1	Refractive Indices (n) [53, 55, 206, 278, 279]	361
9.5.2	Absorption Coefficients (α^*) [53, 55, 56, 59, 110, 206, 211, 212, 280, 281].	361
9.5.3	Reflectivity, Transmissivity and Emissivity.	362

9.6	Thermomechanical Properties of Mould Slags	363
9.6.1	Thermomechanical Tests	363
9.6.2	Stress Relaxation	364
9.7	Dissolution of Oxides, Nitrides and Carbides in Mould Slags	364
9.7.1	Origin of Inclusions	365
9.7.2	Mechanism of Inclusion Removal	366
9.7.3	Transport of Inclusions to the Slag/Metal Interface	366
9.7.4	Transport Through Slag/Metal Interface	369
9.7.5	Dissolution of Inclusions	370
9.8	Other Tests Used on Mould Powders	372
9.8.1	Bulk Density	372
9.8.2	Flowability	373
9.8.3	Permeability Index	374
9.8.4	Thermal Insulation	374
9.8.5	Measurement of Moisture and Hydrogen	376
9.9	Comparison of Properties of Powders Used in Ingot- (IC) and Continuous Casting (CC)	376
9.9.1	Differences in Properties of Mould Powders Used in CC and IC	377
9.9.2	Tasks Carried Out by Powders Used in Continuous- and Ingot Casting	379
9.9.3	Properties and Characteristics of Powders Used in Continuous and Ingot Casting	379
9.9.4	Conclusions from Comparison of CC and IC Mould Powders	379
9.10	Summary	382
	References	383
10	Selection of Mould Fluxes and Special Mould Fluxes for Continuous Casting	393
10.1	Introduction	394
10.2	Selection of Mineral Compositions of Mould Powder for Given Casting Conditions	395
10.2.1	Effect of Mould Geometry on Mould Powder Selection	396
10.2.2	Effect of Casting Conditions on Mould Powder Selection	398
10.2.3	Effect of Steel Grade on Mould Powder Selection	399
10.2.4	Routines to Differentiate Between Steel Grades	400
10.2.5	Plots of T_{br} as a Function of Slag Viscosity	403
10.2.6	Other Casting Conditions Affecting Powder Consumption	404

10.3	Selection of Carbon Components of Mould Powders	405
10.4	Mould Powder Selection for Special Conditions	406
10.4.1	Thin-Slab Casting	408
10.4.2	Round Billets	409
10.4.3	Mould Powder Selection for Moulds with Large “Corner” Regions	409
10.4.4	Casting High-Al (Trip, Twip) Steel Grades.	410
10.4.5	Fluoride-Free Powders	411
10.4.6	Reducing SEN Erosion Rates	412
10.4.7	Minimising Carbon Pick-up	412
10.4.8	Minimising Scale Formation	413
10.5	Summary	413
	References	414
11	Using Mould Fluxes to Minimise Defects and Process Problems	417
11.1	Introduction	418
11.2	Longitudinal Cracking	418
11.2.1	Type of Steel	419
11.2.2	Heat Flux	421
11.2.3	Lubrication and Powder Consumption	425
11.2.4	Metal Flow, Use of EMBr, EMC and EMS	425
11.2.5	Causes and Mechanisms	426
11.2.6	Ways of Dealing with Longitudinal Cracking	428
11.3	Longitudinal Corner Cracking	430
11.3.1	Published Information	430
11.3.2	Causes, Mechanisms	430
11.3.3	Ways of Dealing with Longitudinal Corner Cracking	433
11.4	Sticker Breakouts	434
11.4.1	Factors Affecting Sticker Breakouts	435
11.4.2	Causes, Mechanisms	442
11.4.3	Ways of Dealing with Sticker Breakout	443
11.5	Oscillation Marks (OM’s)	446
11.5.1	Characteristics of Oscillation Marks	446
11.5.2	Mould Oscillation	448
11.5.3	Factors Affecting Depth of OM’s (D_{OM}).	449
11.5.4	Causes, Mechanisms	456
11.5.5	Ways of Dealing with Deep OM’s	459
11.6	Transverse and Corner Cracking	461
11.6.1	Factors Affecting Transverse Cracking	463
11.6.2	Ways of Dealing with Transverse and Corner Cracking	467

11.7	Star Cracking	469
11.7.1	Factors Affecting Star Cracking	469
11.7.2	Ways of Dealing with Star Cracking.	471
11.8	Depressions	471
11.8.1	Longitudinal Depressions	471
11.8.2	Transverse Depressions.	476
11.8.3	Off-Corner Depressions.	477
11.9	Overflows.	479
11.9.1	Factors Affecting Overflows	479
11.9.2	Causes, Mechanisms	480
11.9.3	Ways of Dealing with C-Type Effects.	480
11.10	Slag, Gas Entrapment and Sliver Formation.	480
11.10.1	Metal Flow Conditions Leading to Entrapment.	481
11.10.2	Slag Entrapment	493
11.10.3	Gas Entrapment.	500
11.10.4	Inclusion Capture, Sliver Formation	506
11.11	Formation of Scales	511
11.11.1	Factors Affecting Scale Formation	512
11.11.2	Causes, Mechanisms	513
11.11.3	Ways of Dealing with Scaling	515
11.12	Carbon Pick-up	515
11.12.1	Factors Affecting Carbon Pick-up	515
11.12.2	Causes, Mechanisms	516
11.12.3	Ways of Dealing with Carbon Pick-up	517
11.13	SEN Erosion	519
11.13.1	Factors Affecting SEN Erosion Rates	520
11.13.2	Causes, Mechanisms	522
11.13.3	Ways of Dealing with SEN Erosion	524
11.14	Fluorine Emissions.	525
11.14.1	Factors Affecting Fluoride Emissions	525
11.14.2	Ways of Dealing with Fluoride Emissions	526
11.15	Summary	526
	References	528

<http://www.springer.com/978-3-319-53614-9>

The Casting Powders Book

Mills, K.C.; Däcker, C.-Å.

2017, XIX, 535 p. 322 illus., 151 illus. in color.,

Hardcover

ISBN: 978-3-319-53614-9