

Ag – Ta (Silver – Tantalum)

Phase diagram

On the basis of information taken from Baren [88 Bar], [Moffatt] has sketched a phase diagram which is shown in Fig. 1.

Figure




Fig. 1. Ag-Ta. Phase diagram sketched by [Moffatt].

References

- [88 Bar] Baren, M.R.: Bull. Alloy Phase Diagrams **9** (1988) 244
 [Moffatt] Moffatt, W.G., (ed.): "Handbook of Binary Phase Diagrams", Business Growth Services, General Electric Co., Schenectady, New York (1976)