

Contents

III/33 Diffusion in Semiconductors and Non-Metallic Solids

Subvolume A: Diffusion in Semiconductors

1	General introduction (D.L. BEKE)	1-1
1.1	Atomic fluxes	1-1
1.2	Equations for diffusion	1-3
1.2.1	Bulk diffusion	1-4
1.2.1.1	Tracer diffusion in a homogeneous matrix	1-4
1.2.1.2	Chemical diffusion	1-6
1.2.2	Grain-boundary diffusion	1-9
1.2.2.1	Self-diffusion	1-11
1.2.2.2	Impurity diffusion and segregation	1-12
1.2.3	Dislocation diffusion	1-12
1.2.4	Surface diffusion	1-12
1.3	Atomic mechanisms of diffusion	1-13
1.3.1	Direct interstitial mechanism	1-14
1.3.2	Indirect interstitial or interstitialcy mechanism	1-14
1.3.3	Ring mechanism	1-14
1.3.4	Vacancy mechanism	1-14
1.3.5	Interstitial-substitutional mechanisms	1-14
1.3.6	Other mechanisms	1-15
1.4	Methods for measuring diffusion coefficients	1-15
1.4.1	Macroscopic methods	1-16
1.4.1.1	Steady-state methods	1-16
1.4.1.2	Non steady-state methods	1-16
1.4.2	Microscopic methods	1-17
1.4.2.1	Relaxation methods	1-17
1.4.2.2	Nuclear methods	1-18
1.5	Temperature, pressure and mass dependence of diffusion	1-18
1.5.1	Temperature and pressure dependence	1-18
1.5.2	Mass dependence	1-19
1.6	Notations, use of the tables	1-19
1.7	Further readings	1-20
1.7.1	Textbooks	1-20
1.7.2	Proceedings	1-20
1.7.3	Collections of data	1-21
1.7.4	Review articles	1-21
1.8	References for 1	1-21

2	Diffusion in silicon, germanium and their alloys (N.A. STOLWIJK, H. BRACHT)	2-1
2.1	Introduction	2-1
2.1.1	Characteristics of diffusion in semiconductors	2-1
2.1.2	Expressions for the diffusion coefficient	2-2
2.1.3	Methods of measurement	2-5
2.1.4	Notations and use of tables	2-6
2.2	Diffusion in silicon	2-12
2.2.1	Tables for 2.2	2-12
2.2.1.1	Solute elements of group IA (hydrogen group)	2-12
2.2.1.2	Solute elements of group IIA (beryllium group)	2-19
2.2.1.3	Solute elements of group IIIB (scandium group including rare earth elements)	2-20
2.2.1.4	Solute elements of group IVB (titanium group)	2-22
2.2.1.5	Solute elements of group VB (vanadium group)	2-23
2.2.1.6	Solute elements of group VIB (chromium group)	2-24
2.2.1.7	Solute elements of group VIIB (manganese group)	2-26
2.2.1.8	Solute elements of group VIII (iron group)	2-28
2.2.1.9	Solute elements of group VIII (cobalt group)	2-30
2.2.1.10	Solute elements of group VIII (nickel group)	2-32
2.2.1.11	Solute elements of group IB (copper group)	2-35
2.2.1.12	Solute elements of group IIB (zinc group)	2-44
2.2.1.13	Solute elements of group IIIA (boron group)	2-47
2.2.1.14	Solute elements of group IVA (carbon group)	2-75
2.2.1.15	Solute elements of group VA (nitrogen group)	2-89
2.2.1.16	Solute elements of group VIA (oxygen group)	2-124
2.2.1.17	Solute elements of group VIIA (fluorine group)	2-130
2.2.1.18	Solute elements of group VIIIA (helium group)	2-132
2.2.2	Figures for 2.2	2-135
2.2.3	References for 2.1 and 2.2	2-196
2.2.3.1	Textbooks	2-196
2.2.3.2	Data collections	2-196
2.2.3.3	Review papers	2-196
2.2.3.4	Articles	2-199
2.3	Diffusion in germanium	2-222
2.3.1	Tables for 2.3	2-222
2.3.1.1	Solute elements of group IA to group VIII	2-222
2.3.1.2	Solute elements of group IB and group IIB	2-223
2.3.1.3	Solute elements of group IIIA	2-225
2.3.1.4	Solute elements of group IVA	2-227
2.3.1.5	Solute elements of group VA	2-228
2.3.1.6	Solute elements of group VIA to group VIIIA	2-230
2.3.2	Figures for 2.3	2-231
2.3.3	References for 2.3	2-237
2.3.3.1	Textbooks	2-237
2.3.3.2	Data collections	2-237
2.3.3.3	Review papers	2-237
2.3.3.4	Articles	2-238
2.4	Diffusion in silicon-germanium alloys	2-241
2.4.1	Tables for 2.4	2-241
2.4.2	Figures for 2.4	2-249
2.4.3	References for 2.4	2-256

3	Diffusion in compound semiconductors (M.B. DUTT, B.L. SHARMA)	3-1
3.1	Introduction	3-1
3.2	Use of tables	3-2
3.3	Experimental methods	3-2
3.4	Evaluation techniques	3-4
3.5	Diffusion in III-V compounds and their ternary alloys	3-6
3.5.1	Self-diffusion	3-6
3.5.2	Diffusion of shallow donors	3-9
3.5.2.1	Group IV impurities	3-9
3.5.2.2	Group VI impurities	3-10
3.5.3	Diffusion of shallow acceptors	3-14
3.5.4	Diffusion of group I impurities	3-20
3.5.5	Diffusion of other impurities	3-23
3.5.6	Diffusion in III-V compound ternary alloys	3-27
3.6	Diffusion in II-VI compounds and their ternary alloys	3-31
3.6.1	Diffusion of group II and group VI elements	3-31
3.6.1.1	Metal self-diffusion	3-32
3.6.1.2	Chalcogen self-diffusion	3-32
3.6.1.3	Complementary metal and chalcogen diffusion	3-32
3.6.2	Diffusion of group I impurities	3-38
3.6.3	Diffusion of donor impurities	3-40
3.6.3.1	Group III impurities	3-41
3.6.3.2	Group VII impurities	3-42
3.6.4	Diffusion of other impurities	3-44
3.6.5	Diffusion in II-VI compound ternary alloys	3-47
3.7	Diffusion in IV-VI compounds	3-53
3.7.1	Self-diffusion	3-53
3.7.2	Impurity diffusion	3-53
3.8	Diffusion in other useful compounds	3-59
3.8.1	Diffusion in SiC	3-59
3.8.2	Diffusion in some group II-V and V-VI compounds	3-59
	Figures for 3	3-64
3.9	References for 3	3-70
4	Diffusion in silicides (P. GAS, F.M. d'HEURLE)	4-1
4.1	Introduction	4-1
4.2	Diffusion controlled formation of silicide thin films	4-5
4.3	Diffusion controlled formation of "bulk" silicides	4-12
4.4	Tracer diffusion in silicides	4-15
	Figures for 4	4-21
4.5	References for 4	4-35
5	Chemical diffusion in semiconductors (C.M. BRUFF, G.E. MURCH)	5-1
5.1	Introduction	5-1
5.2	Use of the tables	5-2
5.3	Data	5-3
	Figures for 5	5-9
5.4	References for 5	5-25

6	Grain-boundary and dislocation diffusion in semiconductors and silicides (G. ERDÉLYI, D.L. BEKE)	6-1
6.1	Introduction	6-1
6.1.1	General remarks	6-1
6.1.2	Methods of measurements	6-1
6.1.2.1	Low angle grain boundary method	6-1
6.1.2.2	Defect annealing method	6-2
6.1.2.3	Pavlov-Panteleev method	6-2
6.1.2.4	Indirect methods in type-A kinetic regime	6-2
6.1.2.5	Determination of double products from creep and sintering experiments	6-2
6.1.2.6	Isoconcentration contour method	6-2
6.1.2.7	Hwang-Balluffi method	6-3
6.1.2.8	First appearance method	6-3
6.1.2.9	Gilmer-Farrell method	6-3
6.2	Use of tables and figures	6-4
6.2.1	Some general remarks	6-4
6.2.2	Practical guide to the use of the tables	6-4
6.3	Dislocation diffusion in semiconductors	6-6
6.4	Grain-boundary diffusion in semiconductors and silicides	6-9
6.4.1	Grain-boundary diffusion in elemental semiconductors	6-9
6.4.2	Grain-boundary diffusion in compound semiconductors	6-16
6.4.3	Grain-boundary diffusion in silicides	6-17
	Figures for 6	6-20
6.5	References for 6	6-24
7	Surface diffusion on semiconductors (E.G. SEEBAUER, C.E. ALLEN)	7-1
7.1	Introduction	7-1
7.1.1	General remarks	7-1
7.1.2	Definitions of diffusion parameters	7-1
7.2	Experimental techniques	7-2
7.2.1	Single-atom imaging	7-2
7.2.2	Electron diffraction	7-3
7.2.3	Chemical state relaxation	7-3
7.2.4	Spin axis relaxation	7-4
7.2.5	Profile evolution	7-4
7.2.6	Capillarity-driven effects	7-5
7.2.7	Island growth	7-5
7.2.8	Miscellaneous	7-6
7.3	Physical picture	7-6
7.3.1	Intrinsic diffusion	7-6
7.3.2	Mass transfer diffusion	7-6
7.4	General correlations	7-8
7.4.1	Intrinsic diffusion	7-8
7.4.2	Mass transfer diffusion	7-8
7.4.3	Adsorbate concentration dependence	7-9
7.5	Commentary to tables	7-9
7.6	Surface diffusion tables	7-10
	Figures for 7	7-13
7.7	Special references: review articles	7-17
7.8	References for 7	7-18



<http://www.springer.com/978-3-540-60964-3>

Diffusion in Semiconductors

1998, XIII, 476 p. With CD-ROM., Hardcover

ISBN: 978-3-540-60964-3