

IV/11 Ternary Alloy Systems

Phase Diagrams, Crystallographic and Thermodynamic Data

Subvolume C: Non-Ferrous Metal Systems

Part 3: Selected Soldering and Brazing Systems

Ag - ...	Au - ...	B - ...	Bi - ...	Co - ...
Ag - Bi - Cu Ag - Bi - Sn Ag - Cu - In Ag - Cu - Mn Ag - Cu - Ni Ag - Cu - P Ag - Cu - Sn Ag - Cu - Ti Ag - Cu - Zn Ag - In - Sb Ag - In - Sn Ag - Pb - Sn Ag - Sn - Zn	Au - Bi - Sn Au - Cu - Sn Au - In - Sn	B - Cr - Ni	Bi - In - Sb Bi - In - Sn Bi - Sn - Zn	Co - Cu - Mn

Cr - ...	Cu - ...	In - ...	Mn - ...	Ni - ...
Cr - Ni - P Cr - Ni - Si	Cu - In - Sn Cu - Mn - Ni Cu - Mn - Sn Cu - Ni - Sn Cu - Ni - Zn Cu - P - Sn Cu - Pb - Sn Cu - Pd - Sn Cu - Si - Zn Cu - Sn - Ti Cu - Sn - Zn Cu - Ti - Zr	In - Ti - Zn	Mn - Ti - Zr	Ni - Pd - Si



<http://www.springer.com/978-3-540-25777-6>

Selected Soldering and Brazing Systems
Materials Science International Team MSIT
2007, XVII, 493 p. With CD-ROM., Hardcover
ISBN: 978-3-540-25777-6