
Contents

1	What Does It Mean “Metal Cutting”?	1
1.1	Introduction	1
1.2	Known Results and Comparison with Other Forming Processes	2
1.2.1	Single-shear Plane Model of Metal Cutting	2
1.2.2	Metal Cutting vs. Other Closely Related Manufacturing Operations	5
1.3	What Went Wrong in the Representation of Metal Cutting?	22
1.3.1	Force Diagram	23
1.3.2	Resistance of the Work Material in Cutting	25
1.3.3	Comparison of the Known Solutions for the Single-shear Plane Model with Experimental Results	27
1.4	What is Metal Cutting?	28
1.4.1	Importance to Know the Right Answer	28
1.4.2	Definition	28
1.4.3	Relevance to the Cutting Tool Geometry	29
1.5	Fundamental Laws of Metal Cutting	32
1.5.1	Optimal Cutting Temperature – Makarow’s Law	32
1.5.2	Deformation Law	35
	References	50
2	Basic Definitions and Cutting Tool Geometry,	
	Single Point Cutting Tools	55
2.1	Basic Terms and Definitions	55
2.1.1	Workpiece Surfaces	57
2.1.2	Tool Surfaces and Elements	57
2.1.3	Tool and Workpiece Motions	57
2.1.4	Types of Cutting	58
2.2	Cutting Tool Geometry Standards	60
2.3	Systems of Consideration of Tool Geometry	61
2.4	Tool-in-hand System (T-hand-S)	64

2.4.1	Tool-in-hand Coordinate System	64
2.4.2	References Planes	66
2.4.3	Tool Angles.....	68
2.4.4	Geometry of Cutting Tools with Indexable Inserts	74
2.5	Tool-in-machine System (T-mach-S).....	84
2.5.1	Angles	84
2.5.2	Example 2.3	88
2.6	Tool-in-use System (T-use-S)	90
2.6.1	Reference Planes	91
2.6.2	The Concept	92
2.6.3	Modification of the T-hand-S Cool Geometry	92
2.6.4	Kinematic Angles.....	98
2.6.5	Example 2.4	100
2.7	Avalanched Representation of the Cutting Tool Geometry in T-hand-S.....	102
2.7.1	Basic Tool Geometry	102
2.7.2	Determination of Cutting Tool Angles Relation for a Wiper Cutting Insert	108
2.7.3	Determination of Cutting Tool Angles for a Single-point Tool.....	110
2.7.4	Flank Angles of a Dovetail Forming Tool	117
2.7.5	Summation of Several Motions.....	119
	References.....	125
3	Fundamentals of the Selection of Cutting Tool Geometry Parameters...	127
3.1	Introduction	127
3.2	General Considerations in the Selection of Parameters of Cutting Tool Geometry	129
3.2.1	Known Results	129
3.2.2	Ideal Tool Geometry and Constrains.....	130
3.2.3	Practical Gage for Experimental Evaluation of Tool Geometry ...	132
3.3	Tool Cutting Edge Angles	132
3.3.1	General Consideration.....	132
3.3.2	Uncut ChipT in Non-free Cutting	134
3.3.3	Influence on the Surface Finish.....	142
3.3.4	Tools with $\kappa_r > 90^\circ$	144
3.3.5	Tool Minor Cutting Edge Angle	147
3.4	Edge Preparation	161
3.4.1	General	161
3.4.2	Shape and Extent.....	163
3.4.3	Limitations	163
3.4.4	What Edge Preparation Actually Does.....	169
3.5	Rake Angle.....	171
3.5.1	Introduction.....	171
3.5.2	Influence on Plastic Deformation and Generazliations	175

3.5.3	Effective Rake Angle	183
3.5.4	Conditions for Using High Rake Angles.....	189
3.6	Flank Angle	191
3.7	Inclination Angle.....	193
3.7.1	Turning with Rotary Tools.....	195
3.7.2	Helical Treading Taps and Broaches.....	197
3.7.3	Milling Tools.....	198
	References.....	201
4	Straight Flute and Twist Drills	205
4.1	Introduction	205
4.2	Classification	206
4.3	Basic Terms.....	208
4.4	System Approach	211
4.4.1	System Objective	212
4.4.2	Understanding the Drilling System	212
4.4.3	Understanding the Tool.....	212
4.5	Force System Constrains on the Drill Penetration Rate	213
4.5.1	Force-balance Problem in Conventional Drills	213
4.5.2	Constrains on the Drill Penetration Rate.....	218
4.5.3	Drilling Torque	219
4.5.4	Axial Force.....	220
4.5.5	Axial Force (Thrust)-torque Coupling	221
4.6	Drill Point	223
4.6.1	Basic Classifications	223
4.6.2	Tool Geometry Measures to Increase the Allowable Penetration Rate	224
4.7	Common Design and Manufacturing Flaws.....	259
4.7.1	Web Eccentricity/ Lip Index Error.....	260
4.7.2	Poor Surface Finish and Improper Tool Material/Hardness.....	261
4.7.3	Coolant Hole Location and Size.....	263
4.8	Tool Geometry	267
4.8.1	Straight-flute and Twist Drills Particularities.....	269
4.8.2	Geometry of the Typical Drill Point	270
4.8.3	Rake Angle.....	272
4.8.4	Inclination Angle	280
4.8.5	Flank Angle.....	281
4.8.6	Geometry of a Cutting Edge Located at an Angle to the y_0 -plane	292
4.8.7	Chisel Edge	295
4.8.8	Drill Flank is Formed by Two Planes: Generalization	306
4.8.9	Drill Flank Angle Formed by Three Planes	310
4.8.10	Flank Formed by Quadratic Surfaces.....	313
4.9	Load Over the Drill Cutting Edge	324

4.9.1	Uncut Chip Thickness in Drilling	325
4.9.2	Load Distribution Over the Cutting Edge	327
4.10	Drills with Curved and Segmented Cutting Edges	328
4.10.1	Load of the Cutting Part of a Drill with Curved Cutting Edges	329
4.10.2	Rake Angle	332
	References.....	337
5	Deep-hole Tools.....	341
5.1	Introduction	341
5.2	Generic Classification of Deep-hole Machining Operations	343
5.3	What Does ‘Self-piloting Tool’ Mean?	345
5.3.1	Force Balance in Self-piloting Tools.....	345
5.4	Three Basic Kinematic Schemes of Drilling	350
5.4.1	Gundrill Rotates and the Workpiece is Stationary	351
5.4.2	Workpiece Rotates and the Gundrill is Stationary	352
5.4.3	Counterrotation	352
5.5	System Approach	353
5.5.1	Handling Tool Failure	353
5.5.2	System Considerations	354
5.6	Gundrills.....	362
5.6.1	Basic Geometry	362
5.6.2	Rake Surface	365
5.6.3	Geometry of Major Flanks	370
5.6.4	System Considerations in Gundrill Design	390
5.6.5	Exemplification of Significance of the High MWF Pressure in the Bottom Clearance Space	423
5.6.6	Example of Experimental Study	425
5.6.7	Optimization of Tool Geometry	439
	References.....	440
Appendix A		
Basic Kinematics of Turning and Drilling.....		443
A.1	Introduction	443
A.2	Turning and Boring	444
A.2.1	Basic Motions in Turning.....	444
A.2.2	Cutting Speed in Turning and Boring	448
A.2.3	Feed and Feed Rate	448
A.2.4	Depth of Cut.....	449
A.2.5	Material Removal Rate	449
A.2.6	Resultant Motion.....	450
A.3	Drilling and Reaming	450
A.3.1	Basic Motions in Drilling.....	450
A.3.2	Machining Regime	451
A.4	Cutting Force and Power.....	453

A.4.1 Force System in Metal Cutting.....	453
A.4.2 Cutting Power	454
A.4.3 Practical Assessment of the Cutting Force.....	455
References.....	461

Appendix B

ANSI and ISO Turning Indexable Inserts and Holders.....	463
B.1 Indexable Inserts	463
B.1.1 ANSI Code	464
B.1.2 ISO Code.....	471
B.2 Tool Holders for Indexable Inserts (Single Point Tools)	491
B.2.1 Symbol for the Method of Holding Horizontally Mounted Insert – Reference Position (1)	492
B.2.2 Symbol for Insert Shape – Reference Position (2)	493
B.2.3 Symbol for Tool Style – Reference Position (3)	493
B.2.4 Letter Symbol Identifying Insert Normal Clearance – Reference Position (4).....	494
B.2.5 Symbol for Tool Hand – Reference position (5)	494
B.2.6 Symbol for Tool Height (Shank Height of Tool Holders and Height of Cutting Edge) - Reference Position (6)	494
B.2.7 Number Symbol Identifying Tool Holder Shank Width – Reference Position (7).....	495
B.2.8 Number Symbol Identifying Tool Length – Reference Position (8).....	495
B.2.9 Letter Symbol Identifying Indexable Insert Size – Reference Position (9).....	497

Appendix C

Basics of Vector Analysis	499
C.1 Vectors and Scalars	499
C.2 Definition and Representation.....	500
C.2.1 Definitions.....	500
C.2.2 Basic Vector Operations	503
C.3 Application Conveniences.....	509
C.4 Rotation: Linear and Angular Velocities.....	511
C.4.1 Planar Linear and Angular Velocities	511
C.4.2 Rotation: The Angular Velocity Vector	515
References	518

Appendix D

Hydraulic Losses: Basics and Gundrill Specifics.....	519
D.1 Hydraulic Pressure Losses – General	519
D.1.1 Major Losses: Friction Factor	520
D.1.2 Minor Losses (Losses Due to Form Resistance)	521

D.2	Concept of the Critical MWF Velocity and Flow Rate	521
D.2.1	MWF Flow Rate Needed for Reliable Chip Transportation.....	522
D.2.3	Example D.1.....	527
D.3	Inlet MWF pressure.....	528
D.4	Analysis of Hydraulic Resistances	532
D.4.1	Analysis of Hydraulic Resistances Over Which the Designer Has No or Little Control	532
D.4.2	Variable Resistances Over Which the Designer Has Control	535
D.5	Practical Implementation in the Drill Design	539
References	543
 Appendix E		
Requirements and Examples of Cutting Tool Drawings.....		545
E.1	Introduction	545
E.2	Tool Drawings – the Existent Practice	546
E.3	Tool Drawing Requirements	548
E.4	Examples of Tool Drawing	553
References	559
 Index.....		561

Geometry of Single-point Turning Tools and Drills

Fundamentals and Practical Applications

Astakhov, V.P.

2010, XXII, 565 p. 451 illus., Hardcover

ISBN: 978-1-84996-052-6