

Contents

| | | |
|----------|--|----------|
| 1 | General Information About Piezoelectric Sensors | 1 |
| 1.1 | Short Historical Essay | 1 |
| 1.2 | Determination and Classification of Piezoelectric Sensors | 2 |
| 1.3 | Properties and Descriptions of Piezomaterials | 5 |
| 1.4 | Transducer Research Methods | 7 |
| 1.5 | Piezoceramic Material and Element Parameters | 8 |
| 1.6 | Determining Piezoceramic Element Parameters | 9 |
| 1.6.1 | Defining the Electromechanical Communication Coefficient | 9 |
| 1.6.2 | Phase Measurement of Resonant f_r and Antiresonant f_a Frequencies of Radial and Longitudinal Fluctuations | 9 |
| 1.6.3 | Measurement of Resonant Frequency f_r | 9 |
| 1.6.4 | Measurement of Antiresonant Frequency f_r | 10 |
| 1.6.5 | Best (Amplitude?) Method of Measuring Resonant f_r and Antiresonant f_a Frequencies | 11 |
| 1.6.6 | Measurement of Frequency in the First Overtone f_{01} | 11 |
| 1.6.7 | Definition of Poisson's Coefficient σ | 12 |
| 1.6.8 | Definition of the Least Positive Root of the Frequency Equation η | 12 |
| 1.6.9 | Relative Dielectric Permeability (Constant, Permittivity?) $\varepsilon_{33}^T/\varepsilon_0$ | 12 |
| 1.6.10 | Specific Volume Electric Resistance ρ_v | 13 |
| 1.6.11 | Defining Piezo-modules d_{31} and d_{33} in a Dynamic Mode | 13 |
| 1.6.12 | Piezo-module d_{33} in a Static Mode | 14 |
| 1.6.13 | Young's Modulus Y_{31}^Y | 14 |
| 1.6.14 | Speed of Sound v_3^D | 15 |

| | | |
|----------|---|-----|
| 1.6.15 | Good Mechanical Quality Q_m | 15 |
| 1.6.16 | Definition of Curie Point Temperature T_C | 15 |
| 1.7 | Piezoceramic Materials | 16 |
| 1.8 | Formulas for the Calculation of Piezoceramic Material Descriptions | 18 |
| 1.8.1 | Piezoceramic Disk (Fig. 1.5) | 18 |
| 1.8.2 | Piezoceramic Bar (Fig. 1.6) | 19 |
| 1.8.3 | Piezoceramic Rectangular Plate (Fig. 1.7) | 19 |
| 1.9 | Sensor [Physical Size] Descriptions | 21 |
| | References | 22 |
| 2 | Monomorph Piezoceramic Elements | 25 |
| 2.1 | Calculating Electric Piezoceramic | 25 |
| 2.1.1 | Resonator Parameters | 25 |
| 2.2 | Equivalent Schemes for Piezoresonators | 28 |
| 2.3 | Calculate Piezoresonator Electric Parameters | 34 |
| 2.4 | Fluctuations of Piezoceramic Rods | 47 |
| 2.4.1 | Longitudinal Fluctuations of a Rod in a Transverse Field | 48 |
| 2.4.2 | Longitudinal Fluctuations of a Rod in a Longitudinal Field | 49 |
| 2.4.3 | Fluctuations of a Piezoceramic Disk | 50 |
| 2.5 | Piezoceramic Transformers | 51 |
| 2.5.1 | Piezoelectric Transformer in the Form of Thin Disks and Rings | 55 |
| | References | 68 |
| 3 | Spatial Energy–Force Structure of Piezoceramic Transducers | 71 |
| 3.1 | Synthesis of Piezoelement Spatial Energy–Force Structure | 71 |
| 3.2 | Anisotropy of Piezoceramic Materials Characteristics | 79 |
| 3.3 | Transverse Piezoelectric Transducers | 82 |
| 3.4 | Piezotransformers | 85 |
| 3.4.1 | Disk Piezotransformers | 93 |
| | References | 97 |
| 4 | Measuring Circuits of Piezoelectric Sensors | 99 |
| 4.1 | Charge Amplifiers | 99 |
| 4.2 | Voltage Amplifiers | 110 |
| | References | 111 |
| 5 | Feedback in Piezoceramic Sensors | 113 |
| 5.1 | Feedback Effect on Sensor Characteristics | 113 |
| 5.1.1 | Influence of Frequency-Dependent Feedback | 114 |
| 5.1.2 | Influence of Frequency-Independent FB | 116 |
| 5.1.3 | Feedback Influence on Nonlinear and Frequency Distortions | 117 |
| 5.1.4 | Feedback Influence on Time Constant of Sensors | 118 |

| | | |
|----------|---|------------|
| 5.1.5 | Feedback Influence on Input and Output Resistances | 118 |
| 5.1.6 | Feedback Influence on Static Systems Errors | 119 |
| 5.2 | Piezoceramic Sensors with Spatial Electromechanical NFB | 120 |
| 5.3 | Domain-Dissipative Piezoceramic Sensors with Spatial Electromechanical NFB | 126 |
| 5.4 | Piezoceramic Sensors with Piezoelement in FB Circuit of Charge Amplifier | 130 |
| 5.5 | Electric Feedback in Piezoceramic Sensors | 139 |
| 5.6 | Sensors with Combined Feedback | 143 |
| 5.7 | Electric Damping of Piezoceramic Sensors with Feedback | 147 |
| 5.8 | Sensors with Two Feedback Channels | 151 |
| 5.8.1 | Sensors with Output Charge Amplifier and Voltage Amplifier in Additional Feedback Channel | 160 |
| 5.8.2 | Sensors with Output Voltage Amplifier and Charge Amplifier in Additional FB Channel | 165 |
| 5.8.3 | Piezosensors with Two Charge Amplifiers with Piezoelements in FB Circuits of Amplifiers | 170 |
| 5.9 | Piezosensor with Charge Amplifier and FB Channel on Voltage Amplifier | 174 |
| | References | 176 |
| 6 | Bimorph and Trimorph Piezoelements | 179 |
| 6.1 | Symmetric Bimorph Piezoelements | 179 |
| 6.2 | Asymmetric Bimorph Piezoelements | 184 |
| 6.3 | Trimorph Piezoelements | 196 |
| 6.3.1 | Asymmetric Planar Trimorph Piezoelements | 196 |
| 6.3.2 | Asymmetric Coplanar Trimorph Piezotransducers | 201 |
| 6.3.3 | Symmetric Coplanar Trimorph Transducer | 209 |
| 6.4 | Vibrations of Asymmetric Coplanar Trimorph Piezotransducer with FB | 216 |
| 6.5 | Technology of Bimorph Piezoelement Production | 224 |
| | References | 228 |
| 7 | Devices to Control and Diagnose Bimorph Piezoelements | 231 |
| 7.1 | Defects of Bimorph Piezoelements | 231 |
| 7.2 | Defect Diagnostics by AFC | 232 |
| 7.3 | Diagnostics of Defects by Pulse Characteristic | 237 |
| 7.4 | Diagnostics of Defects by Transitive Characteristic | 241 |
| 7.4.1 | Device Based on Aperiodic Networks | 245 |
| 7.5 | Devices Based on Active Oscillator Circuit | 247 |
| | References | 249 |

| | | |
|-----------|--|-----|
| 8 | Piezomagnetic Sensors | 253 |
| 8.1 | Influence of Magnet Design Factors on Sensor Characteristics | 253 |
| 8.1.1 | Cylindrical Magnets | 253 |
| 8.1.2 | Rectangular Magnets | 257 |
| 8.2 | Piezomagnetic Sensors of Tachometers | 261 |
| 8.2.1 | Piezomagnetic Sensor Models | 266 |
| 8.3 | Improvement of Piezomagnetic Sensor Characteristics | 273 |
| 8.3.1 | Output Signal Enhancement | 273 |
| 8.3.2 | Accuracy Improvement Methods | 276 |
| 8.3.3 | Sensor Design Simplification | 278 |
| 8.3.4 | Suppression of Vibration Hindrances | 280 |
| 8.4 | Piezomagnetic Electro-acoustic Transducers | 282 |
| | References | 284 |
| 9 | Hydroacoustic Transducers | 289 |
| 9.1 | Classification and Characteristics | 289 |
| 9.2 | Ratios of Electromechanical Transformations | 291 |
| 9.3 | Cylindrical Piezoceramic Transducers | 294 |
| 9.4 | Lamellar and Spherical Piezoceramic Transducers | 298 |
| 9.5 | Basic Requirements for Projected Transducers | 300 |
| 9.6 | Selection of Energy Transformation Method and Mode Shape | 301 |
| 9.7 | Certain Transducer Designs | 302 |
| 9.8 | On One Method of Low-Frequency Acoustic Vibration Creation | 309 |
| | References | 313 |
| 10 | Transducers with Non-destructive Control | 317 |
| 10.1 | Designs and Specifications of Ultrasonic Monitor Piezotransducers | 318 |
| 10.1.1 | Coefficient of Electromechanical Transformation | 320 |
| 10.1.2 | Piezotransducer Amplitude–Frequency Response (AFR) | 320 |
| 10.1.3 | Form of Acoustic Field Created | 321 |
| 10.2 | Resonant Volume Piezotransducers | 323 |
| 10.3 | Non-resonant Excitation of Piezoelements | 327 |
| | References | 331 |
| 11 | Sensors of Korotkoff Sounds | 333 |
| 11.1 | General Information | 333 |
| 11.2 | Enhancement of KSS Sensitivity | 337 |
| 11.3 | On Optimum Load Resistance of KSS Piezoelements | 344 |
| 11.4 | Feedback in Korotkoff Sound Sensors | 347 |
| 11.5 | Hindrances at Arterial Pressure Measurement | 350 |
| 11.6 | Sensors of Pulse Waves | 354 |
| | References | 355 |

| | |
|--|-----|
| 12 Electro-acoustic Transducers | 357 |
| 12.1 General Information | 357 |
| 12.2 Transfer Function Calculation of Electro-acoustic Transducers ... | 361 |
| 12.3 Chladni Figures and Transducer Directional Diagrams | 366 |
| 12.4 Methods of Electro-acoustic Transducer Upgrading | 367 |
| 12.5 Electro-acoustic Transducers in Active Oscillator Schemes | 375 |
| References | 379 |
| 13 Piezoceramic Accelerometers | 381 |
| 13.1 Monolithic Accelerometers | 382 |
| 13.2 Multi-element Accelerometers | 386 |
| 13.3 Accelerometer Designs | 390 |
| 13.4 Three-Dimensional Accelerometers | 398 |
| 13.5 Accelerometers Based on Bimorph and Piezoelectric Elements ... | 400 |
| 13.6 Domain-Dissipative Accelerometer and Accelerometers with Feedback | 404 |
| References | 406 |
| 14 Resonant Piezoceramic Sensors | 409 |
| 14.1 Resonant Contact Sensors | 410 |
| 14.2 Measurement of Contact Rigidity and Real Contact Area | 419 |
| 14.3 Frequency-Modulated Oscillation Use for Resonant Piezosensor Excitation | 422 |
| 14.4 Negative Feedback in Resonant Piezosensors | 425 |
| 14.5 Piezosensors with Ultrasonic Concentrators | 428 |
| 14.6 Constructive Control Methods of Force and Pressure Piezosensor Characteristics | 438 |
| 14.7 Piezorezonant Accelerometer | 443 |
| 14.8 Sensor on Acoustically Connected Resonators | 445 |
| 14.8.1 For Gases | 446 |
| References | 448 |
| 15 Sensors with Piezoelements in Scheme Electric Filters | 453 |
| 15.1 Schemes of Electric Filters | 453 |
| 15.1.1 Low-Pass Filters | 456 |
| 15.1.2 High-Pass Filters | 458 |
| 15.2 Sensors with Piezoelements in Low-Pass Filter Schemes | 459 |
| 15.3 Sensors with Piezoelements in High-Pass Filter Schemes | 460 |
| 15.4 Sensors with Piezotransformers in Electric Filter Schemes | 461 |
| References | 468 |
| 16 Piezoceramic Scanners for Probe Nanomicroscopes | 471 |
| 16.1 Nanotechnologies and Nanomicroscopes | 471 |
| 16.1.1 Functional Mechanical Nodes | 472 |
| 16.2 Methods of Scanning Probe Microscopy | 473 |
| 16.2.1 Scanning Tunneling Microscopy | 473 |
| 16.2.2 Atomic-Force Microscopy | 476 |

| | | |
|--------------|--|------------|
| 16.2.3 | Electric Force Microscopy | 478 |
| 16.2.4 | Magnetic Force Microscopy | 479 |
| 16.3 | Scanners on Hollow Piezoceramic Cylinders | 481 |
| 16.4 | Scanners Based on Flat Bimorph Piezoelements | 485 |
| | References | 488 |
| Index | | 491 |



<http://www.springer.com/978-3-642-15310-5>

Piezoceramic Sensors

Sharapov, V.

2011, XII, 500 p., Hardcover

ISBN: 978-3-642-15310-5