

Contents

1	Introduction	1
1.1	Overview	1
1.2	Delayed Hydride Cracking	3
1.3	Objectives and Outline	4
2	Properties of Bulk Zirconium Hydrides	7
2.1	Hydride Phase Compositions, Lattice Structure and Parameter Determinations	7
2.1.1	Crystallographic Properties of the γ -Hydride Phase	8
2.1.2	Phase Relationships, Phase Stability, and Hydrogen Compositions in the δ - and γ -Hydride Phases at the $(\alpha + \delta)/\delta$ Phase Boundary	10
2.1.3	Crystallography of the δ -Hydride Phase	19
2.2	Mechanical Properties of Bulk Zirconium Hydrides	22
2.2.1	Yield Strength	22
2.2.2	Fracture Toughness	37
2.2.3	Microhardness, Elastic Moduli, Internal Friction	40
2.2.4	Summary of Mechanical Strength Results	49
	References	51
3	Hydride Phases, Orientation Relationships, Habit Planes, and Morphologies	53
3.1	Introduction	53
3.2	Hydride Precipitation in α -Zr Alloys: Early Analyses Derived from Observations of γ -hydride Precipitates	54
3.3	Hydride Precipitation in α -Zr Alloys: Determinations of Lattice Transformation Relationships of γ -Hydride Precipitates	64
3.3.1	Introduction	64

3.3.2	$\{1\ 0\ \bar{1}\ \ell\}$ Habit Planes	66
3.3.3	$\{1\ 0\ \bar{1}\ 0\}$ Habit Planes	70
3.4	Hydride Precipitation in α/β -Zr Alloys	74
3.5	Hydride Nucleation Studies in α/β Zr-2.5Nb Pressure Tube Material	91
3.5.1	Microstructure of Zr-2.5Nb Alloys	91
3.5.2	Hydride Precipitation in α/β_{Zr} Microstructures	94
3.5.3	Hydride Precipitation in $\alpha/\beta/\omega$ Microstructures.	95
3.5.4	Influence of Prior Deformation on Hydride Precipitation	99
	References	105
4	Solubility of Hydrogen	109
4.1	Solubility in the Dilute Phase of Single Phase Metal–Hydrogen Systems	109
4.2	Solubility of Hydrogen in the Dilute Phase of α/β Zirconium Alloys	113
4.3	Effect of Stress on Hydrogen Chemical Potential in the Dilute Phase	116
4.4	Interaction Energy Expressions	123
4.4.1	Partial Molar Volume	123
4.4.2	Size–Effect Interaction	127
4.4.3	Diaelastic Polarizability	129
4.4.4	Paraelastic Polarizability	131
4.4.5	Interactions Between Hydrogen Atoms in Solution	132
4.5	Interaction of Hydrogen Atoms in Solution with Internal Defects.	138
4.5.1	Density of Site Energies (DOSE) and Fermi–Dirac Statistics	139
4.5.2	Interaction of Hydrogen with Dislocations: DOSE Method	142
4.5.3	Formation of Hydrides at Dislocations: Thermodynamic Method	148
	References	151
5	Diffusion of Hydrogen.	153
5.1	Phenomenological Flux Equations	153
5.2	Diffusivity—Theory	158
5.3	Diffusivity in Dilute Phase—Results.	162
5.4	Thermal Diffusion—Results.	172
	References	173

6	Characteristics of the Solvus	175
6.1	Introduction	175
6.2	General Considerations Concerning Hysteresis in Phase Transformations.	177
6.3	Theories of Solvus Hysteresis Based on Accommodation Energy	189
	References	203
7	Theories of Coherent Phase Equilibrium	207
7.1	General Features.	207
7.2	Polymorphic Phase Transformation.	210
7.3	Isomorphic Phase Transformation.	219
7.4	Stability Conditions and Path Dependences for Coherent Phase Transformations	229
7.4.1	Stability Conditions for Closed Polymorphic Systems	230
7.4.2	Stability Conditions for Open Isomorphic Systems	235
	References	241
8	Experimental Results and Theoretical Interpretations of Solvus Relationships in the Zr–H System.	243
8.1	Introduction	243
8.2	Application of Coherent Phase Stability Analysis to the Zr–H System	244
8.3	Evaluation of Models of Hysteresis for the Zr–H System	249
8.4	Summary of Results of Experimental Solvus Determinations.	253
8.4.1	Effect of Experimental Methods	254
8.4.2	Differences Between Solvi in α and α/β Zr Materials: Effect of β -Zr Phase	269
8.4.3	Effect of Cold Work and Irradiation	272
8.4.4	Combined Effect of Thermal Aging and Irradiation in Zr–2.5Nb	278
8.4.5	Effect of Manufacturing Variables, Microstructure, and/or Composition.	281
	References	286
9	Fracture Strength of Embedded Hydride Precipitates in Zirconium and its Alloys	291
9.1	Introduction	291
9.2	Early Work	292
9.3	Fracture Strength of Radial Hydrides: Rising Load Tensile Tests	294

9.4	Mechanism for Fracture of Embedded Radial Hydride Clusters in Rising Load Tests	296
9.5	Hydride Stress State Determinations in Tensile Tests Observed Under Synchrotron X-ray Irradiation	305
9.6	Fracture Strength of Radial Hydrides: Constant Load Tests	318
9.7	Comparison of Rising Load and Constant Load Hydride Fracture Strength Results	326
	References	328
10	Delayed Hydride Cracking: Theory and Experiment	333
10.1	Introduction	333
10.2	Historical Overview	334
10.3	General Features of DHC	336
10.4	Theory of DHC Growth Rate.	346
10.4.1	Test Temperature Approached from Below	354
10.4.2	Test Temperature Approached from Above	354
10.4.3	Dependence on Direction of Approach to Temperature.	355
10.4.4	Dependence on K_I and Activation Energy	355
10.4.5	Dependence on Yield Strength	356
10.4.6	Dependence on Total Hydrogen Content	357
10.5	General Theory of K_{IH}	358
10.5.1	Introduction	358
10.5.2	Fracture Condition of Crack Tip Hydrided Region: K_I Versus L_c Relationship	358
10.5.3	Limiting Values of L_c and K_{IH}	362
10.5.4	K_I Versus L_c Relationship: Characteristics and Comparison with Experimental Data.	369
10.5.5	Comparison of K_I Versus L_c Relationships from Different Models.	373
10.5.6	Limits to Crack Tip Hydrided Region Growth	380
10.5.7	Summary of General Limiting Conditions for DHC Initiation at Cracks	381
10.6	Analysis of Some Limiting Conditions for DHC	383
10.6.1	Introduction	383
10.6.2	High Temperature DHC Limit: Experimental Results.	384
10.6.3	High Temperature DHC Limit: Theoretical Analysis	385
10.6.4	DHC Arrest Temperature: Test Temperature Approached from Below	394
10.6.5	DHC Limiting Conditions: Summary Discussion and Conclusions	401
	References	403

11 DHC Initiation at Volumetric Flaws	409
11.1 Introduction	409
11.2 Early Models of Blunt Flaw Assessment	410
11.3 Hydride Process Zone Approach to Volumetric Flaw Assessment: General Considerations	412
11.4 Hydride Process Zone Model: Closed Form Solution	418
11.5 Hydride Process Zone Model: Effect of Flaw Tip Plasticity	421
11.6 Engineering Process Zone Model	424
11.7 Validation of the Engineering Process Zone Model	428
11.7.1 Flaw Shape	428
11.7.2 Flaw Root Radius	428
11.7.3 Flaws with Depth Greater than 1 mm	428
11.7.4 Flaw Surface Roughness and Secondary Flaw Significance	429
11.7.5 Use of Flaw Tip Plasticity and Creep in the Engineering Process Zone Model Application	431
11.7.6 Accuracy of the Cubic Polynomial Expression in the Engineering Process Zone Model Application	431
11.7.7 Scatter and Material Variability	432
11.7.8 Hydrogen Isotope Content and Number of Reactor Cooldown/Heatup Cycles	432
11.7.9 Above Threshold Conditions	433
11.7.10 Effect of Irradiation	433
11.7.11 Cyclic Loading and Overload Conditions	434
References	434
12 Applications to CANDU Reactors	437
12.1 Introduction	437
12.2 Overview of Assessment Approach	439
12.2.1 DHC Initiation at Planar Flaws: K_{IH}	439
12.2.2 DHC Initiation at Volumetric Flaws: TSSD	441
12.2.3 Planar Flaw Growth to the End of an Assessment Period: DHC Growth Rate	443
12.2.4 Reactor Core Assessment: Leak Before Break Analysis	445
References	450

<http://www.springer.com/978-1-4471-4194-5>

The Effect of Hydrogen and Hydrides on the Integrity of
Zirconium Alloy Components

Delayed Hydride Cracking

Puls, M.P.

2012, XXXII, 452 p., Hardcover

ISBN: 978-1-4471-4194-5