

Contents

1	Introduction and Outline	1
1.1	Historical Background	1
1.1.1	X-Ray-Induced Photoelectron Spectroscopy (XPS)	2
1.1.2	Auger Electron Spectroscopy (AES)	3
1.2	Outline of Electron Spectroscopy	5
1.2.1	Outline of X-Ray Photoelectron Spectroscopy (XPS)	7
1.2.2	Outline of Auger Electron Spectroscopy (AES)	7
1.3	State of the Art and Future Development	8
	References.....	9
2	Instrumentation.....	11
2.1	Vacuum System	11
2.1.1	Basic Pressure Requirements	13
2.1.2	Attainment and Maintenance of Ultrahigh Vacuum (UHV)	15
2.2	X-Ray Source.....	18
2.2.1	Conventional X-Ray Source	18
2.2.2	Monochromatic X-Ray Source.....	19
2.2.3	Small-Spot X-Ray Source and Scanning XPS Microscopy	20
2.2.4	Synchrotron X-Ray Source.....	22
2.3	Electron Gun.....	23
2.4	Ion Gun	26
2.5	Electron Energy Analyzer	29
2.5.1	The Cylindrical Mirror Analyzer (CMA)	30
2.5.2	The Concentric Hemispherical Analyzer (CHA)	33
2.5.3	Multichannel Detection	36
2.5.4	Imaging XPS.....	37
2.6	Software	39
	References.....	40

3	Qualitative Analysis (Principle and Spectral Interpretation)	43
3.1	Introduction: Notation of Atomic Electron Levels	43
3.2	Qualitative XPS	43
3.2.1	Principle of XPS Analysis	43
3.2.2	Photoelectron Spectra: Elemental Identification	45
3.2.3	Chemical Shift of Photoelectron Peak Energy	48
3.2.4	Auger Parameter	49
3.2.5	Valence Band Spectra	52
3.2.6	Satellite Peaks	52
3.2.7	XPS Line Shapes	54
3.2.8	Emission Angle Effects	58
3.3	Qualitative AES	63
3.3.1	Principle of AES Analysis	63
3.3.2	Auger Spectra and Elemental Identification	64
3.3.3	Direct and Derivative Spectra	66
3.3.4	Recognition and Influence of Chemical Bonding	68
3.3.5	Electron Backscattering, Channeling, and Diffraction ...	71
	References	74
4	Quantitative Analysis (Data Evaluation)	77
4.1	Measurement and Determination of Intensities	77
4.1.1	Background Subtraction	79
4.1.2	Differential (Derivative) Spectra (APPH in AES)	81
4.1.3	Decomposition of Overlapping Peaks	83
4.1.4	Factor Analysis and Principal Component Analysis	83
4.2	Quantification Using Intensities	84
4.2.1	Quantification Principles Using Elemental Relative Sensitivity Factors (E-RSFs)	84
4.2.2	Key Parameters: Inelastic Mean Free Path (IMFP) and Effective Attenuation Length (EAL)	87
4.3	Quantitative XPS	104
4.3.1	Fundamental Quantities for XPS	104
4.3.2	Quantitative XPS Analysis of Homogeneous Material ...	109
4.3.3	Quantitative XPS Analysis of Thin Surface Layers	135
4.4	Quantitative AES	172
4.4.1	Fundamental Quantities for AES	172
4.4.2	Quantitative AES Analysis of Homogeneous Material ...	179
4.4.3	Quantitative AES Analysis of Thin Surface Layers	189
4.5	Summary and Conclusion	200
	References	201
5	Optimizing Measured Signal Intensity: Emission Angle, Incidence Angle and Surface Roughness	205
5.1	XPS: Intensity Dependence on Emission and Incidence Angles...	205
5.1.1	Sample Tilt Using CHA	208
5.1.2	Double-Pass Cylindrical Mirror Analyzer (DP-CMA) and Thetaprobe (CHA)	209

5.1.3	Total Reflection XPS (TR-XPS)	213
5.1.4	XPS Intensity Dependence on Surface Roughness	214
5.2	AES: Intensity Dependence on Emission and Incidence Angles ..	227
5.2.1	Sample Tilt Using CHA for AES	227
5.2.2	Sample Tilt Using CMA	235
5.2.3	AES Intensity Dependence on Surface Roughness	239
5.3	Summary and Conclusion.....	255
	References.....	256
6	Optimizing Certainty and the Detection Limit:	
	Signal-to-Noise Ratio	259
6.1	Introduction and Definitions for Pulse-Counting Systems	259
6.1.1	Definitions and Explanations	260
6.1.2	Role of Peak-to-Background (<i>P/B</i>) Ratio	263
6.2	Parameters Affecting <i>P/B</i> and Singal-to-Noise (<i>S/N</i>) Ratios.....	266
6.2.1	Emission and Incidence Angle Dependencies of <i>P/B</i> and <i>S/N</i> for XPS and AES.....	266
6.2.2	Analyzer Resolution	270
6.2.3	Surface Roughness	275
6.2.4	Detector Efficiency and Scattered Electrons	275
6.2.5	Excitation Intensity (Primary Beam Current) and Total Measurement Time per Channel	275
6.2.6	Detection Limit	279
6.2.7	<i>S/N</i> Ratio and Uncertainty in Peak Measurements.....	281
6.2.8	<i>S/N</i> in Multichannel Detection.....	286
6.2.9	Uncertainty in Quantified Data and Strategy for Data Acquisition	289
6.3	<i>S/N</i> Ratio for Analog Systems	293
	References.....	295
7	Quantitative Compositional Depth Profiling	297
7.1	Sputter Depth Profiling	298
7.1.1	Instrumentation and Experimental Setup	298
7.1.2	Basic Quantification of Composition and Sputtered Depth	302
7.1.3	Depth Resolution: Definition and Measurement	314
7.1.4	Factors Limiting Depth Resolution and Profile Accuracy	319
7.1.5	Depth Dependence of Depth Resolution: Superposition of Different Contributions.....	338
7.1.6	Optimized Depth Profiling Conditions	339
7.1.7	Modeling, Deconvolution, and Reconstruction of Depth Profiles	344
7.1.8	The MRI Model and Its Modifications	348
7.1.9	Special Sputter Depth Profiling Techniques.....	371

7.2	Nondestructive Depth Profiling	382
7.2.1	Angle-Resolved XPS and AES	382
7.2.2	Depth Profiling by Variation of the Excitation Energy ...	398
7.2.3	Depth Profiling Using Background Information (Peak-Shape Analysis)	400
7.3	Conclusion: Comparison of Nondestructive and Destructive Depth Profiling Methods	402
	References	402
8	Practice of Surface and Interface Analysis with AES and XPS	409
8.1	Analytical Strategy	409
8.2	Sample Properties	411
8.2.1	Type of Material	411
8.2.2	Size, Shape, Morphology, and Roughness	412
8.2.3	Inhomogeneous Structure and Composition	412
8.2.4	Electrical Conductivity	413
8.2.5	Likelihood of Electron- or Photon-Beam- Induced Damage	413
8.3	Sample Preparation	414
8.3.1	Outside (“ <i>Ex Situ</i> ”) Preparation	414
8.3.2	Inside (“ <i>In Situ</i> ”) Preparation	417
8.4	Setting Up the Instrument and Measurement	420
8.4.1	Calibration of the Energy and Intensity Scales	420
8.4.2	Mounting and Alignment of the Sample	422
8.4.3	Measurement Sequence	423
8.5	AES and XPS on Insulators	424
8.5.1	Charging and Charge Compensation in XPS	424
8.5.2	Charging and Charge Compensation in AES	426
8.6	Electron and Photon-Beam Damage During AES and XPS Analyses	434
8.6.1	AES: Electron Beam Stimulated Changes in Composition and Structure	435
8.6.2	XPS: X-Ray-Induced Changes in Composition	441
	References	446
9	Typical Applications of AES and XPS	451
9.1	<i>Ex Situ</i> Sample Preparation	451
9.1.1	Coatings and Layered Structures	452
9.1.2	Corrosion and High-Temperature Oxidation	454
9.1.3	Interfacial Reactions and Diffusion	460
9.1.4	Interfacial Segregation	460
9.1.5	Implantation Layers	465
9.1.6	Further Methods and Materials	468
9.2	<i>In Situ</i> Sample Preparation	469
9.2.1	Surface Layer Formation by Deposition	469
9.2.2	Early Stages of Oxidation	471

9.2.3	Altered Layers by Ion Bombardment	476
9.2.4	Deposited Layer Structure	479
9.2.5	Surface Segregation	479
9.3	Treatment of AES and XPS Data by Factor Analysis	481
	References	482
10	Surface Analysis Techniques Related to AES and XPS	487
10.1	Overview of Surface Analysis Methods	487
10.2	Photon-Beam Excitation	488
10.2.1	Detection of Photons	488
10.2.2	Detection of Electrons	489
10.2.3	Detection of Ions and Neutral Particles	490
10.3	Electron-Beam Excitation	491
10.3.1	Detection of Photons	491
10.3.2	Detection of Electrons	491
10.3.3	Detection of Ions and Neutrals	494
10.4	Ion-Beam Excitation	494
10.4.1	Detection of Photons	494
10.4.2	Detection of Electrons	495
10.4.3	Detection of Ions and Neutrals	495
10.5	Excitation by Electric Field or Heat	497
10.5.1	Detection of Photons	497
10.5.2	Detection of Electrons	497
10.5.3	Detection of Ions and Neutral Particles	498
10.5.4	Detection of Forces	498
10.6	Comparison of the Principal Surface Chemical Analysis Techniques	499
10.6.1	Main Features of AES, XPS, SIMS and ISS	499
10.6.2	Combination of Techniques	501
	References	501
Index		505

Auger- and X-Ray Photoelectron Spectroscopy in
Materials Science

A User-Oriented Guide

Hofmann, S.

2013, XX, 528 p., Hardcover

ISBN: 978-3-642-27380-3