
Contents

Part I Looking at Images

1 Images and Microstructures	3
1.1 Images and Microstructures	3
1.2 Image Analysis	6
1.2.1 Direct Image Analysis	8
1.2.2 Analysis of Image Segments	9
1.2.3 Analysis of Best-fit Ellipses	10
1.2.4 Analysis of Digitized Outlines	10
1.3 Segmentation	11
1.4 Image Models	12
2 Acquiring Images	15
2.1 Photography	15
2.1.1 Field Photography	15
2.1.2 Photomacrography	17
2.2 Optical Scanners	19
2.3 Light Microscopy	19
2.3.1 Modes of Polarization Microscopy	19
2.3.2 Illumination	23
2.3.3 Magnification and Resolution	24
2.4 Digital Cameras	27
2.5 Electron Microscopy	29
2.5.1 Scanning Electron Microscopy (SEM)	29
2.5.2 Transmission Electron Microscopy (TEM)	30
References	30
3 Digital Image Processing	31
3.1 The Digital Image	31
3.1.1 Bit and Bytes	31
3.1.2 Gray Values	33
3.1.3 Color	33
3.2 Stacks	36
3.2.1 R-G-B Stacks	36
3.2.2 X-Y-Z Stacks	37
3.2.3 X-Y-t Stacks	37
3.2.4 X-Y- α Stacks	39
3.3 Format and Compression	39

3.4	Image SXM	42
3.4.1	Quick Start	43
3.4.2	LUT Window	43
3.4.3	Map Window	44
3.4.4	Info Window	44
3.4.5	Tools	45
3.5	Preparing the Data	49
3.5.1	Exploring the Image	49
3.5.2	Scale and Calibrate	50
3.5.3	Using Color	51
3.5.4	Presenting the Data: The Beauty Case	53
	References	56
4	Pre-processing	59
4.1	Comparing Images	59
4.2	Background Corrections	60
4.2.1	Direct Background Correction	61
4.2.2	Background Correction Using a Model Background	64
4.2.3	Background Correction Using a Background Image	64
4.3	Re-sizing	67
4.3.1	Nearest Neighbor	67
4.3.2	Bilinear	68
4.3.3	Bicubic	68
4.4	Noise Removal	72
4.4.1	Median Filtering	72
4.4.2	Fourier Filtering	73
	References	73
Part II Segmentation: Finding and Defining the Object		
5	Segmentation by Point Operations	77
5.1	Look-Up Tables	77
5.1.1	Changing the Contrast: Linear LUTs	77
5.1.2	Non-linear LUTs	78
5.1.3	Special LUTs	78
5.2	Macros	78
5.2.1	Using Macros	78
5.2.2	Lazy LUTs Macro	80
5.2.3	From LUT to Point Operation	86
5.3	Segmentation by Point Operations	88
5.3.1	Segmentation by Thresholding	90
5.3.2	Segmentation by Gray Level Slicing	90
	References	94
6	Post-processing	95
6.1	Ranking Filters	95
6.1.1	Minimum: Median: Maximum	95
6.1.2	Erosion: Dilation	97
6.1.3	Opening: Closing	99

6.2	Copy Modes	100
6.2.1	Logical Operations	100
6.2.2	Combining Images	100
6.3	Structural Filtering	102
6.3.1	Skeletonization	102
6.3.2	Pruning	103
6.3.3	Watershed	103
6.4	Cleaning Up Bitmaps	104
6.5	Phases, Grains and Boundaries	106
	References	111
7	Segmentation by Neighborhood Operations	113
7.1	Neighborhood	113
7.2	Averaging Filters	114
7.2.1	Gauss Filters	116
7.2.2	Influence of Shape and Size	118
7.3	Gradient Filters	119
7.3.1	Roberts Cross	123
7.3.2	Sobel Edge Detection	126
7.3.3	Laplace Filters	128
7.4	Edge Detection	130
	References	135
8	Image Analysis	137
8.1	Image Segments and Best-Fit Ellipses	137
8.2	Deriving Size and Shape Descriptors	140
8.3	Example of Image Analysis	142
8.4	Digitizing Outlines	144
8.4.1	Exporting Segment Boundaries	146
8.4.2	Creating Polygonal Chains	147
8.4.3	The Nature of the Square Grid	149
8.4.4	From Discrete to Continuous	151
8.5	SCASMO	151
8.5.1	How to Run SCASMO	152
8.6	The FABRIC Programs	156
	References	156
9	Test Images	157
9.1	Numerical Simulations	157
9.1.1	Ellipses	157
9.1.2	Shape and Orientation Distributions	158
9.1.3	Spatial Distributions	161
9.2	Synthetic Particle Fabrics	161
9.3	RANDOM	163
9.3.1	How to Run RANDOM	164
9.4	MONTECARLO	166
9.4.1	Random Sampling	167
9.4.2	How to Run MONTECARLO	169
	References	170

Part III Measuring Size and Volume

10	Volume Determinations	173
10.1	Measuring Area Fractions	173
10.1.1	Measuring Areas in Image SXM	174
10.1.2	Counting Pixels	175
10.1.3	Estimating Areas	177
10.2	Estimating Volume Fractions	177
10.3	Determining Errors	179
10.3.1	Errors Associated with Point Counting	179
10.3.2	Errors Associated with Area Measurements	180
10.4	Practical Application	180
10.5	Surface Fractions	182
	References	185
11	2-D Grain Size Distributions	187
11.1	Measures for Grain Size	187
11.2	Mean Grain Size	192
11.3	Grain Size Distribution	194
11.4	Grain Size Mapping	196
	References	199
12	3-D Grain Size	201
12.1	Random Sectioning of a Single Sphere	201
12.2	From 3-D Spheres to 2-D Sections	205
12.2.1	The Stereological Model	205
12.2.2	Four Typical Distributions	207
12.3	From 2-D Sections to 3-D Spheres	207
12.4	STRIPSTAR	213
12.4.1	How to Run STRIPSTAR	214
12.5	Practical Applications	215
12.5.1	Particles in a Matrix	216
12.5.2	Crystalline Aggregates	217
12.5.3	Shortcuts	219
12.5.4	The Influence of Shape: How Random is Random?	221
12.5.5	Error Estimation	222
12.5.6	Phi-Values and Logarithmic Binning	222
	References	224
13	Fractal Grain Size Distributions	225
13.1	Fragmentation in Nature and Experiment	225
13.2	Fragmenting the Cube	227
13.2.1	The Fractal Model for Sectioning	228
13.2.2	Fractal Dimensions	229
13.2.3	Fragmentation Numbers $F > 8$ or $F < 8$	231
13.2.4	Continuous Fragmentation	232
13.3	Fragmentation Matrix	233
13.3.1	Deriving the Fractal Dimension from the Matrix	234
13.3.2	Fractal Dimension from the Matrix and from Grain Size Analysis	239

13.4	Visualizing Grain Size Distributions	241
13.4.1	Preparing the Bitmap	242
13.4.2	Gauss Filtering	243
13.4.3	Converting the Matrix to the Fractal Dimension	245
13.5	Examples	249
	References	249

Part IV Quantifying Shape and Orientation

14	Particle Fabrics	253
14.1	Projections of a Single Ellipse	254
14.2	Projections of Non-elliptical Shapes	255
14.3	Best-Fit Ellipses and Convex Hulls	256
14.4	Projections of Sets of Ellipses	261
14.5	PAROR	263
14.5.1	How to Run PAROR	264
14.5.2	The Monitor Printout File	265
14.5.3	The B(α) File	268
14.5.4	The Axes Orientation File	269
14.5.5	The Particle Data File	270
14.6	PAROR Analysis of Particles in a Matrix	270
14.7	PAROR Analysis of Crystalline Aggregates	272
14.8	PAROR Analysis of Surfaces	274
14.9	Restoring the Input	276
14.10	PAROR Analysis Within Image SXM	279
	References	280
15	Surface Fabrics	283
15.1	Projection of Line Segments	283
15.2	Straight Line Segments	284
15.3	SURFOR	285
15.3.1	How to Run SURFOR	287
15.3.2	The Monitor Printout File	287
15.3.3	The A(α) File	289
15.3.4	The Surface Orientation File	289
15.3.5	The Characteristic Shape File	289
15.4	SURFOR Analysis of Lines Segments	289
15.5	SURFOR Analysis of Closed Outlines	293
15.6	SURFOR Versus PAROR Analysis	294
15.7	SURFOR Analysis of Incomplete Outlines	297
15.8	SURFOR Analysis of Open Lines	298
15.9	SURFOR Analysis Within Image SXM	301
	References	303
16	Strain Fabrics	305
16.1	Fabrics and Strain	305
16.1.1	Strain Markers	305
16.1.2	The Geometry of Strain	306
16.2	Measuring Strain with SURFOR	308
16.3	Testing for Strain	312

16.4	Practical Examples	314
16.5	SURFOR and PAROR Versus the R_f - ϕ Method	317
	References	320
17	Shape Descriptors	323
17.1	Shape Descriptors	323
17.1.1	Deviation from the Circular Form: Classical Shape Factors	324
17.1.2	Aspect Ratios	326
17.1.3	Convexity: Concavity	328
17.1.4	Excess Perimeter and Defect Area	329
17.1.5	Angularity	331
17.2	iSHAPES	335
17.2.1	How to Run iSHAPES	335
17.3	Manual and Automatic Digitization	337
17.4	Applications of iSHAPES	339
17.4.1	Fault Rock Microstructures	339
17.4.2	Grain Boundary Migration Microstructures	342
17.4.3	Annealing Microstructures	344
	References	347
Part V Spatial Relationships		
18	Spatial Distributions	351
18.1	Basic Concepts	351
18.1.1	Spatial Distributions	352
18.1.2	Random Mixing	354
18.1.3	Volume Model and Surface Model	356
18.2	What to Measure	356
18.3	Test Samples	357
18.4	Analysis of a Polyphase Material	359
18.4.1	Focusing on One Phase	361
18.4.2	Selecting Two Phases	363
18.5	Errors	365
18.6	Orientation Dependent Analysis	366
	References	368
19	Spatial Frequencies	369
19.1	Spatial Frequencies	369
19.2	Fourier Transforms	372
19.2.1	One-Dimensional Fourier Transform	372
19.2.2	Two-Dimensional Fourier Transform	373
19.2.3	Discrete Fourier Transforms	373
19.2.4	Fast Fourier Transform	375
19.3	Interpreting Fourier Transform Images	376
19.4	Frequency Filtering	377
19.4.1	Selecting Frequencies	378
19.4.2	High-Pass and Low-Pass Filtering	379
19.5	Practical Applications	385
	References	388

20	Autocorrelation Function	389
20.1	Principles of Autocorrelation	389
20.1.1	Mathematical Definition	390
20.1.2	Autocorrelation Function of Single Shapes . . .	391
20.1.3	Autocorrelation Function of Sets of Shapes . . .	392
20.2	Analysis of Autocorrelation Functions	397
20.3	Practical Applications of Autocorrelation Functions . . .	398
20.3.1	Lazy ACF Tiling Macro	400
20.3.2	Bulk ACF	402
20.3.3	Local ACFs	403
20.4	Autocorrelation Functions and Strain Analysis	405
20.4.1	Heterogeneous Strain	405
20.4.2	Autocorrelation of Center Points	407
20.4.3	Deformation and Reaction	408
	References	409
Part VI Orientation Imaging		
21	Crystal Orientation and Interference Color	413
21.1	Basic Concepts	414
21.2	Interference Colors	417
21.2.1	Birefringence	417
21.2.2	Optical Path	418
21.2.3	Spectra of Interference Colors	419
21.2.4	Color from Spectra	421
21.2.5	First-Order Colors and Section Thickness	421
21.2.6	Adding the Wave Plate	422
21.3	The Crystallographic Color Space	425
21.3.1	Polstacks	426
21.3.2	Polstack Sections	426
21.4	Color to Monochrome	428
21.4.1	Finding the Best Filter	429
21.4.2	Resolving the Azimuth	431
21.4.3	Resolving the Inclination	433
21.5	LUTs for CIP	437
21.5.1	Converting Intensity to Inclination	437
	References	438
22	Computer-Integrated Polarization Microscopy	439
22.1	How CIP Works: The Basic Idea	441
22.2	Acquire the Input	443
22.2.1	The Structure of the Input Stack	444
22.2.2	The Micrographs	445
22.2.3	Circular Polarization	450
22.3	Prepare the Input Stack	451
22.4	Pre-process the Input Stack	456
22.4.1	Calibration Files	456
22.4.2	Image Calibration	457
22.4.3	Lighting and Background Corrections	457
22.4.4	Section Thickness	457

22.5	Do the CIP	460
22.6	Viewing the Result	467
22.7	Pole Figures	469
22.8	Refining the Calculation	469
	References	475
23	Orientation and Misorientation Imaging	477
23.1	Orientation Imaging: Changing the Colors	477
23.2	Using EBSD Input	480
23.2.1	Full Texture Versus c-Axis	480
23.2.2	Euler Angles to c-Axes	480
23.3	Masking	481
23.3.1	Selecting Regions	481
23.3.2	Selecting Minerals	487
23.4	Misorientation Imaging	487
23.4.1	Principal Misorientations	488
23.4.2	Misorientation with Respect to Reference Direction	488
23.4.3	From Misorientation to Orientation	488
23.4.4	Misorientation Profiles	490
23.5	Segmentation in Orientation Space	493
23.5.1	Grain Boundaries and Sub-grain Boundaries	494
23.5.2	Flat Grains	497
23.6	Orientation Tracking	497
23.6.1	Texture Domains	498
23.6.2	Texture Domains of a Low-Strain Sample	498
23.6.3	Texture Domains of a High-Strain Sample	501
23.6.4	Domain Grain Size	503
23.7	Orientation Gradient Imaging	506
23.7.1	Orientation Gradients	506
23.7.2	Orientation Gradient Density	506
23.7.3	Sharp Boundaries	507
23.8	Texture-Dependent Shape Analysis	509
	References	512
	Index	515



<http://www.springer.com/978-3-642-10342-1>

Image Analysis in Earth Sciences
Microstructures and Textures of Earth Materials
Heilbronner, R.; Barrett, S.
2014, XIX, 520 p. 596 illus., 257 illus. in color.,
Hardcover
ISBN: 978-3-642-10342-1