

Contents

1	Introduction	1
1.1	Quartz Crystal Resonators	1
1.2	Piezoelectric Resonators in Time and Frequency Control	3
1.3	The Quartz Crystal Microbalance	5
1.4	Operation in the Liquid Phase, Surface Specificity	9
1.5	A Quick Tour Through Modeling	12
1.5.1	Resonances, Resonators, and the Small Load Approximation	12
1.5.2	Wave Equation and Continuity at Interfaces	15
1.5.3	The QCM as an Acoustic Reflectometer	16
1.5.4	Equivalent Circuits	16
1.5.5	Influences of the Electrical Boundary Conditions	17
1.5.6	Tensor Form of the Small Load Approximation, Third-Order-Perturbation	17
1.5.7	Beyond the Parallel-Plate Model	17
1.6	Related Instruments, Combined Instruments	18
1.7	Overview of Applications	18
	References	20
2	Methods of Read-Out	23
2.1	Oscillator Circuits	23
2.2	Impedance Analysis	25
2.3	Ring-Down	27
	References	30
3	Essentials of Viscoelasticity	33
3.1	General	33
3.2	Linearity	34
3.3	Spatial Homogeneity	34
3.4	Isotropy	35
3.5	Incompressibility	35
3.6	Time-Domain Experiments	35
3.7	Frequency-Domain Experiments, Viscoelastic Dispersion	38
	References	46

4	Modeling the Resonator as a Parallel Plate	49
4.1	Description of Oscillations with Complex Numbers	49
4.1.1	Euler’s Relation and Complex Amplitudes.	49
4.1.2	Sign Conventions	50
4.1.3	Complex Resonance Frequencies	52
4.1.4	Parameters Quantifying Damping	60
4.2	Acoustic Impedance, Acoustic Wave Impedance, and Acoustic Reflectivity.	61
4.3	Acoustic Plane Wave Model: Mathematical Form	69
4.4	Acoustic Plane Wave Model: Description in Terms of Acoustic Reflectivity.	74
4.5	Equivalent Electrical Circuits	79
4.5.1	The Piezoelectric Transducer	81
4.5.2	The Piezoelectric Resonator	83
4.5.3	The Four-Element Circuit	87
4.5.4	The Admittance Circle and the Series Resonance Frequency	95
4.6	The Small Load Approximation	98
4.6.1	Derivation of the Small Load Approximation from the Four-Element Circuit	98
4.6.2	Area-Averaging, Time-Averaging, and Averaging over Displacement	101
4.6.3	Coupled Resonances	102
4.7	Appendices	109
4.7.1	Broadening of a Resonance Curve by Damping	109
4.7.2	Kirchhoff Rules	109
4.7.3	The Electromechanical Analogy	110
4.7.4	Derivation of the Mason Circuit	113
	References	122
5	Piezoelectric Stiffening	125
5.1	General	125
5.2	Formal Structure of the Piezoelectric Equations	127
5.3	Piezoelectric Stiffening of the Parallel-Plate.	130
5.3.1	Open-Circuit Condition	132
5.3.2	Short-Circuited Electrodes	133
5.3.3	Finite Electrical Impedance Between Electrodes.	135
5.4	Appendix: Voigt Notation	138
	References	141

6	The Small Load Approximation Revisited	143
6.1	Small Load Approximation in Tensor Form	143
6.1.1	Derivation	143
6.1.2	Parallel Plate	148
6.1.3	Parallel Plate with Energy Trapping	148
6.1.4	The Modal Mass and Limits of the Sauerbrey Equation	151
6.1.5	Statistical Weight in Area Averaging	152
6.1.6	Parallel Plate with Surface Roughness.	152
6.1.7	Piezoelectric Stiffening	153
6.1.8	Appendix: Self-Adjointness of the Unperturbed ω^2 -Operator	155
6.2	Third-Order Perturbation Analysis	158
	References	167
7	Energy Trapping and Its Consequences.	169
7.1	General	169
7.2	Anharmonic Sidebands	174
7.3	Amplitude Distributions.	175
7.4	Amplitude of Oscillation and Effective Area	176
7.5	Activity Dips	180
7.6	Flexural Deformations, Compressional Waves	181
7.7	Energy Trapping Increases the Resonance Frequency	183
7.8	Modeling Resonators in 3D	184
	References	188
8	Gravimetric Sensing.	191
8.1	The Sauerbrey Equation and Its Implications	191
8.2	Receptor Layers	196
8.3	Remarks on Gravimetric Sensing in the Liquid Phase	198
	References	201
9	Homogeneous Semi-infinite Samples	205
9.1	Newtonian Liquids	205
9.2	Nematic Liquid Crystals	208
9.3	Colloidal Dispersions	211
9.4	Elastomers Contacting the Resonator in the Center only	213
9.5	Solid-Liquid Interfaces with Shallow Roughness	214
	References	218
10	Stratified Layer Systems	221
10.1	Viscoelastic Film in Air	221
10.2	Viscoelastic Film in a Liquid	229
10.3	Equivalent Mass and Equivalent Thickness	232

10.4	Determination of Viscoelastic Constants	233
10.5	The $\Delta\Gamma/\Delta f$ -Ratio and a Film's Elastic Compliance	234
10.6	Multilayers and Continuous Viscoelastic Profiles	236
10.7	Slip	238
10.8	Appendix: Modeling Viscoelastic Profiles Using the Wave Equation	240
	References	244
11	Point Contacts and Contact Stiffness	247
11.1	General	247
11.2	Some Element of Contact Mechanics	249
11.3	Large Particles	254
11.4	Contacts with Particles of Intermediate Size	258
11.5	Coupled Resonances and Shear-Wave Spectroscopy	265
	11.5.1 Finite Element Simulations, Multiple Modes	267
	11.5.2 Vibrational Spectroscopy on Surface-Attached Colloids	269
	11.5.3 Heterogeneous Broadening, Oscillator Strength	272
11.6	Particles Coupled to the Resonator Surface Across a Dashpot	274
11.7	Point Contacts as Centers of Acoustic Scattering	275
11.8	Contact Stiffness of Rough Interfaces	278
	References	283
12	Heterogeneous Samples	287
12.1	Laterally Heterogeneous Interfaces	287
12.2	Numerical Computation of Area-Averaged Stress	288
12.3	$\Delta\Gamma/\Delta f$ -Extrapolation Scheme	297
12.4	Droplets and Bubbles	298
12.5	Vesicles and Supported Lipid Bilayers	303
12.6	Biological Cells	306
	References	309
13	Nonlinear Interactions	313
13.1	General	313
13.2	Steady Streaming	315
13.3	Amplitude Dependence of Δf and $\Delta\Gamma$	319
13.4	Third-Harmonic Generation	331
13.5	Appendix: Determination of the Shear Direction with Polarizing Microscopy	331
	References	335

14	Practical Consequences of Piezoelectric Stiffening	337
14.1	Application of Piezoelectric Stiffening for Sensing	337
14.2	Safeguards Against Electrical Artifacts	339
	References	341
15	Other Surface-Acoustic-Wave Based Instruments	343
15.1	Shear-Wave Reflectometers	343
15.2	The High Overtone Bulk Acoustic Wave Resonator	344
15.3	Resonators Operating in the kHz Range	346
15.4	Instruments Based on Guided Waves	347
15.5	MEMS and NEMS Resonators	349
15.6	The FBAR as a Sensor	350
15.7	Novel Resonator Materials	351
15.8	Smaller and Better?	352
	References	354
16	Combined Instruments	359
16.1	Electrochemical QCM	359
16.2	Optical Reflectometry	361
16.3	QCM/AFM Combination	368
16.4	Combination with the Surface Forces Apparatus	369
16.5	Combination with the JKR Apparatus	370
16.6	Combination with Optical Instrumentation	370
16.7	Combination with Calorimetry	371
16.8	A Magnetic QCM	371
16.9	Combination with Various Forms of Electrical Spectroscopy	371
	References	373
17	Considerations for Well-Controlled QCM Experiments	377
17.1	Temperature-Frequency Coupling	377
17.2	Effects of Pressure and Static Stress	379
17.3	Drive Level Dependence	379
17.4	Compressional Waves	380
17.5	Front Electrode Grounded	381
17.6	Baseline Stability	381
17.7	The 01-Mode Must Be Well Separated from the Anharmonic Side Bands	382
17.8	Check for Electrical Contact by Calculating the Effective Area	382
17.9	Bandwidth Can Be More Robust than Frequency	382
17.10	Do not Use Frequency Shifts from the Fundamental in an Analysis of Overtone Dependence	383

17.11	When Doing Impedance Analysis, Be Aware of the Fact that the Sweep Rate Affects the Values on the Admittance Trace	383
17.12	When Comparing Overtones, Be Aware of the Fact that the Data at the Different Overtones Are Acquired at Different Times	383
17.13	When Analyzing the Overtone Dependence of Frequency Shifts Acquired on Samples in the Dry State, Be Aware of the Electrode Effects	383
17.14	Re-use of Crystals, Cleaning, Maintenance of Holder	384
	References	385
	Collection of Essential Equations	387

The Quartz Crystal Microbalance in Soft Matter
Research

Fundamentals and Modeling

Johannsmann, D.

2015, XX, 387 p. 123 illus., 9 illus. in color., Hardcover

ISBN: 978-3-319-07835-9