

Contents

1	Overview of Reliability Design	1
1.1	Design and Development of Electronic Equipment	1
1.2	Engineering Reliability in Design and Development	2
1.2.1	Reliability Techniques for Design Process	2
1.2.2	Reliability Techniques for Development Process	3
1.3	Computerized System for Reliability Design	4
2	Generic Stress Factors and De-rating	7
2.1	Introduction	7
2.2	Ambient Temperature	7
2.3	Surface Temperature	8
2.4	Thermal Resistance	8
2.5	Junction Temperature	9
2.5.1	Computing Junction Temperature	10
2.6	Basics of De-rating	10
2.6.1	Need for De-rating	10
2.6.2	Examples of De-rating	11
	Assessment Exercises	12
	References	13
3	Selection and Application of Components	15
3.1	Basis of Selection	15
3.2	Reliability Needs of Components	15
3.2.1	De-rating for Stress Factors	16
3.2.2	Application of Components	17
3.3	Stress Factors and Application Information	18
3.3.1	Integrated Circuits	18
3.3.2	Discrete Semiconductor Devices	19
3.3.3	Resistors	20
3.3.4	Capacitors	21
3.3.5	Inductors and Transformers	22

3.3.6	Connectors	22
3.3.7	Switches	23
3.3.8	Relays	24
3.3.9	Fuses	26
3.3.10	Coaxial Cables and PCBs	27
	Assessment Exercises	27
	Research Assignments	28
	References	29
4	Failure Mode and Effects Analysis	31
4.1	Introduction	31
4.2	Significance of FMEA	31
4.3	Examples of FMEA in Design	32
4.4	Benefits of FMEA	32
4.5	Organizing FMEA	34
4.5.1	Planning in Design	34
4.5.2	Resources	34
4.5.3	Assigning FMEA	35
4.6	Terms in FMEA	35
4.6.1	Failure Mode	36
4.6.2	Failure Effect	37
4.6.3	Failure Cause	38
4.6.4	Preventive Actions	38
4.6.5	Characterizing Failure Mode	39
4.7	FMEA at Module Level	40
4.7.1	Interconnection FMEA	40
4.7.2	Library of Preventive Actions	41
4.7.3	Maintenance Flow Diagrams	42
4.8	FMEA at Component Level	43
	Assessment Exercises	43
	Research Assignments	44
	References	44
5	Overstress Analysis	45
5.1	Need for Overstress Analysis	45
5.2	Benefits of Overstress Analysis	45
5.3	Types of Overstress	46
5.3.1	Transient Electrical Overstress	46
5.3.2	Operating Electrical Overstress	47
5.3.3	Thermal Overstress	47
5.3.4	Vibration Resonance Overstress	48
5.4	Low Cost Methods for Overstress Analyses	49
5.4.1	Planning	49
5.4.2	Resources	50

5.5	Measuring Transient Electrical Overstress	51
5.5.1	Modules for Measuring Overstress	51
5.5.2	Measuring Transient Current	51
5.5.3	Measuring Transient Voltage	53
5.6	Measuring Operating Electrical Overstress	53
5.6.1	Practical Considerations	54
5.7	Measuring Thermal Overstress	54
5.7.1	Thermal Stress Analysis	54
5.7.2	Thermal Interaction Stress Analysis	56
5.8	Vibration Resonance Overstress Analysis	59
5.8.1	Vibration Fatigue-Related Defects	59
5.8.2	Vibration Fixture	59
5.8.3	Test Conditions	60
5.8.4	Defining Q-Resonance	62
5.8.5	Identifying Stressed Parts	62
5.8.6	Initiating Preventive Actions	63
	Assessment Exercises	63
	Laboratory Assignments	64
	References	64
6	Reliability Evaluation of Equipment	67
6.1	Definition of Reliability Evaluation	67
6.2	Reliability Evaluation Program	68
6.2.1	Objectives	68
6.2.2	Prerequisites	69
6.3	Internal Verification Testing	70
6.3.1	Types of Latent Design Errors	70
6.3.2	Preparing Internal Verification Test Plan	71
6.3.3	Reliability Improvement Tests	72
6.4	Performance Trend Analysis	73
6.4.1	Application Methodology	73
6.4.2	Example of Application	73
6.4.3	Trend Analysis for In-Circuit Parameters	74
6.5	Thermal Shock	74
6.5.1	Test Conditions	75
6.5.2	Temperature Range	76
6.5.3	Ramp Rate	76
6.5.4	Dwell Time and Number of Shocks	76
6.5.5	Loading PCBs in Test Chamber	77
6.6	Random Vibration	77
6.6.1	Characterization of Random Vibration	78
6.6.2	Test Conditions	78
6.6.3	Conducting Random Vibration Test	79

6.7	Accelerated Burn-in Test	79
6.7.1	Basic Requirements.	80
6.7.2	Usage On-Off Stressing	80
6.7.3	Test Temperature and Duration.	81
6.8	Cause Analysis and Corrective Actions	82
	Assessment Exercises.	82
	Research Assignments	83
	Laboratory Assignments	83
	References	83
7	Failure Data Management	85
7.1	Failure Data	85
7.1.1	Categories of Failure Data	85
7.1.2	Sources of Failure Data	86
7.2	Failure Data Management System	86
7.2.1	Administrative Requirements	87
7.2.2	Analysis of Failures	88
7.3	Cause Analysis on Component Failures	88
7.3.1	Flow Chart for Failure Analysis	89
7.3.2	Failure Confirmation	90
7.3.3	Technical Inputs	90
7.3.4	Brainstorming for Failure Causes	91
7.3.5	Practical Considerations.	91
7.4	Analysis of Failures Induced by Design Errors	92
7.5	Analysis of Failures Induced by Manufacturing Processes	93
7.5.1	Sources of Overstress	93
7.6	Confirming Defective Components	94
7.6.1	Military Standards for Electronic Components	94
7.6.2	Examination and Tests on Failed Components	94
7.6.3	Test Program for ICs and Semiconductor Devices	95
7.6.4	Test Program for Passive Components.	96
7.7	Corrective Actions and Reporting	96
	Assessment Exercises.	97
	Research Assignments	98
	References	98
8	Reliability Database System for Design	99
8.1	Reliability Database System	99
8.1.1	Capabilities	99
8.1.2	Design and Development	100
8.1.3	Practical Considerations.	100
8.2	Parts Database.	101
8.2.1	Data Elements for MOSFETs	102
8.2.2	Application of MOSFET Data Elements	102

8.2.3	Data Elements for Ceramic Chip Capacitors.	104
8.2.4	Application of Chip Capacitor Data Elements	105
8.3	Database for FMEA.	106
8.4	Database for Test Procedures	106
8.4.1	Database for High Temperature Test.	107
8.5	Database for Failure Analysis Reports	108
	Research Assignments	108
	References	108
9	Statistical Analysis of Field Failure Data	111
9.1	Introduction	111
9.2	Statistical Distributions.	111
9.2.1	Poisson Distribution	112
9.2.2	Exponential Distribution	112
9.2.3	Weibull Distribution	113
9.3	Population of Item and Its Characteristics.	114
9.3.1	Independent	114
9.3.2	Identically Distributed	114
9.4	Data Analysis Procedure	115
9.4.1	Define Field Replaceable PCBs	115
9.4.2	Obtain Time to Failure	115
9.4.3	Decide Statistical Distribution	116
9.4.4	Analyze Data	116
9.5	Poisson Process for Data Analysis.	117
9.5.1	Estimating Total Test Time	117
9.5.2	Computing Failure Rate.	118
9.6	Weibull Distribution for Data Analysis	119
9.6.1	Estimating Time to Failure.	120
9.6.2	Weibull Probability Plotting.	121
9.6.3	Estimating Weibull Parameters.	123
9.6.4	Weibull Probability Plotting Chart	124
9.6.5	Confidence Limits.	124
9.7	Exponential Distribution for Data Analysis.	128
9.7.1	Exponential Probability Plotting	129
9.7.2	Confidence Limits.	130
9.8	Spares Prediction.	131
9.8.1	Determining Quantity of Spares	131
	Assessment Exercises.	133
	References	134
	Appendix A: Reliability Testing for Non-standard Loads	135
	Appendix B: Reliability Growth Testing.	139

Appendix C: G_{rms} for Random Vibration Profiles	143
Answers to Quiz and Problems	147
Index	149

<http://www.springer.com/978-3-319-09110-5>

Reliable Design of Electronic Equipment

An Engineering Guide

NATARAJAN, D.

2015, XVII, 150 p. 48 illus., Hardcover

ISBN: 978-3-319-09110-5