

Contents

1	Introduction	1
	References	9
2	Measurement Uncertainty and Requirements of Production System. Selected Issues of Measurement Uncertainty Theory	15
2.1	Coordinate Measurement During Production Process	15
2.2	Measurement Uncertainty	19
2.3	Vector Concept of Describing Coordinate Measurement Accuracy: Measuring Point Reproducibility Error	28
2.4	Coordinate Measurement Uncertainty and Regulatory Requirements	40
	References	46
3	Classic (Nonsimulative) Methods of Measurement Accuracy Assessment	55
3.1	Method Using the Calibrated Object or the Standard	57
3.2	Noncalibrated Object Method (Multiposition Method)	69
3.2.1	Measurement of an Object Characteristic	72
3.2.2	Measurements of Length Standards	72
3.2.3	Measurement of Diameter Standards	73
3.2.4	Calculation of the Value of Measured Object Characteristic	74
3.2.5	Calculation of Measurement Uncertainty	75
3.2.6	Calculation of the Uncertainty Component u_{rep}	76
3.2.7	Calculation of Uncertainty Component u_{geo}	77
3.2.8	Calculation of Uncertainty Component u_{corrL}	77
3.2.9	Calculation of Uncertainty Component of Length Change Derived from Thermal Influences	78
3.3	Monte Carlo Method for Uncertainty Determination in Multiposition and Substitution Method	80
3.4	Determination of Uncertainty of Freeform Profile Measurement	85

3.5	Measurement Uncertainty Estimation for Calibrations Based on Error Source Identification: Error Budget	92
3.5.1	Uncertainty Budget for the Calibration Procedure of the Plate Standard (Hole Plate) Calibrated on PMM12106 Leitz Machine	94
3.5.2	Thermodynamic Model	98
3.5.3	Description of the Hole Plate Calibration Procedure	102
3.6	Methods Based on Relations Resulting from the Model of Maximum Permissible Errors of Coordinate Measuring System	109
3.7	Analytical Method of Measurement Uncertainty Determination	114
3.7.1	Geometric Error Model	115
3.7.2	Measurement Models	115
3.7.3	Measurement Uncertainty as a Complex Uncertainty	120
3.7.4	Estimation of Maximum Value for the Geometric Error Difference	121
3.7.5	Software	122
3.7.6	Particular Stages in the Operating Software	122
	References	125
4	Analysis of the Accuracy of Coordinate Measuring Systems	131
4.1	Sources and Causes of Coordinate Measuring Machine Errors	131
4.2	Identification and Software Correction of Measuring Machine Errors	136
4.2.1	Determination of Geometric Errors of the Measuring Machine Using the Laser Interferometer	139
4.2.2	PTB Method Using Plate Standard for Geometric Errors of Coordinate Measuring Machine Identification	143
4.2.3	Identification of Geometric Errors Using Laser Tracker Systems and Multilateration Method	151
4.3	Error Sources of Point Coordinates Contact Acquisition System—Probe Head Error Function	156
4.3.1	Analysis of Error Sources and Causes: Probe Head Error Function (PEF)	156
4.3.2	Contact Probe Head Error Tests	164
4.4	Matrix Method (MM) of CMM Accuracy Identification	171
4.4.1	Idea of the MM Method	171
4.4.2	Connection of MM Method with Reproducibility Error of Measuring Point (REMP)	173
4.4.3	Matrix Method Evaluation Based on Comparative Tests Carried Out on Accurate Measuring Machine	178
4.4.4	Use of Matrix Method for Error Identification of Large Measuring Machines (LCMM)	182

4.5	Modeling and Identification of Errors of Articulated Arm Coordinate Measuring Machines (AACMM)	194
4.5.1	Idea of AACMM Errors Model	195
4.5.2	AACMM Kinematic Description: Denavit–Hartenberg Notation	198
4.5.3	Kinematic Model (KmAACMM) Parameter Identification	205
4.5.4	Visualization and Correctness Assessment of Kinematic Model (KmAACMM).	209
	References	213
5	Simulation Methods for Assessing Accuracy of Measurements	227
5.1	Introduction to Modeling of Measurement Devices and Systems	227
5.1.1	Construction of the Model	229
5.1.2	Simulation	229
5.1.3	Comparison of Uncertainty Budget with Simulation	233
5.1.4	Model of Measurement Process	235
5.2	Simulation Models of Coordinate Measuring Systems.	236
5.2.1	Virtual Measuring Machine PTB	237
5.2.2	Universal Model of Coordinate Measuring Machine: Virtual CMM CUT	244
5.2.3	Virtual CMM Based on Artificial Neural Networks. . . .	248
5.2.4	Virtual CMM Based on the Monte Carlo Method	287
5.2.5	CMM Simulator and Virtual Machine.	308
5.2.6	Virtual Articulated Arm Coordinate Measuring Machine (VAACMM)	317
	References	328
6	Accuracy of Modern Coordinate Measuring Systems	337
6.1	Coordinate Systems Accuracy Test in Accordance with ISO Standards	338
6.1.1	Accuracy Testing and Calibration of Contact Systems . .	339
6.1.2	Accuracy Testing and Calibration of Optical Systems and Computed Tomography	348
6.2	Standards Used for Reverification and Interim Tests for CMM	357

6.3	Monitoring of Coordinate Measuring System Accuracy.	366
6.3.1	Monitoring and Correction of Thermal Effects.	367
6.3.2	The Internet Platform Tracesys.eu.—A System of Metrological Monitoring of Coordinate Measurement Systems	371
6.3.3	Role of Accredited Calibration Laboratory in the Coordinate Measuring System Accuracy Monitoring	374
	References	378
7	Summary and Directions for Future Works on Coordinate Measurements Accuracy.	383
7.1	Analytical and Calculation Methods Based on Dependencies Resulting from the Model of Maximum Permissible Errors of Coordinate Measuring System	385
	References	388
Annex A:	Procedure for Determining the Uncertainty of Coordinate Measurement Using Multiple Method	391
Annex B:	Standard Accuracy CMM Geometric Error Identification Using Laser Interferometer and Correction Matrix CAA Determination	419
Annex C:	Identification of Geometric Error Components Using Plate Standard and KalKom 4.0 Program According to PTB Method	431
Annex D:	Example of CMM Geometric Error Identification Using Laser Tracker and Trac-Cal Software (Etalon AG)	453

Coordinate Metrology

Accuracy of Systems and Measurements

Śladek, J.A.

2016, VIII, 471 p. 397 illus., Hardcover

ISBN: 978-3-662-48463-0