

Contents

| | | |
|--------------------------------|---|------------|
| 1 | Introduction..... | 1 |
| | Maria Bostenaru Dan | |
| Part I Adobe and Bricks | | |
| 2 | Technology of Rammed-Earth Constructions (“Tapial”) in Andalusia (Spain): Their Restoration and Conservation | 11 |
| | Eduardo Sebastián and Giuseppe Cultrone | |
| 3 | Ancient Clay Bricks: Manufacture and Properties | 29 |
| | Francisco M. Fernandes, Paulo B. Lourenço and Fernando Castro | |
| 4 | The Mỹ Sơn Temples in Vietnam: Construction Techniques and Structural Issues | 49 |
| | Paola Condoleo | |
| Part II Natural Stone | | |
| 5 | The White and Coloured Marbles of the Roman Theatre of <i>Copia</i> (Cosenza, Italy) | 71 |
| | Lorenzo Lazzarini, Silvana Luppino and Carmelo G. Malacrino | |
| 6 | Black “Marble”: The Characteristic Material in the Baroque Architecture of Cracow (Poland) | 93 |
| | Mariola Marszałek and Andrzej Skowroński | |
| 7 | Understanding the Long-Term Survival of Sandstone in Medieval Ecclesiastical Structures: Northern Ireland and Western Scotland | 107 |
| | Stephen McCabe and Bernie J. Smith | |

| | | |
|---|--|------------|
| 8 | The City of Dresden in the Mirror of its Building Stones: Utilization of Natural Stone at Façades in the Course of Time | 137 |
| | Heiner Siedel | |
| 9 | Determination of Source Areas of Natural Stones: A Methodology Approach Applied to Impure Crystalline Limestones..... | 157 |
| | Aneta Šťastná and Richard Přikryl | |
| 10 | In Situ Methods of Testing Stone Monuments and the Application of Nondestructive Physical Properties Testing in Masonry Diagnosis | 177 |
| | Ákos Török | |
| Part III Binders, Concrete and Mixed Materials | | |
| 11 | The Use of Lime Mortars in Restoration Work on Architectural Heritage..... | 197 |
| | Ana Luque, Giuseppe Cultrone and Eduardo Sebastián | |
| 12 | The Basilica of Maxentius and Its Construction Materials | 209 |
| | Carlo Giavarini | |
| 13 | Characterization of Ancient Pozzolan Mortars from Roman Times to the 19th Century: Compatibility Issues of New Mortars with Substrates and Ancient Mortars..... | 235 |
| | Ana Luísa Velosa, Rosário Veiga, João Coroado, Victor M. Ferreira and Fernando Rocha | |
| 14 | Roman Cements: Key Materials of the Built Heritage of the 19th Century..... | 259 |
| | Roman Kozłowski, David Hughes and Johannes Weber | |
| 15 | Historic Mortars and Plasters as a Material for Age Determination | 279 |
| | Danuta Nawrocka, Tomasz Goslar and Anna Pazdur | |
| 16 | Reinforced Concrete Constructions at the Beginning of the 20th Century: Historical Review and Structural Assessment | 293 |
| | Mauro Mezzina, Fabrizio Palmisano and Giuseppina Uva | |
| Part IV Monitoring the Seismic Risk | | |
| 17 | Heritage Masonry Buildings and Reduction of Seismic Risk: The Case of Slovenia..... | 327 |
| | Miha Tomaževič | |

**18 Acoustic Emission Monitoring of the Cathedral of
Palma de Mallorca (Spain)..... 351**
Luis Miguel Suárez del Río, Vicente Gómez Ruiz de Argandoña,
Lope Calleja, Angel Rodríguez Rey, Carlota María Grossi-Sampedro
and Modesto Montoto

Index..... 367

Materials, Technologies and Practice in Historic
Heritage Structures

Bostenaru Dan, M.; Pøikryl, R.; Török, A. (Eds.)

2010, XVII, 371 p., Hardcover

ISBN: 978-90-481-2683-5