

Table of Contents

Preface	vii
Part I – Settlements	
Chapter 1. Interaction between Neighbouring Structures: Mexico City Metropolitan Cathedral, Mexico	3
Chapter 2. Unexpected Excessive Settlements: Kansai International Airport, Japan	23
Chapter 3. Leaning Instability: The Tower of Pisa, Italy	45
Part II – Bearing Capacity	
Chapter 4. Bearing Capacity Failure: Transcona Grain Elevator, Canada	67
Chapter 5. Caisson Failure Induced by Liquefaction: Barcelona Harbour, Spain	85
Part III – Excavations	
Chapter 6. Braced Excavation Collapse: Nicoll Highway, Singapore	151
Chapter 7. Tunnel Excavation Collapse: Borràs Square, Spain	183
Chapter 8. Tunnel Face Instability: Floresta Tunnels, Spain	205
Epilogue	245



<http://www.springer.com/978-90-481-3530-1>

Geomechanics of Failures

Puzrin, A.M.; Alonso, E.E.; Pinyol, N.M.

2010, VIII, 245 p., Hardcover

ISBN: 978-90-481-3530-1