

# Contents

<b>1</b>	<b>Introduction</b> . . . . .	1
1.1	Water Resources of India . . . . .	2
1.1.1	Basin-Wise Per Capita Water Resources Availability of India . . . . .	4
1.2	Water Management. . . . .	6
1.2.1	Integrated Water Resources Management . . . . .	9
1.2.2	Role of Public Partnership and Awareness. . . . .	10
	References . . . . .	10
<b>2</b>	<b>Brief Overview of the Yamuna River Basin and Issues</b> . . . . .	13
2.1	Issues and Challenges . . . . .	15
2.1.1	Water Resources. . . . .	15
2.1.2	Water Quality . . . . .	18
2.1.3	Wastewater Generation . . . . .	19
2.1.4	Environmental Flow . . . . .	20
2.2	Summary of the Yamuna River Catchments. . . . .	21
	References . . . . .	24
<b>3</b>	<b>Methodology for Public Awareness Campaign</b> . . . . .	25
3.1	Conceptual Framework and Strategy. . . . .	25
3.2	Selection of Villages. . . . .	26
3.3	Primary Survey . . . . .	26
3.3.1	Questionnaire Design . . . . .	27
3.3.2	Group Interviews . . . . .	27
3.4	Participatory Mapping. . . . .	29
3.5	Secondary Data Collection. . . . .	31
3.6	Data Analysis. . . . .	31
3.6.1	Descriptive Analysis. . . . .	31

3.6.2	Historical Analysis . . . . .	31
3.6.3	Institutional Analysis . . . . .	32
	References . . . . .	32
<b>4</b>	<b>Case Study: Somb and Boli Catchments . . . . .</b>	<b>33</b>
4.1	Antiquity of Village . . . . .	34
4.2	Geo-Physical Characteristics . . . . .	34
4.2.1	Climate and Rainfall . . . . .	34
4.2.2	Soil, Land Use and Land Cover . . . . .	37
4.2.3	Biodiversity . . . . .	37
4.2.4	Plantation . . . . .	38
4.2.5	Common Crops . . . . .	38
4.3	Inference from Primary Survey . . . . .	39
4.3.1	Integrated Watershed Development Project . . . . .	39
4.3.2	Environmental Status . . . . .	40
4.3.3	Socio-Economic Status . . . . .	42
4.3.4	Agriculture and Irrigation . . . . .	43
4.4	Summary and Conclusions. . . . .	45
	References . . . . .	50
<b>5</b>	<b>Case Study: Middle Alluvial Plains . . . . .</b>	<b>51</b>
5.1	Geo-Physical Characteristics . . . . .	53
5.1.1	Climate and Rainfall . . . . .	53
5.1.2	Soil, Landuse and Land Cover . . . . .	53
5.1.3	Biodiversity . . . . .	54
5.2	Inferences from Primary Survey . . . . .	54
5.2.1	Environmental Status . . . . .	54
5.2.2	Socio-Economic Status . . . . .	57
5.2.3	Amenities . . . . .	59
5.2.4	Agriculture and Irrigation . . . . .	59
5.2.5	Institutional Status . . . . .	62
5.3	Summary and Conclusions. . . . .	66
	References . . . . .	66
<b>6</b>	<b>Case Study: Banganga Catchment. . . . .</b>	<b>67</b>
6.1	Geo-Physical Characteristics . . . . .	68
6.1.1	Climate and Rainfall . . . . .	68
6.1.2	Topography and Soil. . . . .	68
6.1.3	Biodiversity . . . . .	69
6.1.4	Common Crops and Cropping Pattern . . . . .	69
6.2	Inferences from Primary Survey . . . . .	69
6.2.1	Role of Local Institution . . . . .	77
6.2.2	Environmental Status . . . . .	77
6.2.3	Socio-Economic Status . . . . .	79

6.2.4	Agriculture and Irrigation . . . . .	80
6.2.5	Amenities . . . . .	85
6.2.6	Institution . . . . .	86
6.3	Summary and Conclusions. . . . .	86
	References . . . . .	90
<b>7</b>	<b>Case Study: Banas Catchment . . . . .</b>	<b>91</b>
7.1	Geo-Physical Characteristics . . . . .	92
7.1.1	Climate and Rainfall. . . . .	92
7.1.2	Topography and Soil. . . . .	92
7.1.3	Biodiversity . . . . .	92
7.2	Inferences from Primary Survey. . . . .	92
7.2.1	Water Conservation . . . . .	92
7.2.2	Local Institution . . . . .	93
7.2.3	Environmental Status . . . . .	94
7.2.4	Socio-Economic Status . . . . .	95
7.2.5	Agriculture and Irrigation . . . . .	96
7.2.6	Amenities . . . . .	98
7.3	Institutions. . . . .	98
7.3.1	Capacity Building. . . . .	98
7.4	Summary and Conclusions. . . . .	102
	References . . . . .	102
<b>8</b>	<b>Case Study: Chambal Catchment . . . . .</b>	<b>103</b>
8.1	Geo-Physical Characteristics . . . . .	105
8.1.1	Climate and Rainfall. . . . .	105
8.1.2	Topography and Soil. . . . .	105
8.1.3	Biodiversity . . . . .	105
8.1.4	Common Crops . . . . .	106
8.2	Inferences from Primary Survey. . . . .	106
8.2.1	Water Conservation . . . . .	106
8.2.2	Local Institution . . . . .	108
8.2.3	Environmental Status . . . . .	108
8.2.4	Socio-Economic Status . . . . .	109
8.2.5	Agriculture and Irrigation . . . . .	110
8.2.6	Amenities . . . . .	111
8.3	Institution . . . . .	111
8.3.1	Capacity Building. . . . .	115
8.4	Summary and Conclusions. . . . .	115
	References . . . . .	115
<b>9</b>	<b>Case Study: Sind and Betwa Catchments . . . . .</b>	<b>117</b>
9.1	Geophysical Characteristics . . . . .	118
9.1.1	Climate and Rainfall. . . . .	118

9.1.2	Topography and Soil. . . . .	118
9.1.3	Biodiversity . . . . .	119
9.1.4	Common Crops . . . . .	119
9.2	Inferences from Primary Survey. . . . .	119
9.2.1	Water Conservation . . . . .	121
9.2.2	Local Institution . . . . .	124
9.2.3	Environmental Status . . . . .	124
9.2.4	Socio-Economic Status . . . . .	126
9.2.5	Agriculture and Irrigation . . . . .	127
9.2.6	Amenities . . . . .	131
9.3	Institution . . . . .	132
9.3.1	Capacity Building. . . . .	133
9.4	Summary and Conclusions. . . . .	133
	References . . . . .	137
<b>10</b>	<b>Case Study: Ken Catchment . . . . .</b>	<b>139</b>
10.1	Geophysical Characteristics . . . . .	142
10.1.1	Climate and Rainfall. . . . .	142
10.1.2	Topography and Soil. . . . .	142
10.1.3	Biodiversity . . . . .	142
10.1.4	Common Crops . . . . .	143
10.2	Inferences from Primary Survey. . . . .	143
10.2.1	Water Conservation . . . . .	143
10.2.2	Local Institution . . . . .	144
10.2.3	Environmental Status . . . . .	144
10.2.4	Socio-Economic Status . . . . .	145
10.2.5	Agriculture and Irrigation . . . . .	146
10.2.6	Amenities . . . . .	149
10.3	Institution . . . . .	152
10.3.1	Capacity Building. . . . .	152
10.4	Summary and Conclusions. . . . .	152
	References . . . . .	152
<b>11</b>	<b>Lesson Learned . . . . .</b>	<b>153</b>
	<b>Index . . . . .</b>	<b>155</b>

Water Management and Public Participation

Case Studies from the Yamuna River Basin, India

Upadhyay, A.; Upadhyay, A.

2013, X, 156 p. 88 illus., 83 illus. in color., Softcover

ISBN: 978-94-007-5708-0