

Contents

Practical Experiences from Several Moisture Performance Assessments	1
Petri J. Annila, Jukka Lahdensivu, Jommi Suonketo and Matti Pentti	
Analysis of Main Parameters that Affect Contact Area Between Mortar Rendering and Substrate: Use of 3D Laser Scanning Technique.	21
Carina Mariane Stolz and Angela Borges Masuero	
The Pathologies of the ETICS	37
Filiberto Lembo and Francesco Paolo R. Marino	
Criteria for Identification of Ceramic Detachments in Building Facades with Infrared Thermography	51
Elton Bauer, Elier Pavón, Cláudio H.F. Pereira and Matheus L.M. Nascimento	
Diagnosis of Moisture Movements in Massive Dolostone Walls of Medieval Churches	69
Lembit Kurik, Targo Kalamees and Urve Kallavus	
The Wind-Driven Rain and the Buildings: Directional Driving Rain, Experimental Simulation and Quantification of Wetness Areas	91
Lais Zucchetti, Patricia Poyastro, Silvia Trein Heimfarth Dapper, Angela Borges Masuero and Acir Mércio Loredou-Souza	
A Performance Assessment of Prefabricated Bathrooms Installed in the 1990s	105
Martin Morelli and Erik Brandt	
Good Practice: Analysis of the Vulnerability of Seven Churches in Monza. From an Information Model to a Geodatabase	127
Cecilia Bolognesi	

On the Use of Infrared Thermographic Measurements for Evaluating the Airtightness of the Building Envelope	145
Katrien Maroy, Nathan Van Den Bossche, Marijke Steeman and Sven Van De Vijver	
Evaluation of Moisture Transfer to Improve the Conservation of Tiles Finishing Facades	171
Silvia Erba, Bruno Daniotti, Elisabetta Rosina, Antonio Sansonetti and Riccardo Paolini	
Analysis of Microclimate in a Historical Building to Assess the Probability of Recurrence of Filamentous Fungi	195
Fernanda Lamego Guerra, Eduardo Grala da Cunha and Fábio Galli	

Recent Developments in Building Diagnosis Techniques

Delgado, J.M.P.Q. (Ed.)

2016, VIII, 213 p. 141 illus., 13 illus. in color., Hardcover

ISBN: 978-981-10-0465-0