



Page 63. Figure 6. Doppler OCT images taken *in situ* from PWS human skin. A: structural image; B: histological section; C: image before laser treatment; and D: image after laser treatment (from Ref. [23]).